

OIL STORAGE

Chronology of Alterations and Use

Original Construction

The Outer Island Oil Storage was built in 1895 to provide a safe storage area for the kerosene needed to fuel the lamps.⁴²

On file is an undated historic photo that depicts the building in a similar condition to its current appearance. (Historic Image OI-11)

There are no available historic drawings of this building.

Significant Alterations / Current condition

There have been no significant alterations to the Oil Storage. It currently contains an empty steel kerosene storage tank and shelves for general storage.

There have never been electrical or mechanical systems in this building, except for the gravity vent located in the roof.

The Outer Island Oil Storage is in good condition.

⁴² “1895 Annual Report of the Lighthouse Board,” Outer Island Light in annual reports 1850-1920

Summary of Documented Work on the Building

Date	Work Described	Source of Information
1894, August 7	Steamer "Amaranth" brings brick "for an Oil House."	John Leonard, OI Log, Sept 17, 1874 – Dec 10, 1947, Vol I
Annual Report of 1895 Fiscal Year	"Outer Island, Apostle Group, Lake Superior, Wisconsin. – A brick oil house was erected, with iron roof, door, and shelving, located 60' southwest of the dwelling. <i>1324. Outer Island, Wisconsin.</i> - This 10-inch steam whistle was in operation some 478 hours, and consumed about 26 tons of coal."	"1895 Annual Report of the Lighthouse Board," Outer Island Light in annual reports 1850-1920

General Physical Description

This building is a small, one-story, one room, rectangular utilitarian structure with brick bearing walls and foundation, and a sheet metal hipped roof. It has a circular metal vent in the center of the roof and a metal door on the north elevation.

Physical Description -- Architecture

Architecture – Roof

The roofing is sheet metal painted red, with eave molding, and a central vent.

Architecture – Exterior Walls

The exterior walls are three-wythe brick painted. There is stepped brick coursing at the foundation and a brownstone sill at the door. A mortar sample taken indicates that the mortar was composed mostly of sand with minimum lime, the sand was originally dirty, and is extremely fine. The mortar is tan and very soft.

Architecture – Exterior Door

The exterior door is made of steel, has an original lockset, and has two strap hinges. It is 2'7" x 6'10 1/2" and is original to the building. (OI-OS-05) There is a painted stone sill at the door.

Architecture – Wall Finish

The wall finish for this building is the original common bond brick painted gray and yellow.

Architecture – Ceiling Finish

There is no ceiling finish as the ceiling is the underside of the original metal roof. It is sheet metal painted yellow.

Architecture – Floor

The floor is concrete slab-on-grade that is painted blue-gray.

1 *Architecture – Casework*

2 There is a metal shelving unit along the entirety of the west wall, painted blue-gray. There is also a wood
3 platform supporting the kerosene tank. It is 4'6" wide, 1'1" tall, and 2'1 ½" deep. Neither shelving unit is
4 historic. (OI-OS-06)

5
6
7 *Architecture – Accessibility*

8 This building is currently not accessible. The entry door opening is 2'7" clear with a grade to finished floor
9 elevation change of 7 ½" due to a sill/threshold. The door hardware is not ADA compliant.

10
11
12 ***Physical Description -- Structural***

13 *Structural – Foundation*

14 The perimeter foundation system consists of brick masonry walls with stepped coursing.

15
16
17 *Structural – Floor Framing*

18 The floor is a concrete slab-on-grade.

19
20
21 *Structural – Roof Framing*

22 The roof framing is made up of metal angles that were not accessible and could not be measured. The
23 angles are covered by metal roof sheathing.

24
25
26 *Structural – Wall Framing*

27 The exterior walls are constructed of brick masonry.

28
29
30 *Structural – Lateral System*

31 Lateral stability for the building is provided by the brick masonry walls.

32
33
34 *Structural – Load Requirements*

35 The required floor load capacity is 125 psf and the required roof snow load capacity is 40 psf.

36
37
38 ***Physical Description -- Mechanical***

39 *Mechanical – Plumbing Systems*

40 There are no plumbing systems in the Oil Storage.

41
42
43 *Mechanical – HVAC*

44 The original circular metal gravity vent remains on the roof. A roof cap has been put in place above the
45 storage area rendering the vent inoperable.

46
47
48 *Mechanical – Fire Suppression*

49 None in the building.

Physical Description -- Electrical

Electrical – System Configuration

None in the building.

Electrical – Conductor Insulation

None in the building.

Electrical – Overcurrent Protection

None in the building.

Electrical – Lighting Systems

None in building.

Electrical – Telecommunications

None in the building.

Electrical – Fire Alarm System

None in the building.

Electrical – Lightning Protection

None on the building.

Physical Description -- Hazardous Materials

Landmark Environmental collected ten bulk samples from a total of ten different types of suspected asbestos containing materials (ACMs) at Outer Island. Of the ten suspect ACMs that were sampled and analyzed, a total of one suspect ACM resulted in a concentration of greater than one percent (positive for asbestos).

Hazardous Materials – Asbestos

The following suspect ACMs were not sampled due to inaccessibility or park limitation regarding potential for damage to structures. Asbestos is assumed to be present in:

1. Wall and Ceiling Interiors,
2. Adhesives,
3. Brick and Block Filler (The exterior of the structure is brick and has the potential to have a block filler or grout that is potentially asbestos containing), and,
4. Asbestos-cement (Piping, wall-board, wall interior panels, roof flashing and roofing applications can be constructed of asbestos-cement. This type of application was not observed at the structure but may be present).

The assumed ACMs were observed to be in good condition.

Hazardous Materials – Lead Containing Paint

Detectable lead is assumed to be present at the following locations:

1 1. Interior Painted Surfaces, and,

2 2. Exterior Painted Surfaces.

3 Based on the estimated dates of construction of the various structures, LCP is assumed to be present
4 throughout the structure. The confirmed LCP was observed to be in poor condition and the assumed LCP
5 was observed to be in poor condition.

6
7 Loose/flaking LCP is identified on the exterior walls of the structure. Paint chip debris is noted on
8 localized areas of surface soils surrounding the Oil Storage Building.
9

10
11 *Hazardous Materials – Lead Dust*

12 Surface wipe-sampling for lead dust was not conducted in the Oil Storage Building because it in a
13 noninhabited structure.
14

15
16 *Hazardous Materials – Lead in Soils*

17 Historical paint maintenance activities such as manual scraping, power-washing, sanding, abrasive blasting
18 or the general poor and peeling condition of exterior LCP may have created the potential to impact the
19 surrounding soil. Areas of the surface soils adjacent to the structure were observed to have LCP debris and
20 additional areas may exhibit LCP debris or lead-contaminated soils, but are not observable due to
21 vegetative cover surrounding the structure.
22

23 Preliminary lead-in-soil sampling was not performed to assess whether these near-structure soils contain
24 lead concentrations above applicable soil standards.
25

26 Soil Sampling was not conducted around the Oil Storage Building.
27
28

29 *Hazardous Materials – Mold*

30 Inspections of the structure were performed to identify the readily ascertainable visual extent of the mold
31 growth. Moisture testing in building materials was not performed nor was sampling of building materials
32 performed for microbial analysis. Mold was not visually identified in the Oil Storage Building.
33
34

35 *Hazardous Materials – Petroleum Hydrocarbons*

36 Localized areas of staining were observed on concrete floors in the Oil Storage Building. Stained areas are
37 likely associated with fuel oil, diesel or other petroleum hydrocarbons. Tank and piping systems may also
38 contain petroleum hydrocarbons.
39
40
41

Character Defining Features

Mass/Form. A simple utilitarian masonry hipped roof structure.

Exterior Materials. Painted white wood clapboard siding; metal roof shingles painted red.

Openings. One painted metal door painted red to match the painted brick.

Interior Materials. Exposed masonry, concrete floor and galvanized panels at the ceiling.

General Condition Assessment

In general, the Outer Island Oil Storage is in good condition. The original brick walls, concrete floor, and steel door are in good condition.

Structurally, the Oil Storage is in good condition.

The following section is a discipline-by-discipline, component-by-component condition assessment of the building. Refer to Volume I, Chapter 2: Methodology for definitions of the condition ratings.

Condition Assessment -- Architecture

Architecture – Roof

Condition: *Good*

This roof is in good condition.

Architecture – Exterior Walls

Condition: *Fair*

The exterior walls are in fair condition, as the walls need repointing and the brick foundation is exposed and weathering at the southwest corner. The paint is peeling severely.

Architecture – Exterior Door

Condition: *Good*

This steel door is in good condition as there is only minor paint peeling. The sill is cracked.

Architecture – Wall Finish

Condition: *Poor*

The wall finish for this building is in poor condition. The paint is peeling badly and an older layer of white paint is visible.

Architecture – Ceiling Finish

Condition: *Good*

The underside of the roof is in good condition.

1 *Architecture – Floor*

2 Condition: *Good to Fair*

3 The concrete floor is in good condition but the blue-gray paint is deteriorated. The concrete is intact. The
4 front stoop, however, is in fair condition as it is cracked.

7 *Architecture – Casework*

8 Condition: *Fair*

9 The metal shelving unit is in good condition with some peeling paint and deflected shelves. The wood
10 platform shelf is in fair condition as it is also deflected and there stains on the wood.

13 *Architecture – Accessibility*

14 Condition: *Poor*

15 This building is currently not accessible.

18 ***Condition Assessment -- Structural***

19 *Structural – Foundation*

20 Condition: *Good*

21 The visible portion of the foundation system appears to be in good condition. No obvious signs of distress
22 or damage were observed.

25 *Structural – Floor Framing*

26 Condition: *Good*

27 The concrete slab-on-grade is in good condition.

30 *Structural – Roof Framing*

31 Condition: *Unknown*

32 The roof framing could not be observed, thus its condition is unknown. No obvious signs of distress or
33 damage were observed.

36 *Structural – Wall Framing*

37 Condition: *Good*

38 The walls are in good condition.

41 *Structural – Lateral System*

42 Condition: *Good*

43 Lateral stability of the building is good.

46 *Structural – Load Requirements*

47 Condition: *Good*

48 The slab-on-grade has adequate capacity. The roof framing could not be observed, thus its capacity is
49 unknown.

Condition Assessment -- Mechanical

Mechanical – Plumbing Systems and Fire Suppression

Condition: N/A

Mechanical – HVAC

Condition: Good

The original circular metal gravity vent is in good condition, but a roof cap has been put in place above the storage area rendering the vent inoperable.

Condition Assessment -- Electrical

N/A

Condition Assessment -- Hazardous Materials

Refer to ‘Physical Description -- Hazardous Materials’ for detailed descriptions of locations and conditions of hazardous materials.

Ultimate Treatment and Use

This building was constructed in 1895 and served as an oil storage building. Currently, the building is used for secure NPS storage. The proposed use for the Oil Storage is to maintain its existing function as storage with no visitor access.

Preservation, focusing on the exterior, is the recommended treatment for the building.

Requirements for Treatment

Compliance requirements for treatment currently include laws, regulations, and standards as outlined by the NPS and listed in Volume I, Administrative Data section of this report.

The recommended treatments are tailored to the Preferred Alternative as the outcome of the Value Analysis/CBA for the project. As individual buildings are rehabilitated, specific alternatives will present themselves during design and construction. The following section is a discipline-by-discipline, component-by-component description of the treatments proposed for the preservation of the building. Refer to Volume I, Chapter 2: Methodology for the priority rating definitions.

Treatment Recommendations -- Architecture

Architecture – Roof

Priority: Low

No recommendations at this time.

Architecture – Exterior Walls

Priority: Low

Strip the existing paint. Repair masonry, repoint as needed and recoat with a proper vapor permeable coating.

Architecture – Exterior Door

Priority: Low

Repaint steel door. Epoxy repair the crack at the sill.

Architecture – Wall Finish

Priority: Low

Scrape, sand and repaint using the paint analysis to guide the color selection.

Architecture – Ceiling Finish

Priority: Low

No recommendations at this time.

Architecture – Floor

Priority: Low

Repaint the concrete floor to match existing color.

Architecture – Casework

Priority: *Low*

No recommendations at this time.

Architecture – Accessibility

Priority: *Low*

Provide program access through interpretive exhibits and waysides at the Visitor Center.

Treatment Recommendations -- Structural

Structural – Foundation

Priority: *Low*

No recommendations at this time.

Structural – Floor Framing

Priority: *Low*

No recommendations at this time.

Structural – Roof Framing

Priority: *Low*

No recommendations at this time.

Structural – Wall Framing

Priority: *Low*

No recommendations at this time.

Structural – Lateral System

Priority: *Low*

No recommendations at this time.

Treatment Recommendations -- Mechanical

Mechanical – Plumbing Systems and Fire Suppression

Priority: *N/A*

Mechanical – HVAC

Priority: *Low*

No recommendations at this time.

Treatment Recommendations -- Electrical

N/A

Treatment Recommendations -- Hazardous Materials

Hazardous Materials – Asbestos

Priority: *Low*

Recommend sampling of suspect asbestos containing materials, including brick and block filler, adhesives, wall and ceiling interiors, and asbestos cement should be sampled.

Hazardous Materials – Lead-Containing Paint and Lead Dust

Priority: *Low*

Recommend stabilization or abatement of Lead Containing Paint. Lead dust wipe sampling not recommended.

Hazardous Materials – Lead In Soils

Priority: *Low*

No recommendations at this time.

Hazardous Materials – Mold/Biological

Priority: *Low*

No recommendations at this time.

Hazardous Materials – Petroleum Hydrocarbons

Priority: *Low*

No recommendations at this time.

Alternatives for Treatment

One alternative treatment for consideration could be for the use by the park to include this building for interpretive use on the interior as opposed to continued use as park storage. However, due to the limited options for the necessary maintenance functions' storage at this remote site, retaining the storage use on the interior is deemed appropriate.

The following table includes an analysis of the major treatment recommendations which affect Section 106 Compliance:

Assessment of Effects for Recommended Treatments

Recommended Treatment	Potential Effects	Mitigating Measures	Beneficial Effects
1. Additional Hazardous Testing and Mitigation	Mitigation of hazardous material may require removal of historic materials.	Any mitigation will need to be evaluated for benefit and implemented sensitively to minimize damage to the resource.	<ul style="list-style-type: none"> - Improves safety for visitors and staff - Removes hazards from the cultural resource

1 **Oil Storage Photographs, 2009**



2
3 *OI-OS-01: North elevation, 2009 (Source: A&A DSC01362)*



1
2

OI-OS-02: East elevation, 2009 (Source: A&A DSC01364)




1
2

OI-OS-03: South elevation, 2009 (Source: A&A DSC01363)



1
2

OI-OS-04: North and west elevations, 2009 (Source: A&A IMGP3167)



OI-OS-05: North entry door hardware (Source: A&A IMGP3169)



OI-OS-06: Interior, looking south (Source: A&A DSC01355-A)

PRIVY

Chronology of Alterations and Use

Original Construction

The Outer Island Privy was built in 1874, the same year as the Tower.⁴³

A photo of the Privy around 1900 roughly illustrates painted brick on the lower half, and unpainted brick on the upper half of the building. (Historic Image OI-04) Today, the Privy is painted.

There are no available historic drawings of this building.

Significant Alterations / Current condition

There have been no significant alterations to the Privy.

There have never been electrical or mechanical systems in this building, except for the gravity vent located in the roof.

The Outer Island Privy is in fair to good condition.

⁴³ List of Classified Structures, National Park Service, 2009.

General Physical Description

This building is a small, one-story, one room, rectangular utilitarian structure with brick bearing walls and foundation. It has a simple gable roof with boxed rafter tails and a square wood vent. The casement window has an arched opening and the door is located on the west elevation.

At the time of this survey, this building was inaccessible. Interior notes were garnered from looking in the window and therefore the overall condition of interior finishes could not be determined from the partial view.

Physical Description -- Architecture

Architecture – Roof

The roofing is metal shingle, painted red, and is original to the building. (OI-P-06) There is a wood fascia, frieze board, and a vent. The eave consists of a closed raked soffit extending approximately 9". All of the wood is painted and is original to the building. (OI-P-07)

Architecture – Exterior Walls

The exterior walls are made of two-wythe red brick with rowlocks every seventh course (same as the Keepers Quarters – the buildings were built the same year). The foundation is brownstone. A mortar sample from the brick mortar indicates that it was composed of sand and lime, with coarse sand, tan colored, and very soft.

Architecture – Window

The window is a two-lite (one-over-one) casement or awning with a painted wood frame. There is a painted wood surround and sill. The window is 1'1" x 2'8" and is original to the building. A paint sample taken of the exterior window trim indicated that the original layer was whitewash and the subsequent white layer was impervious to acid, meaning it was a later white paint, not a whitewash. Currently, the trim is painted green.

Architecture – Exterior Door

The door is a five panel wood door, similar to the doors in the house, with original exterior knob (interior inaccessible). The door is 2'4" x 6'7".

Architecture – Exterior Trim

There is no exterior trim other than the roof elements.

Architecture – Wall Finish

The interior of this building was inaccessible (observations were made through the window). The wall finish for this building appears to be horizontal beadboard, painted, most likely 3 1/2" wide.

Architecture – Ceiling Finish

The interior of this building was inaccessible (observations were made through the window). The ceiling finish was not visible from this location.

1 *Architecture – Floor*

2 The interior of this building was inaccessible (observations were made through the window). The floor is
3 concrete.

6 *Architecture – Casework*

7 The interior of this building was inaccessible (observations were made through the window). The Privy
8 contains two adult and one child privy seats, made of wood, painted blue.

11 *Architecture – Accessibility*

12 This building is currently not accessible. The main entry door opening is 2’3” clear with a grade to finished
13 floor elevation change of 5 ½” due to the masonry sill/threshold. There is not an adequate 5’ diameter space
14 within. No accessibility upgrades have been made.

17 ***Physical Description -- Structural***

18 *Structural – Foundation*

19 The foundation of the Privy appears to be concrete but was not accessible.

22 *Structural – Floor Framing*

23 The floor is concrete slab-on-grade.

26 *Structural – Roof Framing*

27 The roof framing could not be observed but is believed to be wood framing. The rafters span approximately
28 3’. The rafters are supported on the exterior wood-framed walls. The rafters are sheathed with solid wood
29 underlayment.

32 *Structural – Wall Framing*

33 The exterior walls are constructed of brick masonry.

36 *Structural – Lateral System*

37 Lateral stability for the building is provided by the exterior masonry walls.

40 *Structural – Load Requirements*

41 The required floor and roof snow load capacities are 40 psf.

44 ***Physical Description -- Mechanical***

45 *Mechanical – Plumbing Systems*

46 There are no plumbing systems in the Privy.

49 *Mechanical – HVAC*

50 The original decorative gravity vent for the Privy remains through the roof.

Mechanical – Fire Suppression

None in the building.

Physical Description -- Electrical

Electrical – System Configuration

None in the building.

Electrical – Conductor Insulation

None in the building.

Electrical – Overcurrent Protection

None in the building.

Electrical – Lighting Systems

None in the building.

Electrical – Telecommunications

None in the building.

Electrical – Fire Alarm System

None in the building.

Electrical – Lightning Protection

None in the building.

Physical Description -- Hazardous Materials

Landmark Environmental collected ten bulk samples from a total of ten different types of suspected asbestos containing materials (ACMs) at Outer Island. Of the ten suspect ACMs that were sampled and analyzed, a total of one suspect ACM resulted in a concentration of greater than one percent (positive for asbestos).

Hazardous Materials – Asbestos

The following suspect ACMs were not sampled due to inaccessibility or park limitation regarding potential for damage to structures. Asbestos is assumed to be present in:

1. Adhesives,
2. Wall Interiors,
3. Brick and Block Filler (Wall interiors may be composed of brick or block and have the potential to have a block filler or grout that is potentially asbestos containing), and,
4. Asbestos-cement (Piping, wall-board, wall interior panels, roof flashing and roofing applications can be constructed of asbestos-cement. This type of application was not observed at the structure but may be present).

The assumed ACMs were observed to be in fair condition.

1 *Hazardous Materials – Lead Containing Paint*

2 Detectable lead is assumed to be present at the following locations:

- 3 1. Interior Painted Surfaces, and,
4 2. Exterior Painted Surfaces.

5 Based on the estimated dates of construction of the various structures, LCP assumed to be present
6 throughout the structure. The assumed LCP was observed to be in poor condition.

7
8 Loose/Flaking LCP is identified on the exterior painted surfaces of the structure. Paint chip debris was not
9 seen on the ground surface.

10
11
12 *Hazardous Materials – Lead Dust*

13 Surface wipe-sampling for lead dust was not conducted in the Privy because it is an uninhabited structure.

14
15
16 *Hazardous Materials – Lead in Soils*

17 Historical paint maintenance activities such as manual scraping, power-washing, sanding, abrasive blasting
18 or the general poor and peeling condition of exterior LCP may have created the potential to impact the
19 surrounding soil. Areas of the surface soils adjacent to the structure were not observed to have LCP debris
20 and additional areas may exhibit LCP debris or lead-contaminated soils, but are not observable due to
21 vegetative cover surrounding the structure. Preliminary lead-in-soil sampling was not performed to assess
22 whether these near-structure soils contain lead concentrations above applicable soil standards.

23
24 Soil Sampling was not conducted around the Privy.

25
26
27 *Hazardous Materials – Mold*

28 Inspections of the structure were performed to identify the readily ascertainable visual extent of the mold
29 growth. Moisture testing in building materials was not performed nor was sampling of building materials
30 performed for microbial analysis. Mold was not visually identified in the Privy.

Character Defining Features

Mass/Form. A simple small utilitarian masonry gable roof structure with a decorative wood vent painted red.

Exterior Materials. White painted brick with dark grey accents, a metal shingle roof painted red and wood trim painted grey.

Openings. One wood two-lite casement and one five panel door both painted dark green.

Interior Materials. Unknown – no access.

General Condition Assessment

In general, the Outer Island Privy is in good condition on the exterior and the interior condition could not be determined as it was inaccessible. It is a three-seater privy for two adults and one child.

The following section is a discipline-by-discipline, component-by-component condition assessment of the building. Refer to Volume I, Chapter 2: Methodology for definitions of the condition ratings.

Condition Assessment -- Architecture

Architecture – Roof

Condition: *Fair and Poor*

The roof is in fair condition as there is missing trim at the ridge cap and the peeling paint has revealed rust on the metal shingles. The wood elements are in fair condition as they have badly peeling paint. The wood vent with peeling paint shows deteriorated wood.

Architecture – Exterior Walls

Condition: *Fair*

The exterior walls are in fair condition as they have peeling paint and spalling brick, especially on the east and north elevations.

Architecture – Window

Condition: *Fair and Unknown*

This window is in fair condition as the wood frame, surround, and sill have badly peeling paint. The interior condition of the window is unknown.

Architecture – Exterior Door

Condition: *Fair and Unknown*

The door is in fair condition with splitting wood at the panels and separation of stiles and rails. The condition of the interior face of the door is unknown.

Architecture – Exterior Trim

Condition: *N/A*

Refer to roof.

1 *Architecture – Wall Finish*

2 Condition: *Unknown*

3 The wall finish for this building appears to be horizontal bead board siding, most likely 3 ½” wide.
4 Surveyor was unable to determine the overall condition.

7 *Architecture – Ceiling Finish*

8 Condition: *Unknown*

9 The ceiling finish could not be identified.

12 *Architecture – Floor*

13 Condition: *Unknown*

14 The floor is concrete. Surveyor was unable to determine the overall condition.

17 *Architecture – Casework*

18 Condition: *Unknown*

19 This privy contains two adult and one child privy seats, made of wood, painted blue. Surveyor was unable
20 to determine the overall condition.

23 *Architecture – Accessibility*

24 Condition: *Poor*

25 This building is not accessible.

28 ***Condition Assessment -- Structural***

29 *Structural – Foundation*

30 Condition: *Good*

31 The visible portion of the foundation appeared to be in good condition. No obvious signs of distress or
32 damage were observed.

35 *Structural – Floor Framing*

36 Condition: *Good*

37 The concrete slab-on-grade is in good condition.

40 *Structural – Roof Framing*

41 Condition: *Unknown*

42 The roof framing could not be observed, thus its condition is unknown. No obvious signs of distress or
43 damage were observed.

46 *Structural – Wall Framing*

47 Condition: *Good*

48 The walls are in good condition.

Structural – Lateral System

Condition: *Good*

Lateral stability of the building is good.

Structural – Load Requirements

Condition: *Good*

The slab-on-grade has adequate capacity. The roof framing could not be observed, thus its capacity is unknown.

Condition Assessment -- Mechanical

Mechanical – Plumbing Systems and Fire Suppression

Condition: *N/A*

Mechanical – HVAC

Condition: *Poor*

The original decorative gravity vent on the roof is in poor condition as it needs conservation work.

Condition Assessment -- Electrical

N/A

Condition Assessment -- Hazardous Materials

Refer to ‘Physical Description -- Hazardous Materials’ for detailed descriptions of locations and conditions of hazardous materials.

Ultimate Treatment and Use

The Privy was constructed in 1874 and most likely was the primary sanitary facility until 1930 when indoor plumbing was installed in the Keepers Quarters. The building is currently vacant and not accessible to the public. The proposed use for the Privy is to retain the structure as an integral component of the site's cultural landscape while precluding public access to its interior.

Preservation, focusing on the exterior, is the recommended treatment for the building.

Requirements for Treatment

Compliance requirements for treatment currently include laws, regulations, and standards as outlined by the NPS and listed in Volume I, Administrative Data section of this report.

The recommended treatments are tailored to the Preferred Alternative as the outcome of the Value Analysis/CBA for the project. As individual buildings are rehabilitated, specific alternatives will present themselves during design and construction. The following section is a discipline-by-discipline, component-by-component description of the treatments proposed for the preservation of the building. Refer to Volume I, Chapter 2: Methodology for the priority rating definitions.

Treatment Recommendations -- Architecture

Architecture – Roof

Priority: *Moderate*

Replace the missing trim at the ridge cap and any rusted metal shingles in-kind. Scrape, sand and repaint metal shingles and wood elements at eave and rake. Scrape and sand the vent. Epoxy stabilize the wood members and prep and repaint.

Architecture – Exterior Walls

Priority: *Low*

Strip existing paint at brick. Repair spalling brick by flipping the bricks or by replacing in kind. Repaint the exterior walls with a proper coating allowing vapor permeability.

Architecture – Window

Priority: *Low*

Scrape, sand and repaint the exterior window frame, sash and trim. The interior condition of the window is unknown.

Architecture – Exterior Door

Priority: *Low*

Scrape and sand the door and frame. Epoxy stabilize the split wood in the door panels and repair the stiles and rails that are separating from the door face. Paint the door and frame. The condition of the interior face of the door is unknown.

Architecture – Exterior Trim

Priority: *N/A*

Refer to roof.

Architecture – Wall Finish

Priority: *Unknown*

The interior condition of the building is unknown.

Architecture – Ceiling Finish

Priority: *Unknown*

The interior condition of the ceiling finish is unknown.

Architecture – Floor

Priority: *Unknown*

The interior condition of the concrete floor is unknown.

Architecture – Casework

Priority: *Unknown*

The interior condition of the wood privy seats is unknown.

Architecture – Accessibility

Priority: *Low*

Provide program access through interpretive exhibits and waysides at the Visitor Center.

Treatment Recommendations -- Structural

Structural – Foundation

Priority: *Low*

No recommendations at this time.

Structural – Floor Framing

Priority: *Low*

No recommendations at this time.

Structural – Roof Framing

Priority: *Low*

No recommendations at this time.

Structural – Wall Framing

Priority: *Low*

No recommendations at this time.

Structural – Lateral System

Priority: *Low*

No recommendations at this time.

Treatment Recommendations -- Mechanical

Mechanical – Plumbing Systems and Fire Suppression

Priority: N/A

Mechanical – HVAC

Priority: Low

No recommendations at this time.

Treatment Recommendations -- Electrical

N/A

Treatment Recommendations -- Hazardous Materials

Hazardous Materials – Asbestos

Priority: Low

Recommend sampling of suspect asbestos containing materials, including brick and block filler, adhesives, wall and interiors, and asbestos cement should be sampled.

Hazardous Materials – Lead-Containing Paint and Lead Dust

Priority: Low

Recommend stabilization or abatement of Lead Containing Paint. Lead dust wipe sampling not recommended.

Hazardous Materials – Lead In Soils

Priority: Low

No recommendations at this time.

Hazardous Materials – Mold/Biological

Priority: Low

No recommendations at this time.

Hazardous Materials – Petroleum Hydrocarbons

Priority: Low

No recommendations at this time.

Alternatives for Treatment

The following are several considerations of alternatives for the proposed treatments:

1. An alternative at the exterior walls could be to leave the masonry exposed (if the quality of the brick allowed) or alter the paint pattern vs. what is in situ. The finish of the Privy appeared to have several iterations including that seen in historic photo OI – 04.
2. Another alternative could be, similar to other islands utilitarian structures, allowing a view panel for visitors to experience the interior of the Privy. Given the low visitorship of this island, this is not the currently the recommended treatment.

The following table includes an analysis of the major treatment recommendations which affect Section 106 Compliance:

Assessment of Effects for Recommended Treatments

Recommended Treatment	Potential Effects	Mitigating Measures	Beneficial Effects
1. Additional Hazardous Testing and Mitigation	Mitigation of hazardous material may require removal of historic materials.	Any mitigation will need to be evaluated for benefit and implemented sensitively to minimize damage to the resource.	<ul style="list-style-type: none"> - Improves safety for visitors and staff - Removes hazards from the cultural resource

1 *Privy Photographs, 2009*



01-P-01: Aerial, 2009 (Source: A&A DSC01510)

2



OI-P-02: West elevation, 2009 (Source: A&A IMGP3159)



OL-P-03: North elevation, 2009 (Source: A&A DSC01374)

1
2
3



OI-P-04: East elevation, 2009 (Source: A&A DSC01377)



1
2

OI-P-05: South elevation, 2009 (Source: A&A DSC01376)



OI-P-06: Roof and vent details, south elevation (Source: A&A IMGP3163)



OI-P-07: Trim detail, west elevation (Source: A&A IMGP3164)

GLOSSARY OF TERMS

PRIMARY TREATMENT APPROACH – PRESERVATION

Preservation standards include measures necessary to sustain the existing form, integrity, and materials of a historic property. Work, including preliminary measures to protect and stabilize the property, generally focuses upon the ongoing maintenance and repair of historic materials and features rather than extensive replacement and new construction. Preservation requires the retention of the greatest amount of historic fabric, including the landscape's historic form, features, and details as they have evolved over time. Limited and sensitive upgrading of mechanical, electrical and plumbing systems and other code-required work is permitted.

HOW TERMINOLOGY IS USED IN THE PRESERVATION APPROACH

Maintain – are those standard maintenance practices that are necessary to retain the features of a property as a contributing resource. Maintenance activities are usually not classified as repair, however minor repair such as replacement of posts or railings or segments of paving are included. Limited and sensitive upgrading of building systems (mechanical, electrical, plumbing) and other code related work is appropriate.

Plant – the removal and replanting of landscape plantings and vegetation as part of maintenance activities

Protect – short term and minimal measures used to stabilize and protect features, such as fencing around landscape features

Relocate – the removal and resetting of noncontributing features

Remove – the removal of nonhistoric features

Repair – features, components of features and materials that require additional work. These may include declining building features (e.g., roofing, foundation, mechanical systems) structures, small-scale features (e.g., repair of a railing) or landscape plantings (e.g., repair mass planting by adding infill plantings). Features that are repaired will match the old in design, color, texture, and if possible, material. Distinctive features that are repaired will match the old in design, color, texture, and if possible, material.

Retain – are those actions that are necessary to allow for a feature (contributing or noncontributing) to remain in place in its contributing current configuration and condition.

Stabilize – immediate measures (more than standard maintenance practices) are needed to prevent deterioration, failure, or loss of features.

PRIMARY TREATMENT APPROACH – REHABILITATION

Rehabilitation is intended to return a property to a state of utility, through repair or alteration, which makes possible an efficient contemporary use while preserving those portions and features of the property which are significant to its historic, architectural, and cultural values. Rehabilitation allows for repairs, alterations, restoration of missing features, and additions necessary to enable a compatible use for a property as long as the portions or features which convey the historical, cultural, or architectural values are preserved. Limited and sensitive upgrading of mechanical, electrical and plumbing systems and other code-required work is permitted.

HOW TERMINOLOGY IS USED IN THE REHABILITATION APPROACH

Maintain – are those standard maintenance practices that are necessary to retain the features of a property as a contributing resource. Maintenance activities are usually not classified as repair, however minor repair such as replacement of posts or railings or segments of paving are included. Limited and sensitive upgrading of building systems (mechanical, electrical, plumbing) and other code related work is appropriate.

Plant – the removal and replanting of landscape plantings and vegetation as part of maintenance activities or the restoration of missing features.

Reestablish – are those measures necessary to depict a landscape feature as it occurred historically. Reestablishment may include the replacement of missing landscape features such as views, planting patterns, spatial relationships, or small scale features.

Relocate – remove and reset noncontributing features

Remove – removal of nonhistoric features

Repair – features, components of features and materials that require additional work. These may include declining building features (e.g., roofing, foundation, mechanical systems) structures, small-scale features (e.g., repair of a railing) or landscape plantings (e.g., repair mass planting by adding infill plantings). Features that are repaired will match the old in design, color, texture, and if possible, material. Distinctive features that are repaired will match the old in design, color, texture, and if possible, material.

Restore – are those measures necessary to depict a feature or area as it occurred historically. Restoration may include repair of a feature so that it appears as it did historically or it may include replacement of missing features or qualities.

Retain – are those actions that are necessary to allow for a feature (contributing or noncontributing) to remain in place in its contributing current configuration and condition.

Stabilize – immediate, more extensive measures (more than standard maintenance practices) are needed to prevent deterioration, failure, or loss of features.

PRIMARY TREATMENT APPROACH – RESTORATION

Restoration standards allow for the accurate depiction of a property as it appeared at a particular time in its history by means of the removal of features from other periods in its history and reconstruction of missing features from the period of significance. The limited and sensitive upgrading of systems (mechanical, electrical, plumbing) and other code related work is appropriate.

HOW TERMINOLOGY IS USED IN THE RESTORATION APPROACH

Maintain – are those standard maintenance practices that are necessary to retain the features of a property as a contributing resource. Maintenance activities are usually not classified as repair, however minor repair such as replacement of posts or railings or segments of paving are included. Limited and sensitive upgrading of building systems (mechanical, electrical, plumbing) and other code related work is appropriate.

Plant – the removal and replanting of landscape plantings and vegetation as part of maintenance activities or the restoration of missing features

Relocate – remove and reset noncontributing features

Remove – removal of nonhistoric features

Reestablish – are those measures necessary to depict a landscape feature as it occurred historically. Reestablishment may include the replacement of missing landscape features such as views, planting patterns, spatial relationships, or small scale features.

Repair – features, components of features and materials that require additional work. These may include declining building features (e.g., roofing, foundation, mechanical systems) structures, small-scale features (e.g., repair of a railing) or landscape plantings (e.g., repair mass planting by adding infill plantings). Features that are repaired will match the old in design, color, texture, and if possible, material. Distinctive features that are repaired will match the old in design, color, texture, and if possible, material.

Restore – are those measures necessary to depict a feature or area as it occurred historically. Restoration may include repair of a feature so that it appears as it did historically or it may include replacement of missing features or qualities.

Retain – are those actions that are necessary to allow for a feature (contributing or noncontributing) to remain in place in its contributing current configuration and condition.

Stabilize – immediate, more extensive measures (more than standard maintenance practices) are needed to prevent deterioration, failure, or loss of features.

CONDITION ASSESSMENT DESCRIPTION LEVELS

Feature Condition Definitions

(Note: These terms are also applied to the overall structure/building.)

GOOD The feature is intact, structurally sound and performing its intended purpose. The feature needs no repair or rehabilitation, but only routine or preventive maintenance.

FAIR The feature is in fair condition if either of the following conditions is present:

- There are early signs of wear, failure or deterioration though the feature is generally structurally sound and performing its intended purpose – or –
- There is failure of a portion of the feature.

POOR The feature is in poor condition if any of the following conditions is present:

- The feature is no longer performing its intended purpose – or –
- Significant elements of the feature are missing – or –
- Deterioration or damage affects more than 25% of the feature – or –
- The feature shows signs of imminent failure or breakdown.

UNKNOWN Not enough information is available to make an evaluation.

RATINGS OF TREATMENT SEVERITY

An impact is a detectable result of an agent or series of agents having a negative effect on the significant characteristics or integrity of a structure and for which some form of mitigation or preventative action is possible. The assessment should include only those impacts likely to affect the structure within the next five years.

The Level of Impact Severity and their definitions are given below. For all levels, except UNKNOWN, two criteria are given. At least one of the criteria must be met for the declared Level of Impact Severity.

SEVERE	<ol style="list-style-type: none"> 1. The structure/feature will be significantly damaged or irretrievably lost if action is not taken within two (2) years. 2. There is an immediate and severe threat to visitor or staff safety.
MODERATE	<ol style="list-style-type: none"> 1. The structure/feature will be significantly damaged or irretrievably lost if action is not taken within five (5) years. 2. The situation caused by the impact is potentially threatening to visitor or staff safety.
LOW	<ol style="list-style-type: none"> 1. The continuing effect of the impact is known and will not result in significant damage to the structure/feature. 2. The impact and its effects are not a direct threat to visitor or staff safety.
UNKNOWN	Not enough information is available to make an evaluation.

DEFINITIONS OF TERMS**A**

AAS: Atomic Absorption Spectroscopy

AC: Alternating current; the movement of current through an electrical circuit that periodically reverses direction. Alternating current is the form of electric power that is delivered to businesses and residences.

ACM: Asbestos Containing Material

Accessibility: a term used to describe facilities or amenities to assist people with disabilities and can extend to Braille signage, wheelchair ramps, elevators/lifts, walkway contours, reading accessibility, etc.

According to its website, the Park Service is “committed to making all practicable efforts to make NPS facilities, programs, services, employment, and meaningful work opportunities accessible and usable by all people, including those with disabilities. This policy reflects the commitment to provide access to the widest cross section of the public and to ensure compliance with the Architectural Barriers Act of 1968, the Rehabilitation Act of 1973, the Equal Employment Opportunity Act of 1972, and the Americans with Disabilities Act of 1990. The Park Service will also comply with section 507 of the Americans with Disabilities Act (42 USC 12207), which relates specifically to the operation and management of federal wilderness areas. The accessibility of commercial services within national parks are also covered under all applicable federal, state and local laws” (source: <http://www.nps.gov/aboutus/eo.htm>).

AES-ICP: Atomic Emission Spectroscopy – Inductively Coupled Plasma

AIHA: American Industrial Hygiene Association

Air Terminal: A rod that extends above a surface to attract lightning strikes.

AL: Action Level

B

Beam: a structural member, usually horizontal, with a main function to carry loads cross-ways to its longitudinal axis.

Branch Circuit: Insulated conductors used to carry electricity to an associated device or devices that originate from a single circuit breaker.

BTUH: British Thermal Unit per Hour; A traditional unit of energy.

BX Cable: Cable with flexible steel armored outer tube with individual copper conductors insulated with rubber and covered with a cotton braided sheath.

C

Cantilever: refers to the part of a member that extends freely over a beam or wall, which is not supported at its end.

Cast Iron: a large group of ferrous alloys that are easily cast. Cast iron tends to be brittle and is resistant to destruction and weakening by oxidation. The amount of carbon in cast irons is 2.1 to 4 wt%.

CFR: Code of Federal Regulation

Cistern: An underground receptacle for storage of liquids, usually water.

Clay Sewer: Sewer pipe made from vitrified clay that is highly resistant to corrosion.

Column: a main vertical member that carries axial loads from beams or girders to the foundation parallel to its longitudinal axis.

D

DC: Direct current; the unidirectional flow of current through an electrical circuit. Direct current is produced through such sources as batteries, thermocouples, or photovoltaic solar cells.

Dead Load: describes the loads from the weight of the permanent components of the structure.

Deflection: the displacement of a structural member or system under a load.

DRO: Diesel-Range Organics

E

ELPAT: Environmental Lead Proficiency Analytical Testing

EMT: Electro-metallic tubing; A metallic tube raceway that is used to carry and protect current carrying conductors or cables.

EPA: Environmental Protection Agency

F

Flue Vent: A duct or pipe conveying combustion by-products from a heater or furnace.

Fluorescent: A source of light that emits light radiation at longer wavelengths and lower energy.

Footing: a slab of concrete or an assortment of stones under a column, wall, or other structural member to transfer the loads of the member into the surrounding soil.

Foundation: supports a building or structure.

FRP: Fiberglass reinforced plastic

Full Sawn (FS): Lumber cut, in the rough, to its full nominal size.

G

Gable: located above the elevation of the eave line of a double-sloped roof.

Galvanized Steel: Steel coated with zinc carbonate to resist corrosion.

GPM: Gallon per minute; a standard unit of volumetric liquid flow rate.

Grade: the ground elevation of the soil.

Gravity Vent: Openings in a roof intended to vent hot air by the action of convection.

Gray Water: Wastewater generated from domestic washing activities and not containing human waste.

GRO: Gasoline Range Organics

H

Header: a member that carries joists, rafters or beams and is placed between other joists, rafters or beams.

Hip Roof: a roof sloping from all four sides of a building.

HUD: Housing and Urban Development

HVAC: Heating, Ventilation, and Air Conditioning.

I

IAQ: Indoor Air Quality

IEUBK: Integrated Exposure Uptake Biokinetic

Incandescent: A source of light that works by incandescence, or works by a heat-driven light emission through black-body radiation.

Inverter: A device that converts electrical direct current (DC) to electrical alternating current (AC).

J

Joist: a horizontal structural load-carrying member which supports floors and ceilings.

K

kVA: Kilovolt-ampere equal to 1,000 volt-amperes. kVA is a unit to express the apparent power consumed in an electrical circuit or electrical device.

kW: Kilowatt equal to 1,000 watts. A kilowatt is typically used to express the output power consumption of large devices or electrical systems.

L

LBP: Lead-Based Paint

LCP: Lead-Containing Paint

LCS: Lead-Contaminated Soils

Leach Field: A drain field used to remove contaminants and impurities from liquid that emerges from a septic tank.

LED: Light emitting diode; a semiconductor light source that can emit light in various colors and brightness.

Live Load: nonpermanent loads on a structure created by the use of the structure.

Load: an outside force that affects the structure or its members.

Louver: An opening with horizontal slats angled to allow passage of air while keeping out rain and snow.

M

Mg/kg: Milligrams per Kilogram

N

NEC: National Electric Code.

NESHAP: National Emission Standards for Hazardous Air Pollutants

Nonpotable Water: Water that has not been approved for safe human consumption.

NVLAP: National Voluntary Laboratory Accreditation Program

O

OSHA: Occupational Safety and Health Administration

Overcurrent Protection: A fuse, circuit breaker or relay that will open the electrical circuit when the downstream electrical current exceeds the stated current rating.

P

Passive Ventilation: Ventilation of a building without the use of a fan or other mechanical system.

Pitch: the slope of a member defined as the ratio of the total rise to the total run.

PLM: Polarized Light Microscopy

PV: Photovoltaic; An array of solar modules or cells that collect solar energy and convert the energy into direct current electricity.

PVC: Polyvinyl Chloride; A biologically and chemically resistant plastic widely used for household sewage pipe.

R

Rafter: a sloped structural load-carrying member which supports the roof.

RBM: Regulated/Hazardous Material

Reaction: the force or moment developed at the points of a support.

RLM: Industrial stem mounted reflector.

Romex: Wiring with rubber insulated conductors in an overall sheath of braided cotton fiber.

S

Seismic Load: loads produced during the seismic movements of an earthquake.

Septic Tank: A sewage tank containing anaerobic bacteria which decomposed waste discharged into tank.

Shear: forces resulting in two touching parts of a material to slide in opposite directions parallel to their plane of contact.

Snow Load: loads produced from the accumulation of snow.

Span: the distance between supports.

Step-down Transformer: A device that converts a high voltage down to a lower voltage through a series of winding coils.

Structural Steel: an iron alloy with a carbon content of 0.16% to 0.29%. Steel is malleable, and easily welded.

Strut: a structural brace that resists axial forces.

Stud: a vertical wall member used to construct partitions and walls.

T

Thermal Expansion Tank: A tank used in a closed water heating system to absorb excess water pressure caused by thermal expansion.

TSI: Thermal System Insulation

Turbine Vent: Vents utilizing rotating wind vanes to create air flow.

V

Vent Stack: A vertical pipe providing ventilation.

W

WAC: Wisconsin Administrative Code

WDNR: Wisconsin Department of Natural Resources

Wrought Iron: an iron alloy with very low carbon content, in comparison to steel. Wrought iron is tough, malleable, ductile, and easily welded.

X

XRF: X-ray fluorescence analyzer

Other

30 $\mu\text{g}/\text{m}^3$: 30 micrograms per cubic meter

$\mu\text{g}/\text{SF}$: Micrograms of Lead Dust per Square Foot of Floor Space

1x: Piece of dimensional lumber 1" (nominal) / $\frac{3}{4}$ " (actual) thick

OTHER RESOURCES

Source: Letter from Regional Director of the Midwest Region to Superintendent of Apostle Islands National Lakeshore, June 16, 1977, located at APIS/NPS Business Office File # D3423-Outer

<u>Paint (cheap, fences, etc.) Whitewash</u>	1/2	1/4	1/8	1/16
1 bushel* unslaked lime or Hydrated lime	$\frac{1}{2}$ (2 peck)	$\frac{1}{4}$ (1 peck)	$\frac{1}{8}$ (1 gal)	$\frac{1}{16}$ ($\frac{1}{2}$ gal)
20 lbs Spanish Whiting	10 lbs	5 lbs	2 $\frac{1}{2}$ lbs	1 $\frac{1}{4}$ lbs
17 lbs Rock Salt	8 $\frac{1}{2}$ lbs	4 $\frac{1}{4}$ lbs	2 $\frac{1}{8}$ lbs	1 $\frac{1}{16}$ lbs
12 lbs Brown Sugar	6 lbs	3 lbs	1 $\frac{1}{2}$ lbs	$\frac{3}{4}$ lbs
Slake lime w/ 40 gallons water	20 gals	10 gals	5 gals	2 $\frac{1}{2}$ gals

Apply two coats to wood

Apply three coats to stone or brick

*Bushel = $17 \frac{3}{4}$ " x 15" x 8" deep = 1 bushel - 4 pecks or 2130 cubic inches
 $14 \frac{1}{3}$ " x 10" x 7 $\frac{1}{2}$ " = $\frac{1}{2}$ bushel – 2 pecks

Boxes = 8" x 8" x 8 $\frac{5}{12}$ " deep = 1 peck – 2 gallons (8 qts.)
 7" x 8" x 4 $\frac{1}{8}$ " = 1 gallon

APPENDIX A

1
2
3

1 **APPENDIX B: SUMMARY OF HAZARDOUS MATERIAL FINDINGS**

2

1 **OUTER ISLAND TOWER**

Building Number	LCS ID 006376
Building Name	Outer Island Tower
>1% Asbestos Confirmed	
Asbestos Assumed ⁴⁴	Adhesives, Plaster, Brick/Block Filler, Caulk, Transite and Roofing
Detectable Lead in Paint Confirmed	Window Sashes and Window Trims
Detectable Lead in Paint Assumed	Interior and Exterior Painted Surfaces
Lead Dust on Floors >40 µg/SF Confirmed ⁴⁵	
Lead Dust on Floors >40 µg/SF Assumed ²	Throughout
Lead Dust on Floors <40 µg/SF Confirmed ²	
Visual Mold	Yes
Lead in Soils >50 mg/kg ⁴⁶	Roof Drip line
Lead in Soils <50 mg/kg	
Lead in Soils Assumed	

2
3

< = Greater Than

< = Less Than

µg/SF = Micrograms of Lead Dust per Square Foot of Floor Space

mg/kg = Milligrams of Lead per Kilogram of Soil

⁴⁴ Materials listed are those identified or assumed to be present during the September 15, 2009 site assessment

⁴⁵ In accordance with EPA 40 CFR part 457 the clearance level for lead dust on floors in child occupied housing is 40 micrograms of lead dust per square foot of floor space.

⁴⁶ In accordance with NR720, WIS. Adm Code; 50 milligrams per kilogram, is the conservative acceptable residual containment level for lead in soil based on human health risk from direct contact (ingestion or inhalation) related to nonindustrial land use and considering more than one contaminant may be present in the soil. However, site specific Risk Assessment is recommended to identify the site specific clean up levels for lead contaminated soil at each of these sites.

1 **KEEPERS QUARTERS**

Building Number	LCS ID 101140
Building Name	Outer Island Keepers Quarters
>1% Asbestos Confirmed	Floor Tile
Asbestos Assumed ⁴⁷	Adhesives, Plaster, Brick/Block Filler, Caulk, Transite and Wall Interiors
Detectable Lead in Paint Confirmed	Window Sashes and Trims, Doors and Trims, Walls and Ceilings
Detectable Lead in Paint Assumed	Interior and Exterior Painted Surfaces
Lead Dust on Floors >40 µg/SF Confirmed ⁴⁸	
Lead Dust on Floors >40 µg/SF Assumed ²	Throughout
Lead Dust on Floors <40 µg/SF Confirmed ²	
Visual Mold	Yes
Lead in Soils >50 mg/kg ⁴⁹	Roof Drip line
Lead in Soils <50 mg/kg	
Lead in Soils Assumed	

2
3

< = Greater Than

< = Less Than

µg/SF = Micrograms of Lead Dust per Square Foot of Floor Space

mg/kg = Milligrams of Lead per Kilogram of Soil

⁴⁷ Materials listed are those identified or assumed to be present during the September 15, 2009 site assessment

⁴⁸ In accordance with EPA 40 CFR part 457 the clearance level for lead dust on floors in child occupied housing is 40 micrograms of lead dust per square foot of floor space.

⁴⁹ In accordance with NR720, WIS. Adm Code; 50 milligrams per kilogram, is the conservative acceptable residual containment level for lead in soil based on human health risk from direct contact (ingestion or inhalation) related to nonindustrial land use and considering more than one contaminant may be present in the soil. However, site specific Risk Assessment is recommended to identify the site specific clean up levels for lead contaminated soil at each of these sites.

1 **FOG SIGNAL BUILDING**

Building Number	LCS ID 006378
Building Name	Outer Island Fog Signal Building
>1% Asbestos Confirmed	
Asbestos Assumed ⁵⁰	Adhesives, Brick/Block Filler, Caulk, Transite and Wall Interiors
Detectable Lead in Paint Confirmed	Window Sashes and Trims, Doors and Trims, and Generators
Detectable Lead in Paint Assumed	Interior and Exterior Painted Surfaces
Lead Dust on Floors >40 µg/SF Confirmed ⁵¹	
Lead Dust on Floors >40 µg/SF Assumed ²	
Lead Dust on Floors <40 µg/SF Confirmed ²	
Visual Mold	
Lead in Soils >50 mg/kg ⁵²	
Lead in Soils <50 mg/kg	
Lead in Soils Assumed	Yes

2
3

< = Greater Than

< = Less Than

µg/SF = Micrograms of Lead Dust per Square Foot of Floor Space

mg/kg = Milligrams of Lead per Kilogram of Soil

⁵⁰ Materials listed are those identified or assumed to be present during the September 15, 2009 site assessment

⁵¹ In accordance with EPA 40 CFR part 457 the clearance level for lead dust on floors in child occupied housing is 40 micrograms of lead dust per square foot of floor space.

⁵² In accordance with NR720, WIS. Adm Code; 50 milligrams per kilogram, is the conservative acceptable residual containment level for lead in soil based on human health risk from direct contact (ingestion or inhalation) related to nonindustrial land use and considering more than one contaminant may be present in the soil. However, site specific Risk Assessment is recommended to identify the site specific clean up levels for lead contaminated soil at each of these sites.

1 **OIL STORAGE**

Building Number	LCS ID 006379
Building Name	Outer Island Oil Storage
>1% Asbestos Confirmed	
Asbestos Assumed ⁵³	Adhesives, Brick/Block Filler, Caulk, Transite and Wall Interiors
Detectable Lead in Paint Confirmed	
Detectable Lead in Paint Assumed	Interior and Exterior Painted Surfaces
Lead Dust on Floors >40 µg/SF Confirmed ⁵⁴	
Lead Dust on Floors >40 µg/SF Assumed ²	
Lead Dust on Floors <40 µg/SF Confirmed ²	
Visual Mold	
Lead in Soils >50 mg/kg ⁵⁵	
Lead in Soils <50 mg/kg	
Lead in Soils Assumed	Yes

2
3

< = Greater Than

< = Less Than

µg/SF = Micrograms of Lead Dust per Square Foot of Floor Space

mg/kg = Milligrams of Lead per Kilogram of Soil

⁵³ Materials listed are those identified or assumed to be present during the September 15, 2009 site assessment

⁵⁴ In accordance with EPA 40 CFR part 457 the clearance level for lead dust on floors in child occupied housing is 40 micrograms of lead dust per square foot of floor space.

⁵⁵ In accordance with NR720, WIS. Adm Code; 50 milligrams per kilogram, is the conservative acceptable residual containment level for lead in soil based on human health risk from direct contact (ingestion or inhalation) related to nonindustrial land use and considering more than one contaminant may be present in the soil. However, site specific Risk Assessment is recommended to identify the site specific clean up levels for lead contaminated soil at each of these sites.

1 **PRIVY**

Building Number	LCS ID 006380
Building Name	Outer Island Privy
>1% Asbestos Confirmed	
Asbestos Assumed ⁵⁶	Adhesives, Brick/Block Filler, Caulk, Transite and Wall Interiors
Detectable Lead in Paint Confirmed	
Detectable Lead in Paint Assumed	Interior and Exterior Painted Surfaces
Lead Dust on Floors >40 µg/SF Confirmed ⁵⁷	
Lead Dust on Floors >40 µg/SF Assumed ²	Throughout
Lead Dust on Floors <40 µg/SF Confirmed ²	
Visual Mold	
Lead in Soils >50 mg/kg ⁵⁸	
Lead in Soils <50 mg/kg	
Lead in Soils Assumed	Yes

2

3

4

< = Greater Than

< = Less Than

µg/SF = Micrograms of Lead Dust per Square Foot of Floor Space

mg/kg = Milligrams of Lead per Kilogram of Soil

⁵⁶ Materials listed are those identified or assumed to be present during the September 15, 2009 site assessment

⁵⁷ In accordance with EPA 40 CFR part 457 the clearance level for lead dust on floors in child occupied housing is 40 micrograms of lead dust per square foot of floor space.

⁵⁸ In accordance with NR720, WIS. Adm Code; 50 milligrams per kilogram, is the conservative acceptable residual containment level for lead in soil based on human health risk from direct contact (ingestion or inhalation) related to nonindustrial land use and considering more than one contaminant may be present in the soil. However, site specific Risk Assessment is recommended to identify the site specific clean up levels for lead contaminated soil at each of these sites.

1 **APPENDIX C: MATERIAL ANALYSIS REPORTS, OUTER ISLAND**

2

1 **OUTER ISLAND ACM SAMPLE CHART**

2

Sample #	Sample Date	API ID	Sample Location	Material Description	Laboratory Result
B-OIKQ-FT1-01	9/14/2009	26768	Keepers Quarters - Second Floor	Brown with black and white steaks floor tile with brown mastic	Trace Chrysotile in Brown mastic, 10% Chrysotile in Brown tile
B-OIKQ-BF1-01	9/14/2009	26768	Keepers Quarters - First Floor	Orange/white plaster block filler	ND
B-OIKQ-BF2-02	9/14/2009	26768	Keepers Quarters - First Floor	White chalky plaster block filler	ND
B-OIKQ-SF1-01	9/14/2009	26768	Keepers Quarters - First Floor	Orange/brown pattern sheet flooring	ND
B-OIKQ-SF2-01	9/14/2009	26768	Keepers Quarters - First Floor	Blue sheet flooring w/ black/tan fibrous backing and White leveler	ND
B-OIKQ-SF3-01	9/14/2009	26768	Keepers Quarters - First Floor	Red sheet flooring w/ black fibrous backing and Tan leveler	ND
B-OIKQ-SF4-01	9/14/2009	26768	Keepers Quarters - First Floor	Green marble sheet flooring with black backing and white leveling compound	ND
B-OIKQ-WT1-01	9/14/2009	26768	Keepers Quarters - First Floor	Thick applied white granular wall texture	ND
B-OIKQ-DW1-01	9/14/2009	26768	Keepers Quarters - First Floor	Pink granular drywall	ND
B-OIKQ-WP-01	9/14/2009	26768	Keepers Quarters - First Floor	Wall plaster patching material	ND

3 ND=None Detected

4 TR=Trace, <1% Visual Estimate

5

6

7

8

1 **OUTER ISLAND LEAD SAMPLE CHART**

2

Sample ID	Sample Type	API ID	Sample Location	Sample Date	Reporting Limit (ug/sq ft)	Lead Concentration (ug/sq ft)
S-OILH-01	Soil Composite	26768	Outer Island Tower dripline	9/14/2009	16.9	116.5
S-OIKQ-01	Soil Composite	26768	Keepers Quarters dripline	9/14/2009	16.9	794.3

1

APPENDIX D: FABRIC ANALYSIS

2

**Fabric Analysis
Outer Island
Apostle Island National Lakeshore
October, 2009**

On Tuesday, October 6, 2009, David Arbogast, architectural conservator, of Davenport, Iowa, received a large box containing paint and mortar samples from Elizabeth Hallas, AIA, LEED AP. Senior Associate of Andrews & Anderson Architects, PC of Golden, Colorado. She is in the process of preparing Historic Structures Reports for the historic lighthouse complexes of the Apostle Islands National Lakeshore, headquartered in Bayfield, Wisconsin. As part of the HSRs paint and mortar/plaster analysis is required in an attempt to ascertain historic finishes, mortars, and plasters for the subject structures. The samples were divided into sets contained within large manila mailing envelopes. The analysis follows the order in which the large envelopes have been arranged. The two sets which are contained within this report were from the Outer Island Lighthouse Complex. There were 30 samples in the first set, of which 21 were paint samples and nine were of plaster and mortar (nos. 4, 8, 17, 22, and 24 – 28) and there were 25 samples in the second set of which one (no. 45) was a plaster sample.

During the preceding twenty or more years Mr. Arbogast has performed paint analyses for various structures at the Apostles Islands. Those samples and his reports are in the archives at the headquarters in Bayfield and may be examined in relation to the findings from this analysis.

The paint samples were visually examined on Wednesday, October 21, using the same procedures employed for the samples from the previous seven sets from the other lighthouse complexes. Numbering of the samples commenced with one and ended with 55. The quality of the samples ranged from fair to quite excellent. Because of the exposed nature of many of the samples the paint exhibited weathering and appeared in several cases to be missing older layers seen in other, better samples. The layers are listed from top (most recent) to bottom (oldest). The following results were obtained from the analysis:

Oil House

Sample 1	Munsell
Dark maroon	7.5R 3/6
Dark maroon	7.5R 3/6
Yellow	2.5Y 8/4
Dark green	5G 4/4
Dark green	5G 4/4
Dark green	5G 4/4
Dark green	5G 4/4
Green	5GY 6/2
Dark maroon	7.5R 3/6
Dark maroon	7.5R 3/6

The first sample was collected from the brick of the oil house exterior. Its analysis revealed a relatively large number of paint layers. Most of the pieces did not reveal the oldest pair of dark maroon layers, but they remained semi-detached on one of the pieces. There was no substrate attached to any of the pieces.

Oil House

Sample 2	Munsell
Brown	10YR 6.5/8
Brown	10YR 6.5/8

Brown	10YR 6.5/8
Whitewash	N 9.5/
Whitewash	N 9.5/
Whitewash	N 9.5/

The second sample came from the oil house interior. Its top layer was quite glossy. Beneath the brown layers a minimum of three layers of whitewash were observed.

Oil House

Sample 3	Munsell
Green	10G 5.5/1.5
Green	10G 5/2
Light gray-green	10G 8/1
Dark green	10G 4/2
Whitewash	N 9.5/

The third sample was removed from the oil house exterior. Beneath a set of four varying shades of dull green were multiple layers of whitewash as evidenced by its dissolution in hydrochloric acid.

As noted in the introduction above there were nine plaster and mortar samples in the first set of samples from the Outer Island Lighthouse complex. The fourth sample was the first of these samples. It was analyzed on Thursday, October 22 utilizing the standard testing procedure developed by E. Blaine Cliver, Regional Historical Architect of the North Atlantic Region of the National Park Service. The sample was from the mortar of the oil house. It was tan in color and was very soft in consistency. The resultant reaction displaced a minimum amount of water. That fact, coupled with the softness of the sample and its very rapid filtering time leads to the conclusions that it was probably composed of sand and a minimum amount of lime. There were an extremely large proportion of fines in the sample indicating that the sand was originally quite dirty. The sand sieve analysis revealed bits of red brick which were trapped in the two largest sieves. The largest sieve contained only brick bits and the second largest sieve also contain some sand as well. Taking that into account, the sand was extremely fine. At least 42% passed all of the sieves and at least 36% was trapped in the finest sieve.

Mortar/Plaster/Stucco Analysis Test Sheet

Sample No. 4
 Building: Oil House, Outer Apostle Islands NL
 Location: Mortar
 Sample Description: Tan, very soft, small reaction, rapid filtering time

Test No. 1 – Soluble Fraction

Data:

1. <u>185.5</u> Container A weight	8. <u>No</u> Hair or fiber <u> </u> type
2. <u>193.2</u> Container A and sample	9. <u>3.8</u> Fines and paper weight
3. <u>760.22</u> Barometric pressure	10. <u>3.0</u> Filter paper weight

4. 23 Temperature 11. 190.5 Sand and Container A weight
 5. 0.03 Liters of water displaced 12. 3.8 cc. of sand
 6. Champagne Filtrate color 13. 33.8 Weight of graduated cylinder and sand
 7. Tan Fines color 14. 28.8 Weight of graduated cylinder

Computations:

15. 7.7 Starting weight of sample: No. 2 – No. 1
 16. 0.8 Weight of fines: No. 9 – No. 10
 17. 5.0 Weight of sand: No. 11 – No. 1
 18. .76 Sand density: No. 12 divided by (No. 13 – No. 14)
 19. 1.9 Weight of soluble content: No. 15 – (No. 16 + No. 17)
 20. 0.0012321 Mols. Of CO₂: No. 5 x No. 3. x 0.016 divided by (No. 4 + 273.16 C.)
 21. 0.12 Gram weight of CaCO₃: 100 x No. 20
 22. 1.78 Gram weight of Ca(OH)₂: No. 19 – No. 21
 23. .024 Mols. of Ca(OH)₂: No. 22 divided by 74
 24. 1.87 Gram total weight of Ca(OH)₂: 74 x (No. 20 + No. 23)
 25. 0.05 Gram weight CO₂: No. 20 x 44
 26. 1.11 Gram weight total possible CO₂: 44 x (No. 20 + No. 23)
 27. 4.5 %CO₂ gain: No. 25 divided by No. 26

Conclusions:

28. 7.65 Gram weight of sample: No. 15 – No. 25
 29. 10.46 Fine parts/volume: No. 16 divided by No. 28
 30. 49.67 Sand parts/volume: (No. 17 divided by No. 28) x No. 18
 31. 26.89 Lime parts/volume: (No. 24 divided by No. 28) x 1.1

Cement (if present)

32. Portland cement parts/volume: (No. 16 divided by No. 28) x 0.78
 33. Natural cement parts/volume: (No. 16 divided by No. 28) x 0.86
 34. Lime with cement parts/volume: (No. 16 x 0.2) divided by No. 28 x 1.1

Test No. 2 – Sand Sieve Analysis

Sieve	Sieve w/ sand weight	Sieve weight	Sand weight	Sand ratio
No. 10	<u>107.0</u>	<u>106.7</u>	<u>0.3</u>	<u>6</u>
No. 20	<u>106.6</u>	<u>106.4</u>	<u>0.2</u>	<u>4</u>
No. 30	<u>99.4</u>	<u>99.3</u>	<u>0.1</u>	<u>2</u>
No. 40	<u>101.2</u>	<u>100.7</u>	<u>0.5</u>	<u>10</u>
No. 50	<u>95.0</u>	<u>93.2</u>	<u>1.8</u>	<u>36</u>
Base	<u>73.3</u>	<u>71.2</u>	<u>2.1</u>	<u>42</u>

Outhouse

Sample 5

Munsell

Whitewash

N 9.5/

The fifth sample continued the paint series and was from the brick exterior wall of the outhouse. Its relatively thick coating of whitewash layers entirely disappeared in hydrochloric acid.

Outhouse

Sample 6	Munsell
Green	10G 5.5/1.5
Dark gray-green	10G 4/1
Gray-green	5G 5/1
White	N 9.5/
Whitewash	N 9.5/

The sixth sample was found on the trim of the outhouse exterior. Interestingly, it retained a stark white paint layer above a set of whitewash layers. The paint was impervious to the acid as opposed to the whitewash which completely dissolved in the acid.

Outhouse

Sample 7	Munsell
Green	5G 4.5/4
Dark gray	5Y 4/1
Dark gray	5Y 4/1

The seventh sample was collected from the exterior side of the outhouse door. Its analysis revealed only three paint layers with dark gray being the oldest.

The eighth sample continued the series of mortar and plaster samples. It was collected from the outhouse mortar. It was tan in color and was very soft with large, visible sand grains. It had a fast and bubbly reaction with a relatively small water displacement. That, along with a rapid filtering time indicated a composition of sand and lime. There were a relatively small proportion of fines, indicating a level of care initially taken to clean the sand. As anticipated, the sand sieve analysis revealed coarse sand. Over 5% failed to pass any of the sieves, which was a large amount than that which passed all but the finest sieve and all of the sieves, combined. Almost 2/3 was trapped in the second largest sieve.

Mortar/Plaster/Stucco Analysis Test Sheet

Sample No. 8
 Building: Outhouse, Outer Island, Apostle Islands NL
 Location: Mortar
 Sample Description: Tan, very soft, large sand grains, fast and bubbly reaction, rapid filtering time

Test No. 1 – Soluble Fraction**Data:**

1. <u>188.9</u> Container A weight	8. <u>No</u> Hair or fiber <u> </u> type
2. <u>203.8</u> Container A and sample	9. <u>3.3</u> Fines and paper weight
3. <u>760.22</u> Barometric pressure	10. <u>3.0</u> Filter paper weight
4. <u>23</u> Temperature	11. <u>199.8</u> Sand and Container A weight
5. <u>0.18</u> Liters of water displaced	12. <u>6.9</u> cc. of sand
6. <u>Clear</u> Filtrate color	13. <u>39.7</u> Weight of graduated cylinder and sand

7. Tan Fines color14. 28.8 Weight of graduated cylinder

Computations:

15. 14.9 Starting weight of sample: No. 2 – No. 116. 0.3 Weight of fines: No. 9 – No. 1017. 10.9 Weight of sand: No. 11 – No. 118. .633 Sand density: No. 12 divided by (No. 13 – No. 14)19. 3.7 Weight of soluble content: No. 15 – (No. 16 + No. 17)20. 0.0073925 Mols. Of CO₂: No. 5 x No. 3. x 0.016 divided by (No. 4 + 273.16 C.)21. 0.74 Gram weight of CaCO₃: 100 x No. 2022. 2.96 Gram weight of Ca(OH)₂: No. 19 – No. 2123. .04 Mols. of Ca(OH)₂: No. 22 divided by 7424. 3.51 Gram total weight of Ca(OH)₂: 74 x (No. 20 + No. 23)25. 0.33 Gram weight CO₂: No. 20 x 4426. 2.09 Gram weight total possible CO₂: 44 x (No. 20 + No. 23)27. 15.79 %CO₂ gain: No. 25 divided by No. 26

Conclusions:

28. 14.57 Gram weight of sample: No. 15 – No. 2529. 2.06 Fine parts/volume: No. 16 divided by No. 2830. 47.36 Sand parts/volume: (No. 17 divided by No. 28) x No. 1831. 26.50 Lime parts/volume: (No. 24 divided by No. 28) x 1.1

Cement (if present)

32. Portland cement parts/volume: (No. 16 divided by No. 28) x 0.7833. Natural cement parts/volume: (No. 16 divided by No. 28) x 0.8634. Lime with cement parts/volume: (No. 16 x 0.2) divided by No. 28 x 1.1

Test No. 2 – Sand Sieve Analysis

Sieve	Sieve w/ sand weight	Sieve weight	Sand weight	Sand ratio
No. 10	<u>107.4</u>	<u>106.8</u>	<u>0.6</u>	<u>5.55</u>
No. 20	<u>113.4</u>	<u>106.4</u>	<u>7.0</u>	<u>64.81</u>
No. 30	<u>101.1</u>	<u>99.3</u>	<u>1.8</u>	<u>16.67</u>
No. 40	<u>101.4</u>	<u>100.7</u>	<u>0.7</u>	<u>6.48</u>
No. 50	<u>93.5</u>	<u>93.2</u>	<u>0.3</u>	<u>2.78</u>
Base	<u>71.6</u>	<u>71.2</u>	<u>0.4</u>	<u>3.70</u>

Fog Signal

Sample 9

Munsell

Black

N 0.5/

Dark gray

N 2.0/

Black

N 0.5/

Gray-green

10 G 6/1

Dark gray

N 4.0/

Dark gray-green

10G 4/1

White

N 9.5/

The ninth sample was collected from the fog signal exterior. Its analysis revealed a set of gray and greenish gray layers. The oldest white layer appeared on only one end of one of the pieces.

Fog Signal

Sample 10	Munsell
Light green	7.5G 7/2

The tenth sample came from the workroom wall of the fog signal. It consisted on a single layer of light green paint without any substrate.

Fog Signal

Sample 11	Munsell
White	N 9.5/
White	N 9.5/
White	N 9.5/
Tan	2.5Y 6/5
Tan	2.5Y 7/4
Tan	2.5Y 7/4
Tan	2.5Y 7/4
Tan	2.5Y 7/4
Gray-tan	2.5Y 7/2

The eleventh sample was removed from the workroom ceiling of the fog signal. Beneath a set of three stark white layers was a relatively consistent set of tan layers with the oldest being somewhat grayer than the others. No substrate remained.

Fog Signal

Sample 12	Munsell
Gray	N 6.0/
White	5Y 9/1

The twelfth sample was from the workroom trim of the fog signal. The white layer on its wood surface was extremely thin and probably served as a prime coat for the gray finish coat.

Fog Signal

Sample 13	Munsell
Light green	7.5G 7/2
Cream	2.5Y 8.5/2
Light brown	10YR 6/4
Light brown	10YR 6/4
Light brown	10YR 6/4
Light brown	10YR 6/4
Black	N o.5/

The thirteenth sample was found on the storage wall of the fog signal. The substrate was a thick paper. On its surface was a very glossy, flaky, black substance which readily delaminated from the light brown paint on its surface. It is unlikely that the black layer was an applied finish.

Fog Signal

Sample 14	Munsell
White	N 9.5/
White	N 9.5/
White	N 9.5/
White	N 9.5/

The fourteenth sample was collected from the interior trim of the storage of the fog signal. Its top layer was a stark white, high-gloss paint. All of the layers were extremely thin and evenly applied.

Fog Signal

Sample 15	Munsell
Dark maroon	2.5R 3/4
Gray	5Y 7/1
Light green	7.5G 7/2
Light gray	5Y 8/1
Gray	5Y 6/1
Dark gray	5Y 4/1
White	5Y 9/1

The fifteenth sample came from the battery storage wall of the fog signal. It was in excellent condition, clearly revealing a set of evenly applied, thin layers with white being the oldest color. The sample was detached from its substrate.

Fog Signal

Sample 16	Munsell
Dark maroon	2.5R 3/4
Dark maroon	2.5R 3/4
Gray	5Y 6/1
Gray	5Y 6.5/1
Gray	5Y 6/1
Light gray	5Y 8/1
Green	5G 4/4
Charcoal	5Y 3/1
Light gray	5Y 8/1
Gray	5Y 7/1
Gray	5Y 7/1
Gray	5Y 7/1
White	5Y 9/1
Gray	5Y 6.5/1
Charcoal	5Y 3/1
Gray	5Y 5/1
White	5Y 9/1
White	5Y 9/1

The sixteenth sample was removed from the equipment room wall of the fog signal. It was truly outstanding in its quality, revealing a very large set of evenly-applied paint layers, but without attached substrate. The oldest pair of white layers was relatively thick indicating that they were probably not prime coats, but were finish coats.

The seventeenth sample continued the plaster and mortar samples. It came from the equipment room chimney mortar of the fog signal. It was tan in color and was very soft. With a very fast reaction and a small water displacement it was evident that this was composed of a relatively small part of lime in relation to its sand content. The sand sieve analysis revealed fine sand of which well over one-fifth passed all of the sieves and almost one-third was trapped in the finest sieve.

Mortar/Plaster/Stucco Analysis Test Sheet

Sample No. 17
 Building: Fog Signal, Outer Island, Apostle Islands NL
 Location: Equipment Room Chimney Mortar
 Sample Description: Tan, very soft, speedy reaction, extremely fast filtering time

Test No. 1 – Soluble Fraction

Data:

1. <u>185.1</u> Container A weight	8. <u>No</u> Hair or fiber _____ type
2. <u>201.0</u> Container A and sample	9. <u>3.6</u> Fines and paper weight
3. <u>760.22</u> Barometric pressure	10. <u>3.0</u> Filter paper weight
4. <u>23</u> Temperature	11. <u>197.9</u> Sand and Container A weight
5. <u>0.05</u> Liters of water displaced	12. <u>7.6</u> cc. of sand
6. <u>Champagne</u> Filtrate color	13. <u>41.6</u> Weight of graduated cylinder and sand
7. <u>Brown</u> Fines color	14. <u>28.87</u> Weight of graduated cylinder

Computations:

15. 15.5 Starting weight of sample: No. 2 – No. 1
 16. 0.6 Weight of fines: No. 9 – No. 10
 17. 12.8 Weight of sand: No. 11 – No. 1
 18. .59375 Sand density: No. 12 divided by (No. 13 – No. 14)
 19. 2.1 Weight of soluble content: No. 15 – (No. 16 + No. 17)
 20. 0.0020535 Mols. Of CO₂: No. 5 x No. 3. x 0.016 divided by (No. 4 + 273.16 C.)
 21. 0.20 Gram weight of CaCO₃: 100 x No. 20
 22. 1.9 Gram weight of Ca(OH)₂: No. 19 – No. 21
 23. .0256 Mols. of Ca(OH)₂: No. 22 divided by 74
 24. 1.74 Gram total weight of Ca(OH)₂: 74 x (No. 20 + No. 23)
 25. 0.09 Gram weight CO₂: No. 20 x 44
 26. 1.04 Gram weight total possible CO₂: 44 x (No. 20 + No. 23)
 27. 8.65 %CO₂ gain: No. 25 divided by No. 26

Conclusions:

28. 15.41 Gram weight of sample: No. 15 – No. 25
 29. 3.89 Fine parts/volume: No. 16 divided by No. 28
 30. 49.32 Sand parts/volume: (No. 17 divided by No. 28) x No. 18
 31. 12.42 Lime parts/volume: (No. 24 divided by No. 28) x 1.1

Cement (if present)

32. _____ Portland cement parts/volume: (No. 16 divided by No. 28) x 0.78

33. _____ Natural cement parts/volume: (No. 16 divided by No. 28) x 0.86
 34. _____ Lime with cement parts/volume: (No. 16 x 0.2) divided by No. 28 x 1.1

Test No. 2 – Sand Sieve Analysis

Sieve	Sieve w/ sand weight	Sieve weight	Sand weight	Sand ratio
No. 10	<u>107.3</u>	<u>106.8</u>	<u>0.5</u>	<u>3.97</u>
No. 20	<u>107.3</u>	<u>106.4</u>	<u>0.9</u>	<u>7.14</u>
No. 30	<u>100.3</u>	<u>99.3</u>	<u>1.0</u>	<u>7.94</u>
No. 40	<u>104.3</u>	<u>100.8</u>	<u>3.5</u>	<u>27.78</u>
No. 50	<u>97.2</u>	<u>93.2</u>	<u>4.0</u>	<u>31.75</u>
Base	<u>73.9</u>	<u>71.2</u>	<u>2.7</u>	<u>21.43</u>

Fog Signal

Sample 18	Munsell
Gray	N 7.0/
Dark gray	N 5.5/
Gray	N 7.0/
Light gray	N 8.0/
Gray	N 7.0/
Gray	N 6.5/

The eighteenth sample resumed the paint analysis. The sample was from the second floor wall of the fog signal. It consisted of a palette of layers in varying shades of gray.

Fog Signal

Sample 19	Munsell
White	5Y 9/1
White	5Y 9/1
Light gray	5Y 8/1
Gray	5Y 6/1
Dark gray	5Y 4/1
Gray	5Y 6/1
Off-white	5Y 8.5/1
Dark gray	5Y 4/1
White	5Y 9/1
White	5Y 9/1
White	5Y 9/1

The nineteenth sample was found on the second floor trim of the fog signal. It began with a pair of white layers and ended with a pair of white layers with a set of varying gray layers between them.

Fog Signal

Sample 20	Munsell
Red	7.5R 3/12
Gray	N 6.5/
Gray	N 6.5/

APPENDIX D

1	Charcoal	N 1.5/
2	Dark gray	N 4.0/
3	Dark gray	N 4.0/
4	Gray	N 7.0/
5	Dark gray	N 5.0/
6	Dark gray	N 5.0/
7	Gray	N 6.5/
8	Gray	N 6.5/
9	Gray	N 6.5/
10	Light gray	N 8.0/
11	White	5Y 9/1
12	White	5Y 9/1
13	White	5Y 9/1

The twentieth sample was collected from the equipment room of the fog signal. It was in excellent condition with numerous layers beneath a bright red top layer of paint. At the base of the sample, beneath the oldest white layer, was a thin layer of black and dark maroon which may have been a ferrous metal substrate. It did not appear to be an applied paint.

Fog Signal

Sample 21	Munsell
Gray	N 7.0/
Dark gray	N 5.5/
Gray	N 7.0/
Light gray	N 8.0/
Gray	N 7.0/
Gray	N 6.5/

Sample 21 came from the exterior baseboard trim of the fog signal. It retained a set of varying shades of gray paint.

Sample 22 resumed the mortar and plaster sample analysis. It was from the exterior mortar of the fog signal. Its attributes of color (gray), hardness, brittleness, very small water displacement, and lengthy filtering time pointing toward a mixture of Portland cement and sand. The sand sieve analysis revealed very moderate sand of which virtually passed the largest sieve and less than 3% pass all of the sieves. Almost half was trapped in sieve #40 and almost 30% was trapped in sieve #30.

Mortar/Plaster/Stucco Analysis Test Sheet

Sample No. 22
 Building: Fog Signal, Outer, Island, Apostle Islands NL
 Location: Exterior brick mortar
 Sample Description: Gray, hard and brittle, small reaction followed by prolonged reaction, slow filtering time

Test No. 1 – Soluble Fraction

Data:

1. <u>187.8</u> Container A weight	8. <u>No</u> Hair or fiber <u> </u> type
2. <u>227.2</u> Container A and sample	9. <u>4.1</u> Fines and paper weight
3. <u>760.22</u> Barometric pressure	10. <u>3.1</u> Filter paper weight
4. <u>23</u> Temperature	11. <u>216.6</u> Sand and Container A weight
5. <u>0.08</u> Liters of water displaced	12. <u>19.3</u> cc. of sand
6. <u>Yellow-green</u> Filtrate color	13. <u>57.5</u> Weight of graduated cylinder and sand
7. <u>Brown</u> Fines color	14. <u>28.7</u> Weight of graduated cylinder

Computations:

15. <u>39.4</u> Starting weight of sample: No. 2 – No. 1
16. <u>1.0</u> Weight of fines: No. 9 – No. 10
17. <u>28.8</u> Weight of sand: No. 11 – No. 1
18. <u>.67</u> Sand density: No. 12 divided by (No. 13 – No. 14)
19. <u>9.6</u> Weight of soluble content: No. 15 – (No. 16 + No. 17)
20. <u>0.0032856</u> Mols. Of CO ₂ : No. 5 x No. 3. x 0.016 divided by (No. 4 + 273.16 C.)
21. <u>0.33</u> Gram weight of CaCO ₃ : 100 x No. 20
22. <u>9.27</u> Gram weight of Ca(OH) ₂ : No. 19 – No. 21
23. <u>.1253</u> Mols. of Ca(OH) ₂ : No. 22 divided by 74
24. <u>9.51</u> Gram total weight of Ca(OH) ₂ : 74 x (No. 20 + No. 23)
25. <u>0.14</u> Gram weight CO ₂ : No. 20 x 44
26. <u>5.66</u> Gram weight total possible CO ₂ : 44 x (No. 20 + No. 23)
27. <u>2.47</u> %CO ₂ gain: No. 25 divided by No. 26

Conclusions:

28. <u>39.26</u> Gram weight of sample:	No. 15 – No. 25
29. <u>2.55</u> Fine parts/volume:	No. 16 divided by No. 28
30. <u>49.15</u> Sand parts/volume:	(No. 17 divided by No. 28) x No. 18
31. <u> </u> Lime parts/volume:	(No. 24 divided by No. 28) x 1.1

Cement (if present)

32. <u>1.99</u> Portland cement parts/volume:	(No. 16 divided by No. 28) x 0.78
33. <u> </u> Natural cement parts/volume:	(No. 16 divided by No. 28) x 0.86
34. <u> </u> Lime with cement parts/volume:	(No. 16 x 0.2) divided by No. 28 x 1.1

Test No. 2 – Sand Sieve Analysis

Sieve	Sieve w/ sand weight	Sieve weight	Sand weight	Sand ratio
No. 10	<u>106.9</u>	<u>106.7</u>	<u>0.2</u>	<u>0.70</u>
No. 20	<u>109.0</u>	<u>106.4</u>	<u>2.6</u>	<u>9.12</u>
No. 30	<u>107.8</u>	<u>99.3</u>	<u>8.5</u>	<u>29.82</u>
No. 40	<u>114.6</u>	<u>100.7</u>	<u>13.9</u>	<u>48.77</u>
No. 50	<u>95.7</u>	<u>93.2</u>	<u>2.5</u>	<u>8.77</u>
Base	<u>72.0</u>	<u>71.2</u>	<u>0.8</u>	<u>2.81</u>

Lighthouse

Sample 23

White
White

Munsell

N 9.5/
N 9.5/

1	White	N 9.5/
2	White	N 9.5/
3	White	N 9.5/
4	White	N 9.5/
5	White	N 9.5/
6	White	N 9.5/

Sample 23 continued the paint layers. It was removed from the exterior siding of the lighthouse. Its analysis revealed eight layers of stark white paint.

Sample 24 continued the mortar and plaster sample analysis. The sample was collected from the exterior block mortar of the lighthouse. It proved to be a classic Portland cement and sand mortar. It was gray and hard. It had a very low water displacement. Its filtering was a matter of almost two days time. It produced gelatinous byproducts with the reaction which dried to a very large quantity of fines. There is no doubt that a large proportion of Portland cement was used in the mortar in relation to the sand content. The sand sieve analysis was unusually interesting in that the sand proved to be virtually identical to that analyzed from the kitchen plaster (sample 22) from the Michigan Island Light. All of it easily passed the largest sieve and almost 10% passed all of the sieves. One-third was trapped in the finest sieve, #50, and over 42% was trapped in the next finest sieve, #40.

Analysis of sample 25 and the subsequent four other plaster and mortar samples were undertaken on Friday, October 23. The sample 25 came from the exterior brick mortar of the lighthouse. It was tan in color and was moderately soft. With a very low water displacement and a relatively large amount of fines it appears that the mortar consisted of sand and cement. With its color (tan) this was probably natural cement and not Portland cement, which is typically gray. The relatively small sample size probably accounts for the fairly fast filtering time. Cement samples normally filter slowly. Natural cement, as its name implies, is quarried from the ground and is similar to the cements the Romans used for their construction. Portland cement, named after Portland, England where it was invented and first manufactured, is a synthetic cement. The primary difference is that natural cement contains a wider range of possible elements which can affect its performance whereas Portland cement is completely predictable and consistent. As a result, Portland cement is hard, impervious, and brittle. Natural cements tend not to be as hard or impervious or brittle, plus their color is different (shades of gray to white for Portland cement and tan or buff for natural cement). Natural cements were overtaken by Portland cement in the later decades of the nineteenth century as natural cement quarries played out and production costs for Portland cement became competitive. Generally, if one encounters natural cement it is an indication that it is from a nineteenth century structure. The sand sieve analysis revealed fine sand which easily passed the largest sieve. Well over one-quarter of it passed all of the sieves and well over one-third was trapped in the finest sieve, #50.

Sample 26 was removed from the brick mortar patch of the lighthouse. It was brown in color and was moderately hard. It had a very modest water displacement. Its hardness and water displacement coupled with a slow filtering time and a relatively large proportion of fines points toward a mixture of sand and cement. The brown color of the sample points toward a natural cement rather than a Portland cement, which is typically gray. The sand sieve analysis was quite interesting. It revealed moderately coarse sand. Identical amounts were trapped in sieves #40 and #50 (both over 25%) and in the base and in sieve #20 (both almost 15%). The sand in sieve #30 was almost the same in weight as the latter two from the base and sieve #20.

Sample 27 was from the brick mortar patch of the lighthouse. It was gray in color and was relatively soft. That softness, coupled with a fast and bubbly reaction, a fair amount of water displacement, as well as a rapid filtering time points toward a mixture of approximately five parts of sand to two parts of lime, by

volume. The sand sieve analysis produced a moderate sand which easily passed the largest sieve, but less than 7% passed all of the sieves. Almost one-fifth was trapped in the finest sieve, #50, and well over 58% was trapped in the next finest sieve, #40.

Sample 28 was taken from the mortar of the lighthouse. It was tan in color and moderately soft. Its minimal reaction is typical of a lime and cement mortar. The speed of the reaction coupled with its foaminess, in addition to the relatively large proportion of fines indicates a high probability that the cement was not Portland cement, but natural cement. In addition, natural cement yields a tan color whereas most Portland cement is gray in color. The sand sieve analysis revealed very moderate sand. Over 18% of it passed all of the sieves whereas only slightly over 1% was trapped in the largest sieve. In a curious turn of events equal portions were trapped in sieves #20 and #30 (both 13%) and in #40 and #50 (both over 27%). This was extremely similar to the sand of sample 25 above.

Mortar/Plaster/Stucco Analysis Test Sheet

Sample No. 24
 Building: Lighthouse, Outer Island, Apostle Islands NL
 Location: Exterior block mortar
 Sample Description: Gray, very hard, small reaction followed by prolonged reaction, gelatinous by-products, extremely slow filtering time

Test No. 1 – Soluble Fraction

Data:

1. <u>192.0</u> Container A weight	8. <u>No</u> Hair or fiber <u> </u> type
2. <u>208.6</u> Container A and sample	9. <u>8.8</u> Fines and paper weight
3. <u>760.22</u> Barometric pressure	10. <u>3.4</u> Filter paper weight
4. <u>23</u> Temperature	11. <u>200.3</u> Sand and Container A weight
5. <u>0.05</u> Liters of water displaced	12. <u>6.0</u> cc. of sand
6. <u>Off-white</u> Filtrate color	13. <u>37.1</u> Weight of graduated cylinder and sand
7. <u>Gray</u> Fines color	14. <u>28.8</u> Weight of graduated cylinder

Computations:

15. 16.6 Starting weight of sample: No. 2 – No. 1
 16. 5.4 Weight of fines: No. 9 – No. 10
 17. 8.3 Weight of sand: No. 11 – No. 1
 18. .7229 Sand density: No. 12 divided by (No. 13 – No. 14)
 19. 2.9 Weight of soluble content: No. 15 – (No. 16 + No. 17)
 20. 0.002 Mols. Of CO₂: No. 5 x No. 3. x 0.016 divided by (No. 4 + 273.16 C.)
 21. 0.20 Gram weight of CaCO₃: 100 x No. 20
 22. 2.7 Gram weight of Ca(OH)₂: No. 19 – No. 21
 23. .0364 Mols. of Ca(OH)₂: No. 22 divided by 74
 24. 2.84 Gram total weight of Ca(OH)₂: 74 x (No. 20 + No. 23)
 25. 0.09 Gram weight CO₂: No. 20 x 44
 26. 1.69 Gram weight total possible CO₂: 44 x (No. 20 + No. 23)
 27. 5.33 %CO₂ gain: No. 25 divided by No. 26

Conclusions:

APPENDIX D

28. 16.51 Gram weight of sample: No. 15 – No. 25
 29. 32.71 Fine parts/volume: No. 16 divided by No. 28
 30. 36.34 Sand parts/volume: (No. 17 divided by No. 28) x No. 18
 31. _____ Lime parts/volume: (No. 24 divided by No. 28) x 1.1
 Cement (if present)
 32. 25.51 Portland cement parts/volume: (No. 16 divided by No. 28) x 0.78
 33. _____ Natural cement parts/volume: (No. 16 divided by No. 28) x 0.86
 34. _____ Lime with cement parts/volume: (No. 16 x 0.2) divided by No. 28 x 1.1

Test No. 2 – Sand Sieve Analysis

Sieve	Sieve w/ sand weight	Sieve weight	Sand weight	Sand ratio
No. 10	<u>106.8</u>	<u>106.8</u>	<u>0.0</u>	<u>0</u>
No. 20	<u>106.7</u>	<u>106.4</u>	<u>0.3</u>	<u>3.61</u>
No. 30	<u>100.2</u>	<u>99.3</u>	<u>0.9</u>	<u>10.84</u>
No. 40	<u>104.3</u>	<u>100.8</u>	<u>3.5</u>	<u>42.17</u>
No. 50	<u>96.0</u>	<u>93.2</u>	<u>2.8</u>	<u>33.73</u>
Base	<u>72.0</u>	<u>71.2</u>	<u>0.8</u>	<u>9.64</u>

Mortar/Plaster/Stucco Analysis Test Sheet

Sample No. 25
 Building: Lighthouse, Outer Island, Apostle Islands NL
 Location: Exterior brick mortar
 Sample Description: Tan, moderately soft, fast and bubbly reaction, rapid filtering time

Test No. 1 – Soluble Fraction

Data:

1. <u>185.5</u> Container A weight	8. <u>No</u> Hair or fiber _____ type
2. <u>193.8</u> Container A and sample	9. <u>3.7</u> Fines and paper weight
3. <u>763.02</u> Barometric pressure	10. <u>2.9</u> Filter paper weight
4. <u>23</u> Temperature	11. <u>190.7</u> Sand and Container A weight
5. <u>0.08</u> Liters of water displaced	12. <u>3.4</u> cc. of sand
6. <u>Yellow-green</u> Filtrate color	13. <u>34.0</u> Weight of graduated cylinder and sand
7. <u>Light brown</u> Fines color	14. <u>28.8</u> Weight of graduated cylinder

Computations:

15. 8.3 Starting weight of sample: No. 2 – No. 1
 16. 0.8 Weight of fines: No. 9 – No. 10
 17. 5.2 Weight of sand: No. 11 – No. 1
 18. .653846 Sand density: No. 12 divided by (No. 13 – No. 14)
 19. 2.3 Weight of soluble content: No. 15 – (No. 16 + No. 17)
 20. 0.0032977 Mols. Of CO₂: No. 5 x No. 3. x 0.016 divided by (No. 4 + 273.16 C.)
 21. 0.33 Gram weight of CaCO₃: 100 x No. 20

22. 1.97 Gram weight of Ca(OH)₂: No. 19 – No. 21
 23. .0266 Mols. of Ca(OH)₂: No. 22 divided by 74
 24. 4.41 Gram total weight of Ca(OH)₂: 74 x (No. 20 + No. 23)
 25. 0.15 Gram weight CO₂: No. 20 x 44
 26. 2.62 Gram weight total possible CO₂: 44 x (No. 20 + No. 23)
 27. 5.73 %CO₂ gain: No. 25 divided by No. 26

Conclusions:

28. 8.15 Gram weight of sample: No. 15 – No. 25
 29. 9.81 Fine parts/volume: No. 16 divided by No. 28
 30. 41.72 Sand parts/volume: (No. 17 divided by No. 28) x No. 18
 31. Lime parts/volume: (No. 24 divided by No. 28) x 1.1

Cement (if present)

32. Portland cement parts/volume: (No. 16 divided by No. 28) x 0.78
 33. 8.44 Natural cement parts/volume: (No. 16 divided by No. 28) x 0.86
 34. Lime with cement parts/volume: (No. 16 x 0.2) divided by No. 28 x 1.1

Test No. 2 – Sand Sieve Analysis

Sieve	Sieve w/ sand weight	Sieve weight	Sand weight	Sand ratio
No. 10	<u>107.0</u>	<u>106.7</u>	<u>0.3</u>	<u>5.56</u>
No. 20	<u>107.2</u>	<u>106.4</u>	<u>0.8</u>	<u>14.81</u>
No. 30	<u>99.9</u>	<u>99.2</u>	<u>0.7</u>	<u>12.96</u>
No. 40	<u>102.1</u>	<u>100.7</u>	<u>1.4</u>	<u>25.93</u>
No. 50	<u>94.6</u>	<u>93.2</u>	<u>1.4</u>	<u>25.93</u>
Base	<u>72.0</u>	<u>71.2</u>	<u>0.8</u>	<u>14.81</u>

Mortar/Plaster/Stucco Analysis Test Sheet

Sample No. 26
 Building: Lighthouse, Outer Island, Apostle Islands NL
 Location: Brick mortar patch
 Sample Description: Brown, moderately hard, fast and bubbly reaction, slow filtering time

Test No. 1 – Soluble Fraction

Data:

1. <u>188.9</u> Container A weight	8. <u>No</u> Hair or fiber <u> </u> type
2. <u>199.4</u> Container A and sample	9. <u>3.8</u> Fines and paper weight
3. <u>763.02</u> Barometric pressure	10. <u>3.1</u> Filter paper weight
4. <u>23</u> Temperature	11. <u>193.8</u> Sand and Container A weight
5. <u>0.08</u> Liters of water displaced	12. <u>3.1</u> cc. of sand
6. <u>Yellow-green</u> Filtrate color	13. <u>33.7</u> Weight of graduated cylinder and sand
7. <u>Tan</u> Fines color	14. <u>28.8</u> Weight of graduated cylinder

APPENDIX D

Computations:

15. 10.5 Starting weight of sample: No. 2 – No. 1
16. 0.7 Weight of fines: No. 9 – No. 10
17. 4.9 Weight of sand: No. 11 – No. 1
18. .632653 Sand density: No. 12 divided by (No. 13 – No. 14)
19. 4.9 Weight of soluble content: No. 15 – (No. 16 + No. 17)
20. 0.0033 Mols. Of CO₂: No. 5 x No. 3. x 0.016 divided by (No. 4 + 273.16 C.)
21. 0.33 Gram weight of CaCO₃: 100 x No. 20
22. 4.57 Gram weight of Ca(OH)₂: No. 19 – No. 21
23. .0618 Mols. of Ca(OH)₂: No. 22 divided by 74
24. 4.81 Gram total weight of Ca(OH)₂: 74 x (No. 20 + No. 23)
25. 0.15 Gram weight CO₂: No. 20 x 44
26. 2.86 Gram weight total possible CO₂: 44 x (No. 20 + No. 23)
27. 5.24 %CO₂ gain: No. 25 divided by No. 26

Conclusions:

28. 10.35 Gram weight of sample: No. 15 – No. 25
29. 6.76 Fine parts/volume: No. 16 divided by No. 28
30. 29.95 Sand parts/volume: (No. 17 divided by No. 28) x No. 18
31. Lime parts/volume: (No. 24 divided by No. 28) x 1.1

Cement (if present)

32. Portland cement parts/volume: (No. 16 divided by No. 28) x 0.78
33. 5.82 Natural cement parts/volume: (No. 16 divided by No. 28) x 0.86
34. Lime with cement parts/volume: (No. 16 x 0.2) divided by No. 28 x 1.1

Test No. 2 – Sand Sieve Analysis

Sieve	Sieve w/ sand weight	Sieve weight	Sand weight	Sand ratio
No. 10	<u>106.8</u>	<u>106.8</u>	<u>0.0</u>	<u>0</u>
No. 20	<u>106.7</u>	<u>106.4</u>	<u>0.3</u>	<u>6.12</u>
No. 30	<u>99.7</u>	<u>99.3</u>	<u>0.4</u>	<u>8.16</u>
No. 40	<u>101.9</u>	<u>100.8</u>	<u>1.1</u>	<u>22.45</u>
No. 50	<u>94.9</u>	<u>93.2</u>	<u>1.7</u>	<u>34.69</u>
Base	<u>72.6</u>	<u>71.2</u>	<u>1.4</u>	<u>28.57</u>

Mortar/Plaster/Stucco Analysis Test Sheet

Sample No. 27
Building: Lighthouse, Outer Island, Apostle Islands NL
Location: Brick mortar patch
Sample Description: Gray, soft, fast and bubbly reaction, rapid filtering time

Test No. 1 – Soluble Fraction

Data:

- | | |
|--|---|
| 1. <u>185.1</u> Container A weight | 8. <u>No</u> Hair or fiber _____ type |
| 2. <u>203.1</u> Container A and sample | 9. <u>3.7</u> Fines and paper weight |
| 3. <u>763.02</u> Barometric pressure | 10. <u>3.1</u> Filter paper weight |
| 4. <u>23</u> Temperature | 11. <u>199.0</u> Sand and Container A weight |
| 5. <u>0.12</u> Liters of water displaced | 12. <u>8.4</u> cc. of sand |
| 6. <u>Yellow-green</u> Filtrate color | 13. <u>42.7</u> Weight of graduated cylinder and sand |
| 7. <u>Off-white</u> Fines color | 14. <u>28.8</u> Weight of graduated cylinder |

Computations:

- | |
|---|
| 15. <u>18.0</u> Starting weight of sample: No. 2 – No. 1 |
| 16. <u>0.6</u> Weight of fines: No. 9 – No. 10 |
| 17. <u>13.9</u> Weight of sand: No. 11 – No. 1 |
| 18. <u>.6043</u> Sand density: No. 12 divided by (No. 13 – No. 14) |
| 19. <u>3.5</u> Weight of soluble content: No. 15 – (No. 16 + No. 17) |
| 20. <u>0.0049466</u> Mols. Of CO ₂ : No. 5 x No. 3. x 0.016 divided by (No. 4 + 273.16 C.) |
| 21. <u>0.49</u> Gram weight of CaCO ₃ : 100 x No. 20 |
| 22. <u>3.01</u> Gram weight of Ca(OH) ₂ : No. 19 – No. 21 |
| 23. <u>.0406</u> Mols. of Ca(OH) ₂ : No. 22 divided by 74 |
| 24. <u>3.37</u> Gram total weight of Ca(OH) ₂ : 74 x (No. 20 + No. 23) |
| 25. <u>0.22</u> Gram weight CO ₂ : No. 20 x 44 |
| 26. <u>2.00</u> Gram weight total possible CO ₂ : 44 x (No. 20 + No. 23) |
| 27. <u>11</u> %CO ₂ gain: No. 25 divided by No. 26 |

Conclusions:

- | | |
|---|-------------------------------------|
| 28. <u>17.78</u> Gram weight of sample: | No. 15 – No. 25 |
| 29. <u>3.37</u> Fine parts/volume: | No. 16 divided by No. 28 |
| 30. <u>47.24</u> Sand parts/volume: | (No. 17 divided by No. 28) x No. 18 |
| 31. <u>20.85</u> Lime parts/volume: | (No. 24 divided by No. 28) x 1.1 |

Cement (if present)

- | | |
|--|--|
| 32. _____ Portland cement parts/volume: | (No. 16 divided by No. 28) x 0.78 |
| 33. _____ Natural cement parts/volume: | (No. 16 divided by No. 28) x 0.86 |
| 34. _____ Lime with cement parts/volume: | (No. 16 x 0.2) divided by No. 28 x 1.1 |

Test No. 2 – Sand Sieve Analysis

Sieve	Sieve w/ sand weight	Sieve weight	Sand weight	Sand ratio
No. 10	<u>106.8</u>	<u>106.8</u>	<u>0.0</u>	<u>0</u>
No. 20	<u>106.6</u>	<u>106.4</u>	<u>0.2</u>	<u>1.44</u>
No. 30	<u>101.4</u>	<u>99.3</u>	<u>2.1</u>	<u>15.11</u>
No. 40	<u>108.7</u>	<u>100.7</u>	<u>8.0</u>	<u>57.55</u>
No. 50	<u>95.9</u>	<u>93.2</u>	<u>2.7</u>	<u>19.42</u>
Base	<u>72.1</u>	<u>71.2</u>	<u>0.9</u>	<u>6.47</u>

Mortar/Plaster/Stucco Analysis Test Sheet

Sample No. 28
 Building: Lighthouse, Outer, Island, Apostle Islands NL
 Location: Brick mortar
 Sample Description: Tan, moderately soft, fast and foamy reaction, slow filtering time

Test No. 1 – Soluble Fraction

Data:

1. <u>187.8</u> Container A weight	8. <u>No</u> Hair or fiber <u> </u> type
2. <u>201.4</u> Container A and sample	9. <u>4.1</u> Fines and paper weight
3. <u>763.02</u> Barometric pressure	10. <u>3.0</u> Filter paper weight
4. <u>23</u> Temperature	11. <u>195.6</u> Sand and Container A weight
5. <u>0.03</u> Liters of water displaced	12. <u>5.9</u> cc. of sand
6. <u>Yellow-green</u> Filtrate color	13. <u>36.5</u> Weight of graduated cylinder and sand
7. <u>Tan</u> Fines color	14. <u>28.7</u> Weight of graduated cylinder

Computations:

15. <u>13.9</u> Starting weight of sample: No. 2 – No. 1
16. <u>1.1</u> Weight of fines: No. 9 – No. 10
17. <u>7.8</u> Weight of sand: No. 11 – No. 1
18. <u>.7564</u> Sand density: No. 12 divided by (No. 13 – No. 14)
19. <u>4.0</u> Weight of soluble content: No. 15 – (No. 16 + No. 17)
20. <u>0.0012366</u> Mols. Of CO ₂ : No. 5 x No. 3. x 0.016 divided by (No. 4 + 273.16 C.)
21. <u>0.12</u> Gram weight of CaCO ₃ : 100 x No. 20
22. <u>3.88</u> Gram weight of Ca(OH) ₂ : No. 19 – No. 21
23. <u>.0524</u> Mols. of Ca(OH) ₂ : No. 22 divided by 74
24. <u>3.97</u> Gram total weight of Ca(OH) ₂ : 74 x (No. 20 + No. 23)
25. <u>0.05</u> Gram weight CO ₂ : No. 20 x 44
26. <u>2.36</u> Gram weight total possible CO ₂ : 44 x (No. 20 + No. 23)
27. <u>2.12</u> %CO ₂ gain: No. 25 divided by No. 26

Conclusions:

28. <u>13.86</u> Gram weight of sample:	No. 15 – No. 25
29. <u>7.94</u> Fine parts/volume:	No. 16 divided by No. 28
30. <u>42.60</u> Sand parts/volume:	(No. 17 divided by No. 28) x No. 18
31. <u> </u> Lime parts/volume:	(No. 24 divided by No. 28) x 1.1

Cement (if present)

32. <u> </u> Portland cement parts/volume:	(No. 16 divided by No. 28) x 0.78
33. <u>6.83</u> Natural cement parts/volume:	(No. 16 divided by No. 28) x 0.86
34. <u> </u> Lime with cement parts/volume:	(No. 16 x 0.2) divided by No. 28 x 1.1

Test No. 2 – Sand Sieve Analysis

Sieve	Sieve w/ sand weight	Sieve weight	Sand weight	Sand ratio
No. 10	<u>106.9</u>	<u>106.8</u>	<u>0.1</u>	<u>1.23</u>

No. 20	<u>107.4</u>	<u>106.4</u>	<u>1.0</u>	<u>12.99</u>
No. 30	<u>100.3</u>	<u>99.3</u>	<u>1.0</u>	<u>12.99</u>
No. 40	<u>102.9</u>	<u>100.7</u>	<u>2.1</u>	<u>27.27</u>
No. 50	<u>95.3</u>	<u>93.2</u>	<u>2.1</u>	<u>27.27</u>
Base	<u>72.6</u>	<u>71.2</u>	<u>1.4</u>	<u>18.18</u>

Lighthouse**Sample 29****Munsell**

White

N 9.5/

White

N 9.5/

Sample 29 resumed the paint layers and was from the lighthouse exterior trim. It retained only a pair of stark white paint layers.

Lighthouse**Sample 30****Munsell**

Off-white

N 8.5/

Cream

2.5Y 8/3

White

N 9.5/

Tan

2.5Y 7/5

Tan

2.5Y 7/5

Tan

2.5Y 7/5

Tan

2.5Y 7/4

Tan

2.5Y 7/4

Tan

2.5Y 7/4

Tan

2.5Y 7/5

Light brown

10YR 6/4

Cream

2.5Y 8/2

Cream

2.5Y 8/2

Sample 30 was found on the entry wall of the lighthouse. A set of tan-colored paint layers represented a consistent history of that color. However, the oldest cream layers were lighter and grayer than the tan layers.

Lighthouse**Sample 31****Munsell**

Yellow

2.5Y 8/8

White

N 9.5/

White

N 9.5/

Light brown

10YR 7.5/5

Blue-green

5G 8/1

Blue-green

5G 8/1

Gray

5Y 6/1

Very dark brown

2.5Y 3/2

Gray

5Y 6/1

Gray

5Y 7/1

Very dark green

5G 3/4

Gray

5Y 7/1

Lighthouse

Sample 32 came from the living room wall of the lighthouse. There was a complete cleavage between the peach and the pastel blue-green layer. The peach-colored paint was firmly adhered to its paper substrate. The cleavage may indicate that the peach layer was incompatible with the pastel blue-green layer or that a thin film of dirt had built up over time resulting in the weak adhesion between the layers

Lighthouse

Sample 33 was removed from the interior door trim of the lighthouse. Its quality was quite excellent with clearly observable paint layers. Despite a very lengthy history of white paint the older layers were primarily gray with a few exceptions. The oldest layer was gray.

Lighthouse

Sample 34	Munsell
Pastel blue-green	5BG 9/1
Whitewash	N 9.5/
Light blue-green	5BG 8/1
Peach	7.5YR 7/4
Peach	7.5YR 7/4
Peach	7.5YR 7/4
Blue-green	5BG 8/1
Blue-green	5BG 7.5/1
Blue-green	5BG 8/1
Brown	7.5YR 5.5/4
Blue-green	5BG 6/1
Blue-green	5BG 6/1
Blue-green	5BG 7/2
White	5Y 9/1

Sample 34 was from the wall of bedroom 1 in the lighthouse. Its quality was excellent, revealing a large array of paint layers. The oldest white layer was extremely thin and probably served as a prime coat for an original finish coat of blue-green paint.

Lighthouse

Sample 35	Munsell
White	5Y 9/1
Brown	7.5YR 4/4
Brown	7.5YR 5/4
Blue-green	5BG 5/2
Blue-green	5BG 5/2
Blue-green	5BG 5/2
White	N 9.5/

Sample 35 was found on the wall of bedroom 1 of the lighthouse. Its paint layers were extremely thin and evenly applied. The oldest white layer was exceptionally thin and probably served as a prime coat for an original finish layer of blue-green.

Lighthouse

Sample 36	Munsell
White	N 9.5/
Whitewash	N 9.5/
Tan	10YR 8/4
Blue-green	5BG 5/2
Peach	10YR 8/5
White	5Y 9/1
Rose	10R 7/5
Tan	10YR 8/4
Blue-green	5BG 6/2
Blue-green	5BG 6/2
Gray	5Y 6.5/1

Sample 36 was collected from the wall of bedroom 2 of the lighthouse. Its analysis revealed a set of paint layers beneath a relatively thick layering of whitewash with a white paint layer on their surface. The oldest surviving paint layer was gray which may have served as a prime coat for a finish layer of blue-green.

	Lighthouse	
Sample 37		Munsell
Light yellow		5Y 8.5/4
Light rose		5YR 8/4

Sample 37 was collected from the wall of the first floor hallway of the lighthouse. It retained only two layers of paint on its paper substrate.

	Lighthouse	
Sample 38		Munsell
White		5Y 9/1
Warm gray		5Y 8/2
Light yellow		5Y 8.5/4
Light green		2.5G 7/2
Green		2.5G 5/4

Sample 38 came from the first floor main stair of the lighthouse. It revealed five paint layers on its paper substrate.

	Lighthouse	
Sample 39		Munsell
White		5Y 9/1
White		5Y 9/1
White		5Y 9/1
Tan		10YR 7/4
Tan		10YR 7/4
Tan		10YR 7/4

Sample 39 was removed from the wall of the first floor storage room of the lighthouse. Beneath the oldest tan layer was a translucent (roughly off-white – 5Y 8.5/1) layer which may have been a sizing or a glue probably used for wallpaper. The layers were quite thin and no substrate remained.

	Lighthouse	
Sample 40		Munsell
White		5Y 9/1
Tan		10YR 8/4
Tan		10YR 8/3
Tan		10YR 8/3
Tan		10YR 8/3
Gray		5Y 7/1
Light blue-green		5BG 8/2
Light blue-green		5BG 8/2
Rose		10R 6/4
Rose		10R 6/2

1	Light rose	10R 7/2
2	Light blue-green	5BG 8/1
3	Light blue-green	5BG 8/1
4	Light blue-green	5BG 8/1
5	Dark gray	5Y 4/1
6	Blue-green	5BG 5/4
7	Blue-green	5BG 5/4

Sample 40 was from the wall of the hall of the lighthouse. It was excellent in quality, revealing a large array of paint layers with blue-green being the oldest observed color on the plaster substrate.

Lighthouse

Sample 41	Munsell
Dark gray	N 4.0/
Gray	N 5.0/
Dark gray	N 4.0/
Gray	N 5.0/
Dark gray	N 4.0/
Dark gray	N 4.0/
Dark gray	N 4.0/
Whitewash	N 9.5/

Sample 41 was collected from the entry stair of the lighthouse. Beneath a set of dark gray and gray paint layers was a relatively thick set of ill-defined whitewash layers.

Lighthouse

Sample 42	Munsell
Red	5R 4/14
Cream	2.5Y 8.5/3
Cream	2.5Y 8.5/3
Cream	2.5Y 8.5/3
Cream	2.5Y 8.5/3

Sample 42 was collected from the wall of the entry of the lighthouse. Between a striking red surface layer of paint and the wood substrate were four layers of cream-colored paint.

Lighthouse

Sample 43	Munsell
Black	N 0.5/
White	5Y 9/1
Off-white	5Y 8.5/1

Sample 43 came from the window trim of the lighthouse tower. There were but three paint layers on the wood substrate of white the oldest off-white layer was extraordinarily thin and probably served as a prime coat for the white layer.

Lighthouse

Sample 44	Munsell
------------------	----------------

1	Brown	2.5YR 4/6
2	Gray	N 6.0/
3	Black	N 0.5/
4	Gray	N 6.0/
5	White	5Y 9/1
6	Gray	5Y 6/1
7	Dark gray	N 4.0/
8	Gray	5Y 5/1
9	Dark gray	N 4.5/
10	Gray	N 5.5/
11	Light gray	N 7.5/
12	Gray	N 5.5/
13	Dark gray	N 4.5/
14	Dark gray	N 4.5/
15	Gray	N 5.5/
16	Dark gray	N 4.5/
17	Black, glossy varnish	-----

Sample 44 was removed from the kitchen stair of the lighthouse. It proved to be particularly challenging, although it did reveal a large number of finish layers on its wood substrate. The oldest layer was a very glossy, very dark varnish.

Sample 45 was from the hall plaster of the lighthouse. It was warm gray in color and was very soft. It gave every evidence of having been composed of lime and sand with an approximate ratio of one part of lime to three parts of sand, by volume. The sand sieve analysis revealed very fine sand. 22 ½% passed all of the sieves whereas only 1% was trapped in the largest sieve. Moreover 46 ½% was trapped in the finest sieve.

Mortar/Plaster/Stucco Analysis Test Sheet

Sample No. 45
 Building: Lighthouse, Outer Island, Apostle Islands NL
 Location: Hall plaster
 Sample Description: Warm gray, very soft, fast and fizzy reaction, extremely slow filtering time

Test No. 1 – Soluble Fraction

Data:

- | | |
|--|---|
| 1. <u>187.5</u> Container A weight | 8. <u>No</u> Hair or fiber <u> </u> type |
| 2. <u>212.1</u> Container A and sample | 9. <u>3.4</u> Fines and paper weight |
| 3. <u>763.02</u> Barometric pressure | 10. <u>3.0</u> Filter paper weight |
| 4. <u>23</u> Temperature | 11. <u>207.8</u> Sand and Container A weight |
| 5. <u>0.25</u> Liters of water displaced | 12. <u>12.2</u> cc. of sand |
| 6. <u>Off-white</u> Filtrate color | 13. <u>49.1</u> Weight of graduated cylinder and sand |
| 7. <u>Warm gray</u> Fines color | 14. <u>28.8</u> Weight of graduated cylinder |

Computations:

15.	24.6	Starting weight of sample: No. 2 – No. 1
16.	0.4	Weight of fines: No. 9 – No. 10
17.	20.3	Weight of sand: No. 11 – No. 1
18.	.60	Sand density: No. 12 divided by (No. 13 – No. 14)
19.	3.9	Weight of soluble content: No. 15 – (No. 16 + No. 17)
20.	0.0103	Mols. Of CO ₂ : No. 5 x No. 3. x 0.016 divided by (No. 4 + 273.16 C.)
21.	1.03	Gram weight of CaCO ₃ : 100 x No. 20
22.	2.87	Gram weight of Ca(OH) ₂ : No. 19 – No. 21
23.	0.0387763	Mols. of Ca(OH) ₂ : No. 22 divided by 74
24.	3.63	Gram total weight of Ca(OH) ₂ : 74 x (No. 20 + No. 23)
25.	0.45	Gram weight CO ₂ : No. 20 x 44
26.	2.16	Gram weight total possible CO ₂ : 44 x (No. 20 + No. 23)
27.	20.83	%CO ₂ gain: No. 25 divided by No. 26

Conclusions:

28.	24.15	Gram weight of sample:	No. 15 – No. 25
29.	1.66	Fine parts/volume:	No. 16 divided by No. 28
30.	50.43	Sand parts/volume:	(No. 17 divided by No. 28) x No. 18
31.	16.53	Lime parts/volume:	(No. 24 divided by No. 28) x 1.1

Cement (if present)

32.		Portland cement parts/volume:	(No. 16 divided by No. 28) x 0.78
33.		Natural cement parts/volume:	(No. 16 divided by No. 28) x 0.86
34.		Lime with cement parts/volume:	(No. 16 x 0.2) divided by No. 28 x 1.1

Test No. 2 – Sand Sieve Analysis

Sieve	Sieve w/ sand weight	Sieve weight	Sand weight	Sand ratio
No. 10	107.0	106.8	0.2	1.0
No. 20	107.2	106.4	0.8	4.0
No. 30	100.6	99.3	1.3	6.5
No. 40	104.7	100.8	3.9	19.5
No. 50	102.5	93.2	9.3	46.5
Base	75.7	71.2	4.5	22.5

Lighthouse

Sample 46	Munsell
Dark gray	N 4.5/
Gray	5Y 5/1
Dark gray	N 4.5/
Gray	5Y 5/1
Light gray	N 7.5/
Gray	N 5.0/
Gray	N 5.0/
Charcoal	5Y 3/1
Tan	7.5YR 7/2
Gray	N 6.5/
Gray	N 6.5/
Dark gray	5Y 4/1
Light gray	5Y 8/1

1	Dark gray	5Y 4/1
2	Dark green	5G 4/4
3	Whitewash	N 9.5/

Sample 46 resumed the paint analysis. The sample was from the basement stair wall of the lighthouse. It was excellent in its quality. Beneath a very large number of paint layers was a thick accumulation of whitewash layers of which at least six layers were visible.

10	Lighthouse	
11	Sample 47	Munsell
12	White	N 9.5/
13	Whitewash	N 9.5/

Sample 47 was found on the basement wall of the lighthouse. Beneath a layer of white paint was a very thick set of whitewash layers which were virtually indistinguishable from each other.

19	Lighthouse	
20	Sample 48	Munsell
21	Pastel blue-green	5G 9/1
22	Dark green	5G 3/4
23	Gray	5Y 7/1
24	Pastel peach	5YR 9/2
25	Pastel peach	5YR 9/2
26	Light peach	7.5YR 8/3
27	Pastel peach	5YR 9/2
28	Light peach	7.5YR 8/3
29	Off-white	5Y 8.5/1
30	Gray	5Y 5/1
31	Green	10GY 7.5/4
32	Pale green	2.5G 9/3

Sample 48 was collected from the wall of bedroom 3 of the second floor of the lighthouse. Its quality was excellent. The oldest pale green layer may have served as a prime coat for a finish coat of green.

38	Lighthouse	
39	Sample 49	Munsell
40	Blue-green	5BG 5,5/2
41	White	N 9.5/
42	Tan	7.5YR 7/2
43	Light green	10G 7/2
44	Light green	10G 7/2
45	Light green	10G 7/2
46	Dark green	10G 3/4

Sample 49 came from the wall of the closet of bedroom 3 on the second floor of the lighthouse. It retained a relatively large number of paint layers considering its location with dark green being the oldest observed layer on its white plaster substrate.

Lighthouse**Sample 50****Munsell**

White

5Y 9/1

Sample 50 was removed from the trim of bedroom 4 of the second floor of the lighthouse. It retained a single layer of dirty white paint on its wood substrate.

Lighthouse**Sample 51****Munsell**

Light blue-green

5BG 8/1

White

N 9.5/

Tan

7.5YR 7/3

Tan

7.5YR 7/3

Tan

7.5YR 7/3

Light green

10G 7/2

Light green

10G 7/2

Gray

10YR 7/1

Gray

5Y 7/1

Dark gray

5Y 3/1

Dark green

10G 3/4

Sample 51 was from the wall of the closet of bedroom 4 of the second floor of the lighthouse. Like its counterpart, sample 49, it revealed a surprisingly large number of paint layers in light of its location. The oldest apparent finish layer was dark green.

Lighthouse**Sample 52****Munsell**

Light green

7.5GY 7.5/2

White

N 9.5/

Warm gray

5Y 7/2

Warm gray

5Y 7/2

Warm gray

5Y 7/2

Warm gray

5Y 7/2

Tan

10YR 8/5

Tan

10YR 8/2

Tan

10YR 8/2

Tan

10YR 8/2

Tan

10YR 8/2

Tan

10YR 8/2

Tan

10YR 8/2

Tan

10YR 8/2

Blue-green

5BG 6/1

Blue-green

5BG 6/1

Light blue-green

5BG 8/1

Dark green

10G 3/4

Sample 52 was found on the wall between bedrooms 1 and 2 on the second floor of the lighthouse. The white and warm gray layers were quite thick and filled with microbubbles, which is typical of some early forms of latex paint. The oldest dark green layer was firmly adhered to its plaster substrate.

Lighthouse

Sample 53	Munsell
Pastel blue-green	5G 9/1

Sample 53 was collected from the wall of bedroom 1 of the second floor of the lighthouse. It revealed a single layer of pastel blue-green paint on its very brittle paper substrate.

Lighthouse

Sample 54	Munsell
Brown	5YR 6/4
Brown	5YR 6/4
Brown	5YR 6/4
Brown	5YR 6/4
Brown	5YR 6/4
Warm gray	5Y 7/2

Sample 54 came from the wall of the third floor stair of the lighthouse. It was challenging as the paint beneath the four brown layers appeared unevenly with only warm gray as the layer that could be exactly identified.

Lighthouse

Sample 55	Munsell
Brown	5YR 6/4
Brown	5YR 6/4
Brown	5YR 6/4
Brown	5YR 6/4
Brown	5YR 6/4
White	5Y 9/1
White	5Y 9/1
White	5Y 9/1
White	5Y 9/1
Tan	10YR 8/3
Blue-green	5BG 6.5/1
Blue-green	5BG 6.5/1
Dark gray	5Y 4/1
Blue-green	5BG 6.5/1
Blue-green	5BG 6.5/1
Blue-green	5BG 6.5/1
Blue-green	5BG 5/1
Blue-green	5BG 6.5/1
Dark blue-green	5BG 4/1

Sample 55 was removed from the trim of the third floor of the lighthouse. It was excellent in its quality. Beneath the same five layers of brown paint seen in the previous sample was a large array of additional paint layers with dark blue-green as the oldest observed color.

A number of conclusions can be drawn from the analysis, as follow:

1. There was a relatively high degree of consistency between the samples so that comparisons could easily be made between the samples.
 2. A number of samples had so few layers that one of the following conclusions can be reached:
 - a. The oldest layers had either weathered away over time, which is probable with exterior paint.
 - b. They may have been stripped.
 - c. The element itself had been replaced or is of recent date.
 - d. Other coverings such as wallpaper may have preceded the paint and were removed prior to painting. Wallpaper was a popular covering, especially for damaged plaster.
 3. There is no doubt that several of the buildings had various elements which were whitewashed as their probable original finish.
 4. Many of the samples revealed lengthy sequences of layers so that positive conclusions can be reached for those samples and other samples can be evaluated in relation to them
 5. When it is states “sample detached from substrate” (sample #15 for example) there is not necessarily an implication that can be directly drawn. It simply means that there was no substrate or indication of a substrate beneath the oldest layer. There may be any number of reasons for this, as follow:
 - a. The substrate may have been hard and impervious such as metal or stone so that it was impossible to remove the substrate with the sample.
 - b. There may have been a natural cleavage between the substrate and the oldest finish layer. This is typical found when linseed oil was used as a prime coat on wood or when calcimine paint remains on the surface of plaster.
 - c. There may have been cleavage between layers so that only those layers above that cleavage survived the sampling process.

It does mean that it is impossible to identify a prime coat so that one is left to speculate as to the relative age of the oldest layer. It also means that older finish layers may have been left behind in the sampling process.
 6. As can be seen with many of the mortar sample discussions no relative ratios of sand to Portland cement or sand to Portland cement and lime has been stated. The acid reduction method which was used is better than other methods for determining lime to sand ratios. Hence, they were provided for those samples composed of sand and lime. For samples containing Portland cement, the best this form of testing can do is to indicate the presence of Portland cement and the sand itself.
- The primary goal in repointing is to achieve a compatible mortar. This can be done for lime and sand samples that were analyzed. It can also be done for Portland cement samples with a bit of trial and error. If the mortar is very hard then a higher ratio of Portland cement to sand will work. One must take into consideration any deterioration of the masonry as a result of the mortar. If this has been the case it may be advisable to use a softer mortar for repointing.

1 The other primary mode of mortar analysis is spectrographic testing. Unfortunately, it also cannot
2 accurately determine exact ratios of Portland cement to sand and/or to lime.

3
4 The secondary goal is to match the appearance of the mortar, which depends to a very large extent
5 on the sand. This is where acid reduction testing shines. It provides an exact calculation of the
6 sand grain sizes as well as a sample of the sand for matching of color. If the sand is carefully
7 matched then the appearance will be successful. This is especially critical in partial repointing and
8 patching.

- 9
10 7. There are instances where the narrative of the mortar make up refers to Portland – but the data
11 sheet following does not include it in line #32. The reason for this is that rather than a number for
12 lime content, the calculation is made for lime with Portland cement content. If the sample merely
13 had Portland cement and sand there would be a number for Portland cement
14



As the nation's principal conservation agency, the Department of the Interior has the responsibility for most of our nationally owned public lands and natural resources. This includes fostering sound use of our land and water resources; protecting our fish, wildlife, and biological diversity; preserving the environmental and cultural values of our national parks and historical places; and providing for the enjoyment of life through outdoor recreation. The department assesses our energy and mineral resources and works to ensure that their development is in the best interests of all our people by encouraging stewardship and citizen participation in their care. The department also has a major responsibility for American Indian reservation communities and for people who live in island territories under U.S. administration.

NPS D-633/106,232 / March 2011