

BENITO JUAREZ MONUMENT Sieve Analysis

Washington, D.C.

L. Brad Shotwell Associate Principal

Final Report March 1, 2010 WJE No. 2009.5347

Prepared for: Oehrlein and Associates Architects 1350 Connecticut Avenue, NW, Suite 412 Washington, DC 20036-1701

Prepared by: Wiss, Janney, Elstner Associates, Inc. 9655 Sweet Valley Drive, Suite 3 Cleveland, OH 44125-4262 216.642.2300 tel | 216.642.6288 fax



BENITO JUAREZ MONUMENT Sieve Analysis

Washington, D.C.

INTRODUCTION

At the request of Mr. Martin Howell, AIA, of Oehrlein and Associates, Washington, D.C., the approximate aggregate gradation for sand contained in a sample of hardened mortar was determined. The mortar contained a dark gray to black pigment. The mortar had been used to set stone at the Benito Juarez Monument. Previously, compositional studies of the mortar had been conducted¹.

STUDIES

Figure 1 shows the distribution of sand particles in the thin section that was used for the petrographic studies. The angular nature of the sand particles and the uniform distribution throughout the mortar is apparent.

Petrographic studies conducted previously indicated that the sand contained in the mortar was siliceous and would not be expected to dissolve in dilute hydrochloric acid. Representative fragments of the mortar were immersed in dilute acid in order to remove the cementitious matrix that encased the sand particles. The acid-insoluble fraction of the sample was then sieved into various size fractions. Representative portions of the various fractions of the aggregate are pictured in Figures 2 through 6. The resultsof the sieve analysis are given in Table 1.

Soft gray particles were occasionally detected in the various sand fractions (Figures 2 through 5). Closer inspection of these particles contained in each of the sieve fractions revealed that they were composed primarily of remnants of the cementitious matrix that had not dissolved during the acid-dissolution procedure. Occasionally, these soft particles were seen to contain smaller siliceous sand particles surrounded by the soft gray material (Figure 3).

The pan fraction of the sample was composed of a combination of small angular siliceous particles and even finer sized black opaque material that represents the mortar pigment (Figure 6).

¹ WJE report 2009.5347 Benito Juarez Monument, Petrographic and Chemical Studies of Mortar, January 22, 2010.



SUMMARY AND DISCUSSION

Some of the cementitious matrix of the pigmented mortar was not completely dissolved during the acidtreatment. The cause for this incomplete dissolution was not determined by the studies.

The presence of these soft particles has skewed the resulting sieve analysis making the results appear somewhat more "coarse" for fractions of sand retained on the 30, 50, 100 and 200 mesh screens. However, this amount of deviation from the actual gradation was judged to be minimal.

Although a small amount of angular siliceous particles was detected in the pan fraction of the sand, the bulk of material retained on this screen is likely composed of the insoluble remnants of pigment contained in the mortar.

If the pan fraction of the sand is eliminated from the calculations and the results for the remaining fractions are normalized, the resulting "calculated" sieve analysis may more nearly represent the original gradation of the sand.

Storage: Thirty days after completion of our studies, samples will be discarded unless the client submits a written request for their return. Shipping and handling fees will be assessed for any samples returned to the client. Any hazardous materials that may have been submitted for study will be returned to the client and shipping and handling fees will apply. The client may request that WJE retain samples in storage in our warehouse. In that case, a yearly storage fee will apply.



Sieve Size	Individual Weight Retained	Individual % Retained	Cumulative % Retained	Cumulative % Passing
3/8 in.		0.0	0.0	100.0
No. 4		0.0	0.0	100.0
No. 8		0.0	0.0	100.0
No. 16		0.0	0.0	100.0
No. 30	0.64	6.7	6.7	93.3
No. 50	3.53	37.0	43.7	56.3
No. 100	2.83	29.6	73.3	26.7
No. 200	0.68	7.1	80.4	19.6
Pan	1.87	19.6	-	-
		Fineness Modulus	1.24	

Table 1. Sieve Analysis for Particles That Remained after Acid Digestion of Mortar



Benito Juarez Monument Sieve Analysis March 1, 2010 Page 4

Appendix. Appearance of the Sand Fraction Samples




Figure 1. A close-up of the thin section used for the petrographic studies is pictured. The distribution of the sand in the gray mortar is shown in the area outlined by the box. The width of the field of view is 1.26 inch (32 mm).






Figure 2. A close-up of the +30 mesh fraction is pictured. The yellow arrow marks one of the many soft gray particles contained in this fraction. The red arrow marks a siliceous sand particle that is still partially coated with mortar matrix. The width of the field of view is 0.5 inch (12.7mm).





Figure 3. A close-up of the +50 mesh fraction is pictured. The yellow arrow marks one of the many soft gray particles contained in this fraction. This particle when touched with a needle probe was easily broken and found to contain smaller sand particles that would have passed the 50 mesh screen. The width of the field of view is 0.25 inch.






Figure 4. A close-up of the +100 mesh fraction is pictured. The yellow arrow marks one of the many soft gray particles contained in this fraction. Some of these gray particles, when touched with a needle probe, were easily broken and found to contain smaller sand particles that might have passed the 100 mesh screen. The width of the field of view is 0.25 inch.






Figure 5. A close-up of the +200 mesh fraction is pictured. The photo was taken using reflected light. Most of the particles are composed of clean angular siliceous sand fragments and are generally free of coatings. However, a few medium gray soft particles are present too. Two particles tentatively identified as graphite are marked with arrows. Graphite could have been introduced with the pigment used in the mortar. The width of the field of view is 0.25 inch.






Figure 6. A close-up of the pan fraction is pictured. The photo was taken using reflected light. An estimated 80% of the particles are composed of friable soft remnants of matrix or pigment. These matrix particles generally did not contain smaller sand particles. Angular white quartz and feldspar fragments are also visible. The width of the field of view is 0.156 inch.

APPENDIX F – COST ESTIMATE

Benito Pablo Jaurez Monument & Plaza Investigative Condition Assessment and Report

Prepared for: Oehrlein & Associates Architects 1350 Connecticut Avenue, NW Suite 412 Washington, DC 20036-1701 202-785-7336 Fax 202-785-7334

March 2, 2010

Prepared by: **R.W. Brown & Associates** 404 Pine Street, S.E., Suite 202 Vienna, Virginia 22180-4871 703-255-2580 Fax 703-255-4927

Project: Benito Pablo Jaurez Monument & Plaza - Investigative Condition Assessme	ent & Re	Page 1
Architect: Oehrlein & Associates Architects	R	WB Job # 09-88-B
Estimated by: R.W. Brown & Associates		3/2/10

Project: Benito Pablo Jaurez Monument & Plaza

Park: National Mall & Memorial Parks, Washington, D.C.

PMIS: 43681

Basis of Estimate

Date of Estimate:

03/02/10

Estimated By:

R.W. Brown & Associates 404 Pine Street, S.E., Suite 202 Vienna, Virginia 22180-4871 703-255-2580 Fax 703-255-4927

Supporting Material:

100% Draft Submission Report dated January 25, 2010.

Cost Data:

Priced Quantities w/In place unit costs

Unit prices based on Baltimore/Washington D.C. market experiences

Mark-ups and Add-ons:

Published Location Factor: Actual local experience - factors are not applicable.

Project Remoteness: Site is within the local market labor source.

Federal Wage Rate Factor: Included in unit costs.

Design Contingency: 15% based on development of the supporting data.

Taxes: 6% Sales Tax included in Unit Costs

Standard General Conditions: Within Normal Range: 15%.

Government General Conditions: 10%.

Bonds and Permits: 1.5% bond included in General Conditions. No permit costs.

Historic Preservation Factor: Used 10% in markups on recap.

Overhead: 10%

Profit: 10 %

Contracting Method Adjustment: An allowance of 10% for 8A is added to the total cost. **Inflaton Escalation:** Assume start of construction to be Spring 2011. Escalation

to mid-point of construction is calculated @ 4.5% p.a.

Comments:

"Other Costs" are common to all options.

Project: Benito Pablo Jaurez Monument & Plaza - Investigative Condition Assessm	ent	Page 2
Architect: Oehrlein & Associates Architects		RWB Job # 09-88-B
Estimated by: R.W. Brown & Associates		3/2/10

Project Recapitulation

Page	Item	Cost Per Option	Recommended Cost
3	Granite Option #1	47,280	
4	Granite Option #2	147,691	
5	Granite Option #3	166,391	166,391
6	Bronze Option #1	28,696	28,696
7	Bronze Option #2	34,082	
8	Waterproofing Option #1	862	
9	Waterproofing Option #2	10,811	
10	Waterproofing Option #3	11,914	11,914
11	Other Costs	39,425	39,425

Total Project Cost

\$246,426

Project: Benito Pablo Jaurez Monument & Plaza - In	vestigative Condition Assessment 8	Report	Page 3
Architect: Oehrlein & Associates Architects		RWB Job #	09-88-B
Estimated by: R.W. Brown & Associates	Granite Option #1		3/2/10

Granite Option #1

		** *	Unit	Total	
Item	Quantity	Unit	Price	Cost	
STONE WORK		~ -			
REMOVE GRANITE @ BASE	120		8.00	960	
REMOVE PAVERS WHERE PONDING	150		5.50	825	
CONCRETE LEVELING	150		10.00	1,500	
SETTING BED	150		4.50	675	
RESET PAVERS	150		30.00	4,500	
PREP/RESET BASE GRANITE	120	SF	18.00	2,160	
RAKE & POINT MONUMENT MORTAR JOINT	330		6.00	1,980	
CAULK & BACKER ROD - PLAZA PAVING	680	LF	4.50	3,060	
NEW WEEPS	24	EA	36.00	864	
REMOVE/RESET CURB STONES	83	LF	10.00	830	
CLEAN GRANITE	1,148	SF	4.00	4,592	
Subtotal Direct Construction Costs				\$21,946	
Published Location Factor	Included	in Unit	t Costs	-	
Remoteness Factor @		NA		-	
Federal Wage Rate Factor	Included	in Unit	t Costs	-	
Design Contingency @		15%		\$3,292	
Total Direct Construction Costs				\$25,238	
Standard General Conditions @		15%		\$3,786	
Government General Conditions @		10%		\$2,524	
Historic Preservation Factor		10%		\$2,524	
Subtotal NET Construction Cost				\$34,071	
General Contractor's Overhead @		10%		\$3,407	
General Contractor's Profit @		10%		\$3,407	
Estimated NET Construction Cost				\$40,885	
Contracting Method Adjustment (8A)		10%		\$4,089	
Inflation Escalation to Spring 2011		5.64%		\$2,306	
Total Estimated NET Cost of C	onstruction			\$47,280	

\$10,643

\$10,643

\$12,772

\$7,203

\$127,716

\$147,691

Project: Benito Pablo Jaurez Monument & Plaza - Investigative Condition Assessment & Report Page			
Architect: Oehrlein & Associates Architects		RWB Job #	09-88-B
Estimated by: R.W. Brown & Associates	Granite Option #2		3/2/10

Granite Option #2

General Contractor's Overhead @

Estimated NET Construction Cost

Inflation Escalation to Spring 2011

Contracting Method Adjustment (8A)

Total Estimated NET Cost of Construction

General Contractor's Profit @

			Unit	Total	
Item	Quantity	Unit	Price	Cost	
STONE WORK					
REMOVE GRANITE @ BASE	328	~-	8.00	2,624	
REMOVE PAVERS	820		5.50	4,510	
CONCRETE LEVELING	820		10.00	8,200	
MEMBRANE WATERPROOFING	820	SF	7.00	5,740	
SETTING BED	820	SF	4.50	3,690	
RESET PAVERS	820	SF	30.00	24,600	
PREP/RESET BASE GRANITE	328	SF	18.00	5,904	
RAKE & POINT MONUMENT MORTAR JOINTS	390	LF	6.00	2,340	
CAULK & BACKER ROD - PLAZA PAVING	680	LF	4.50	3,060	
NEW WEEPS	24	EA	36.00	864	
REPLACE METAL CRAMPS	8	EA	50.00	400	
REPAIR CRACKS IN GRANITE	3	EA	400.00	1,200	
REMOVE/RESET CURB STONES	83	LF	10.00	830	
CLEAN GRANITE	1,148	SF	4.00	4,592	
Subtotal Direct Construction Costs				\$68,554	
Published Location Factor	Include	d in Unit	Costs	-	
Remoteness Factor @		NA		-	
Federal Wage Rate Factor	Include	d in Unit	Costs	-	
Design Contingency @		15%		\$10,283	
Total Direct Construction Costs				\$78,837	
Standard General Conditions @		15%		\$11,826	
Government General Conditions @		10%		\$7,884	
Historic Preservation Factor		10%		\$7,884	
Subtotal NET Construction Cost				\$106,430	

10%

10%

10%

5.64%

Project: Benito Pablo Jaurez Monument & Plaza - In	vestigative Condition Assessment &	Report	Page 5
Architect: Oehrlein & Associates Architects	· · · · · · · · · · · · · · · · · · ·		09-88-B
Estimated by: R.W. Brown & Associates	Granite Option #3		3/2/10

Granite Option #3

			Unit	Total	
Item	Quantity	Unit	Price	Cost	
STONE WORK					
REMOVE GRANITE @ BASE	328	SF	8.00	2,624	
REMOVE PAVERS	820	SF	5.50	4,510	
CONCRETE LEVELING	820	SF	10.00	8,200	
MEMBRANE WATERPROOFING	820	SF	7.00	5,740	
SETTING BED	820	SF	4.50	3,690	
RESET PAVERS	820	SF	30.00	24,600	
PREP/RESET BASE GRANITE	328	SF	18.00	5,904	
RAKE & POINT MONUMENT MORTAR JOINTS	970	LF	6.00	5,820	
CAULK & BACKER ROD - PLAZA PAVING	680	LF	4.50	3,060	
NEW WEEPS	24	EA	36.00	864	
REPLACE METAL CRAMPS	8	EA	50.00	400	
REPAIR CRACKS IN GRANITE	6	EA	400.00	2,400	
REPAIR SPALL IN GRANITE	8	EA	500.00	4,000	
REMOVE/RESET CURB STONES	83	LF	10.00	830	
CLEAN GRANITE	1,148	SF	4.00	4,592	
Subtotal Direct Construction Costs				\$77,234	
Published Location Factor	Included	d in Unit	Costs	-	
Remoteness Factor @		NA		-	
Federal Wage Rate Factor	Included	d in Unit	Costs	-	
Design Contingency @		15%		\$11,585	
Total Direct Construction Costs				\$88,819	
Standard General Conditions @		15%		\$13,323	
Government General Conditions @		10%		\$8,882	
Historic Preservation Factor		10%		\$8,882	
Subtotal NET Construction Cost				\$119,906	
General Contractor's Overhead @		10%		\$11,991	
General Contractor's Profit @		10%		\$11,991	
Estimated NET Construction Cost				\$143,887	
Contracting Method Adjustment (8A)		10%		\$14,389	
Inflation Escalation to Spring 2011		5.64%		\$8,115	
Total Estimated NET Cost of Co	onstruction			\$166,391	

Project: Benito Pablo Jaurez Monument & Plaza - In	vestigative Condition Assessment &	Report	Page 6
Architect: Oehrlein & Associates Architects		RWB Job #	09-88-B
Estimated by: R.W. Brown & Associates	Bronze Option #1		3/2/10

Bronze Option #1

			Unit	Total	
Item	Quantity	Unit	Price	Cost	
BRONZE WORK					
REPAIR MAJOR CRACKS IN BRONZE	1	LS	2,500.00	2,500	
FILL HOLES IN BRONZE SURFACE	1	LS	2,000.00	2,000	
REMOVE FERROUS PINS/FILL	1	LS	500.00	500	
CLEAN & WAX BRONZE SURFACE	200	SF	30.00	6,000	
LIFTING EQUIPMENT	1	LS	2,000.00	2,000	
REPAIR LETTER ANCHORAGE	8	EA	40.00	320	
Subtotal Direct Construction Costs				\$13,320	
Published Location Factor	Include	d in Unit	Costs	-	
Remoteness Factor @	NA		-		
Federal Wage Rate Factor	Include	d in Unit	Costs	-	
Design Contingency @		15%		\$1,998	
Total Direct Construction Costs				\$15,318	
Standard General Conditions @		15%		\$2,298	
Government General Conditions @		10%		\$1,532	
Historic Preservation Factor		10%		\$1,532	
Subtotal NET Construction Cost				\$20,679	
General Contractor's Overhead @		10%		\$2,068	
General Contractor's Profit @		10%		\$2,068	
Estimated NET Construction Cost				\$24,815	
Contracting Method Adjustment (8A)		10%		\$2,482	
Inflation Escalation to Spring 2011		5.64%		\$1,400	
Total Estimated NET Cost of C	onstruction			\$28,696	

Project: Benito Pablo Jaurez Monument & Plaza - Ir	nvestigative Condition Assessment &	Report	Page 7
Architect: Oehrlein & Associates Architects RWB Job # 0			09-88-B
Estimated by: R.W. Brown & Associates	Bronze Option #2		3/2/10

Bronze Option #2

			Unit	Total	
Item	Quantity	Unit	Price	Cost	
BRONZE WORK					
REPAIR CRACKS IN BRONZE - COMPLETE	1	LS	4,000.00	4,000	
FILL HOLES IN BRONZE SURFACE	1	LS	3,000.00	3,000	
REMOVE FERROUS PINS/FILL	1	LS	500.00	500	
CLEAN & WAX BRONZE SURFACE	200	SF	30.00	6,000	
LIFTING EQUIPMENT	1	LS	2,000.00	2,000	
REPAIR LETTER ANCHORAGE	8	EA	40.00	320	
Subtotal Direct Construction Costs				\$15,820	
Published Location Factor	Include	d in Unit	Costs	-	
Remoteness Factor @	NA			-	
Federal Wage Rate Factor	Included in Unit Costs		-		
Design Contingency @		15%		\$2,373	
Total Direct Construction Costs				\$18,193	
Standard General Conditions @		15%		\$2,729	
Government General Conditions @		10%		\$1,819	
Historic Preservation Factor		10%		\$1,819	
Subtotal NET Construction Cost				\$24,561	
General Contractor's Overhead @		10%		\$2,456	
General Contractor's Profit @	10%			\$2,456	
Estimated NET Construction Cost				\$29,473	
Contracting Method Adjustment (8A)		10%		\$2,947	
Inflation Escalation to Spring 2011		5.64%		\$1,662	
Total Estimated NET Cost of C	onstruction			\$34,082	

Project: Benito Pablo Jaurez Monument & Plaza - Ir	nvestigative Co	ondition As	ssessment & F	Report	Page 8
Architect: Oehrlein & Associates Architects	-			RWB Job #	09-88-B
Estimated by: R.W. Brown & Associates	١	Naterproc	ofing Option	#1	3/2/10
Waterproofing Option #1					
Item	Quantity	Unit	Unit Price	Total Cost	
WATERPROOFING	Quantity	Cint	Thee	Cost	
REPLACE METAL FLASHING IN PLACE	10	6 SF	25.00	400	
Subtotal Direct Construction Costs				\$400	
Published Location Factor	Includ	led in Unit	Costs	-	
Remoteness Factor @		NA		-	
Federal Wage Rate Factor	Included in Unit Costs			-	
Design Contingency @	15%			\$60	
Total Direct Construction Costs				\$460	
Standard General Conditions @		15%		\$69	
Government General Conditions @		10%		\$46	
Historic Preservation Factor		10%		\$46	
Subtotal NET Construction Cost				\$621	
General Contractor's Overhead @		10%		\$62	
General Contractor's Profit @		10%		\$62	
Estimated NET Construction Cost				\$745	
Contracting Method Adjustment (8A) Inflation Escalation to Spring 2011		10% 5.64%		\$75 \$42	
Total Estimated NET Cost of C	Constructio	n		\$862	

٦

Project: Benito Pablo Jaurez Monument & Plaza - Ir	nvestigative Condition Assessment &	Report	Page 9
Architect: Oehrlein & Associates Architects RWB Job #		09-88-B	
Estimated by: R.W. Brown & Associates	Waterproofing Option	#2	3/2/10

Waterproofing Option #2

			Unit	Total	
Item	Quantity	Unit	Price	Cost	
WATERPROOFING					
DISCONNECT ANCHORAGE/LIFT STATUE	1	LS	2,500.00	2,500	
MEMBRANE WATERPROOFING	16	SF	15.00	240	
SEAT & CAULK REGLET	16	LF	8.00	128	
NEOPRENE GASKET	10	LF	15.00	150	
RESET STATUE	1	LS	2,000.00	2,000	
Subtotal Direct Construction Costs				\$5,018	
Published Location Factor	Include	d in Unit	Costs	-	
Remoteness Factor @	NA			-	
Federal Wage Rate Factor	Included in Unit Costs			-	
Design Contingency @		15%		\$753	
Total Direct Construction Costs				\$5,771	
Standard General Conditions @		15%		\$866	
Government General Conditions @	10%			\$577	
Historic Preservation Factor	10%			\$577	
Subtotal NET Construction Cost				\$7,790	
General Contractor's Overhead @	10%			\$779	
General Contractor's Profit @	10%		\$779		
Estimated NET Construction Cost				\$9,349	
Contracting Method Adjustment (8A)		10%		\$935	
Inflation Escalation to Spring 2011		5.64%		\$527	
Total Estimated NET Cost of (Construction			\$10,811	

Project: Benito Pablo Jaurez Monument & Plaza - Investigative Condition Assessment & Report			
Architect: Oehrlein & Associates Architects	Irlein & Associates Architects RWB Job # 0		09-88-B
Estimated by: R.W. Brown & Associates	Waterproofing Option	#3	3/2/10

Waterproofing Option #3

			Unit	Total	
Item	Quantity	Unit	Price	Cost	
WATERPROOFING					
DISCONNECT ANCHORAGE/LIFT STATUE	1	LS	2,500.00	2,500	
MEMBRANE WATERPROOFING	16	SF	15.00	240	
METAL FLASHING	16	SF	30.00	480	
SEAT & CAULK REGLET	16	LF	10.00	160	
NEOPRENE GASKET	10	LF	15.00	150	
RESET STATUE	1	LS	2,000.00	2,000	
Subtotal Direct Construction Costs				\$5,530	
Published Location Factor	Include	d in Unit	Costs	-	
Remoteness Factor @	NA			-	
Federal Wage Rate Factor	Included in Unit Costs		-		
Design Contingency @	15%		\$830		
Total Direct Construction Costs				\$6,360	
Standard General Conditions @		15%		\$954	
Government General Conditions @		10%		\$636	
Historic Preservation Factor		10%		\$636	
Subtotal NET Construction Cost				\$8,585	
General Contractor's Overhead @		10%		\$859	
General Contractor's Profit @	10%			\$859	
Estimated NET Construction Cost				\$10,302	
Contracting Method Adjustment (8A)		10%		\$1,030	
Inflation Escalation to Spring 2011		5.64%		\$581	
Total Estimated NET Cost of C	construction			\$11,914	

1

Project: Benito Pablo Jaurez Monument & Plaza - Inv	vestigative Condition Assessment &	Report	Page 11
Architect: Oehrlein & Associates Architects RWB Job #		09-88-B	
Estimated by: R.W. Brown & Associates	Other Costs		3/2/10

Other Costs

			Unit	Total	
Item	Quantity	Unit	Price	Cost	
LANDSCAPE RESTORATION					
REMOVE SHRUBS - ALLOW	20	EA	40.00	800	
SOD	350	SY	12.00	4,200	
TREES	2	EA	900.00	1,800	
SHRUBS	20	EA	150.00	3,000	
PRUNE EXISTING TREES	1	LS	2,500.00	2,500	
OTHER COSTS					
MISCELLANEOUS PATCH & REPAIR OF					
CONCRETE APPROACHES - ALLOW	1	LS	2,000.00	2,000	
PERMITS & FEES	1	LS	4,000.00	4,000	
Subtotal Direct Construction Costs				\$18,300	
Published Location Factor	Included in Unit Costs		-		
Remoteness Factor @	NA		-		
Federal Wage Rate Factor	Included in Unit Costs		-		
Design Contingency @	15%		\$2,745		
Total Direct Construction Costs				\$21,045	
Standard General Conditions @		15%		\$3,157	
Government General Conditions @		10%		\$2,105	
Historic Preservation Factor		10%		\$2,105	
Subtotal NET Construction Cost				\$28,411	
General Contractor's Overhead @		10%		\$2,841	
General Contractor's Profit @	10%		\$2,841		
Estimated NET Construction Cost				\$34,093	
Contracting Method Adjustment (8A)	10%			\$3,409	
Inflation Escalation to Spring 2011		5.64%		\$1,923	
Total Estimated NET Cost of C	onstruction			\$39,425	

APPENDIX G – E-MAIL REGARDING FUNDIDORES ARTISTICOS IN MEXICO CITY

 From:
 Quesnel Melendez, Carlos [cquesnel@sre.gob.mx]

 To:
 Jennifer_Talken-Spaulding@nps.gov; Martin Howell

RE: Assistance with foundry in Mexico City

Dear Jennifer,

I tried to contact you last week to let you know that unfortunately Fundidores Artisticos is out of business. I found a person related to the former owner (Otilia Montano, who is the owner of another foundry), but she does not have any information on the Juarez statue.

I also appreciate Martins' questionnaire. However since FA is no longer in existence we haven't been able to locate anyone in a position to answer these questions.

We know that the author of the statue was Enrique Alciati, and the 2 reproductions of this work were cast in 1969 (the other was given as gift from the government of Mexico to the government of Guatemala). The foundry, Fundidores Artísticos, ceased operations around 1976. The only information we have is that the last name of the owners was Portilla, and that they had a cousin named Francisco Cortina Portilla, whom we have unfortunately not been able to locate.

Last week I spoke over the phone with Mrs. Montano, whose husband had a relationship with Fundidores Artísticos. However, she has no information or background on the sketches or the crafting of these sculptures. However, she told us that most of the sculptures cast there received a black or dark brown finish (Patina), and that she believes the original patina for this sculpture was dark Brown, since it was the most classical one (the statue's present greenish color is the result of exposure to the elements over the years).

I hope this information is useful for you. Please let me know if you need anything else, and I will be glad to be of assistance.

Here's the information of Otilia Montano's foundry, just in case you need it. And please do not hesitate to let me know if you want me to talk to somebody in Spanish.

Taller Otilia Montaño Address: Poniente 108 #96 Colonia Defensores de la República Delegación A. Madero Tel: 55 67 58 08 Fax: 53 68 87 91

Best regards Carlos

Carlos Quesnel-Meléndez Counselor for Legal Affairs Embassy of Mexico Tel. 202.7281688 Fax 202.7281783

Advertencia: el contenido de este correo y archivos adjuntos es confidencial y para el uso exclusivo de su(s) destinatario(s). Si usted ha recibido este correo por error, por favor notifíquelo al remitente y bórrelo de su sistema. Está prohibido el uso, distribución, copia o divulgación por cualquier medio de la información contenida en el mismo por persona distinta al destinatario de este mensaje.

Disclaimer: The content of this email and any of its attachments is confidential and intended solely for the use of its addressee(s). If you have received this email by mistake, please notify the sender immediately and delete it from your system. Disclosing, copying, distributing or taking any action in reliance on the contents of this information by anyone other than the intended recipient(s) is strictly prohibited.