

1 ***Sand Island Light Station Quarters Photographs, 2009***



SI-LSQ-01: North elevation, 2009 (Source: A&A DSC01353)

2
3
4
5
6
7
8
9
10
11
12



SI-LSQ-02: East elevation, 2009 (Source: A&A DSC01342)

1
2
3
4



SI-LSQ-03: South elevation, 2009 (Source: A&A DSC01343)

1
2
3
4



SI-LSQ-04: West elevation, 2009 (Source: A&A DSC01264)



SI-LSQ-05: Roof shingles, view from Tower to south shed roof (Source: A&A IMGP3047)



SI-LSQ-06: Roof finial and trim, north elevation (Source: A&A IMGP3067)



SI-LSQ-07: Trim, wall, and chimney detail, south elevation (Source: A&A IMGP3036)



SI-LSQ-08: Chimney and roof detail, looking south from Tower (Source: A&A IMGP3049)



SI-LSQ-09: Trim and downspout detail, west elevation (Source: A&A IMGP3041)



SI-LSQ-10: Window shutter hardware (Source: A&A 100_9865)



SI-LSQ-11: Entry stairs and downspout, north elevation (Source: A&A DSC01301)



SI-LSQ-12: North entry doors (Source: A&A 100_9866)



SI-LSQ-13: Doors to summer kitchen from kitchen vestibule, west elevation (Source: A&A 100_9863)



SI-LSQ-14: Oil room in basement and Tower stairs, looking northwest (Source: A&A CIMG4327)



SI-LSQ-15: Basement wood cellar, looking southwest (Source: A&A CIMG4299)



SI-LSQ-16: Basement cellar ceiling and remnants of lath and plaster, looking east (Source: A&A CIMG4320)



SI-LSQ-17: Basement stairs to summer kitchen (Source: A&A CIMG4293)



SI-LSQ-18: Summer kitchen, west elevation (Source: A&A CIMG4249)



SI-LSQ-19: Summer kitchen and stairs, east elevation (Source: A&A CIMG4252)



SI-LSQ-20: Summer kitchen built-in pantry and stair to kitchen, north elevation (Source: A&A CIMG4254)



SI-LSQ-21: Kitchen, looking southwest (Source: A&A CIMG4230)



SI-LSQ-22: First floor east bedroom, west elevation (Source: A&A CIMG4222)



SI-LSQ-23: Entry to Tower from entry hall, west elevation (Source: A&A CIMG4213)



SI-LSQ-24: First floor west bedroom and corner closet, north elevation (Source: A&A CIMG4278)



1
2
3

SI-LSQ-25: Second floor stairs to Quarters from Tower stairs (Source: A&A DSC01327)



4
5

SI-LSQ-26: Second floor hall and door, looking west towards Tower stairs (Source: A&A CIMG4347)



SI-LSQ-27: Second floor south bedroom, south elevation (Source: A&A CIMG4364)



SI-LSQ-28: Second floor south bedroom ceiling detail, looking southeast (Source: A&A CIMG4373)



SI-LSQ-29: Tower stairs looking up from second floor access (Source: A&A DSC01335)



SI-LSQ-30: Light Tower window (Source: A&A 100_9834)



1
2
3

SI-LSQ-31: Lantern interior and floor hatch to stairs (Source: A&A 100_9840)



4
5

SI-LSQ-32: Lantern ceiling vent (Source: A&A 100_9839)



SI-LSQ-33: Lantern roof and lightning rod (Source: A&A IMGP3055)



SI-LSQ-34: Lantern trim and glazing detail (Source: A&A IMGP3053)



SI-LSQ-35: Lantern door to walkway with circular imprints (Source: A&A 100_9836)



SI-LSQ-36: Lantern walkway and railing (Source: A&A 100_9835)



SI-LSQ-37: Joist header above window at basement (Source: Martin/Martin)



SI-LSQ-38: Sealed joints in roof (Source: Martin/Martin)



SI-LSQ-39: Cistern opening in summer kitchen floor (Source: Martin/Martin)



SI-LSQ-40: Lightning protection, historic grounding conductor with insulator (Source: RMH)