

## ENTRANCES

Entrances were defined as the visual and spatial connection between the main walkway and the house or business.

The resultant image values are the calculated values as a result to the participants response to “ How appropriate is the Image you are seeing, now and in the future, for Entrances on Fire Island.

### Entrances

Entrance treatment, boardwalk to house with landscaping

+6 (4)



This walkway is also not directly connected to the house but it goes through a series of turns. It floats above the landscape. The house in the background is partially obscured by vegetation.

### Entrances

Entrance treatment, boardwalk to house with landscaping

+7 (3)



This was the top-rated entrance photo. The narrow, elevated boardwalk bends as it approaches the home's entrance.

+6 (4)



This entrance way is composed of a combination of concrete and wood with a gateway defined by two wooden volumes.



## Entrances

Entrance treatment, boardwalk to house with landscaping

**+6 (4)**



This positive image shows a combination of the wooden main walkway with its wood ramp connection to the house. It has a simple 2 by 4 wooden railing. The bike parking area is also in wood.

## Entrances

Entrance treatment, wooden gate, naturalized landscape

**+3 (5)**



This positive image shows a combination of the wooden gate with a metal fence and a loose stone walkway with a natural landscape. Even though this image has a positive value it is controversial due to the (5) standard deviation.

## Entrances

Entrance treatment, wooden posts/handrails with signage

**0 (6)**



This image shows a private entry indicated with wooden post and hand painted signs and a wooden boardwalk. Even though this image has a neutral value of (0) it is controversial due to the (6) standard deviation.

## Entrances

Entrance treatment, boardwalk to house

**-1 (6)**



This image shows a closed poorly maintained private entry walkway of 2x4 and wooden post. This image has a negative value and is controversial due to the (6) standard deviation.



## Entrances

Entrance treatment with exposed waste facilities

-2 (6)



A wooden elevated walkway between a private deck and a wooden boardwalk with exposed propane tanks and waste receptacle adjacent to boardwalk. Even though this image has a negative value due to its standard deviation of (6) it is considered controversial.

## Entrances

Entrance treatment, exposed waste facilities

-3 (6)



This is the lowest rated image in this sub-set that shows a plywood exposed waste storage adjacent to a raised boardwalk. Even though this image has a negative value due to its standard deviation of (5) it is considered controversial.

### 39 How do you feel about current methods of waste disposal and standards governing waste disposal throughout the Island (ie; exposed garbage cans, daily pick-up, etc.)?

1	Exposed garbage cans don't bother me, we don't need tighter standards.	7.7%	34
2	Exposed garbage cans don't bother me, as long as they are protected from wildlife and scavengers.	37.9%	167
3	There should be standards so that all garbage cans and utility facilities are screened from the boardwalk and protected from wildlife.	52.6%	232
		98.2%	433

Waste Disposal Standards

