

Appendix V: Photographs

Planning team discussing alternatives near Totten's Battery



Existing overlook and wayside near the trail head at the beginning of Tour Stop 7



Existing cannon near the trail head at the beginning of Tour Stop 7



Existing timber used to control runoff limits access



Existing drainage pipe running under trail limits access



Wash out of materials on existing trail



Existing water pipe under trail causes sudden grade change



Existing uneven distribution of trail materials and vegetative growth on path



Existing trail to Lyon marker across the glade



Existing view of Lyon marker



Existing uneven slope on glade near Lyon marker



Existing trail looking south from sinkhole towards cabin overlook



Existing bench on Bloody Hill Trail towards the southern end of project area



Existing view of sinkhole on Bloody Hill Trail



Existing view from Totten's Battery looking east



Existing view from Totten's Battery looking south-southwest



Existing view from Totten's Battery looking south



Existing view from Totten's Battery looking south-southeast



Existing view from Totten's Battery looking southeast



Existing view from Totten's Battery looking south-southeast



Existing view from trail near junction with glade/sinkhole loop looking north



Existing view from trail near junction with glade/sinkhole loop looking north



Existing view from trail south of Lyon marker looking north



Existing view from trail south of Lyon marker looking south



Existing view from trail south of Lyon marker near an existing bench



Existing view from south end of project area looking south towards the Edward's cabin

