



Site ID MONO-6 WET-1 Potential Restoration Area 2.19 (Acres) Date of Field Assessment 4/6/2016 Existing Land Use Old field Old field, stream, residential, Adjacent Land Use road Distance to Nearest Road 100 RTE Species Present? No Known Cultural Concern? No Stream Restoration Yes Opportunity? Site Currently Wetland? Yes Site Formerly Wetland? No Evidence of Disturbance No Soils Score 8 8 Hydrology Score Existing Vegetation Score 6 Geomorphic Score 9 Surrounding Land Use Score 6 Function and Value Score Presence of Invasive Species 5 Score Site Disturbance Score 3 Ease of Access Score Stormwater Influence Score 8 Total Score 69 Invasive Species Control? No Native Plantings? Yes Yes Restore Hydrology? Increase Diversity? Yes Convert Open Water to No Vegetated? Convert Emergent to Yes Shrub/Forested Increase Asthetic or Yes Educational Value Other No Wetland area recently planted with trees hydrology exists along west side. Ground water likely,

is likely from runoff and groundwater small channel exists along west side. Ground water likely, surface water runoff from surrounding field. Grass and recently planted trees. Adjacent to stream, surrounding topography slopes to wet area. Disconnected from stream due to erosion. Road bisects wetland. Wetland area adjacent to road has standing water and small channel flowing to stream

Notes

 Site ID
 MONO 6

 Potential Restoration (linear feet)
 1750

 Date
 4/6/2016

Existing Land Use Old field

Residential, old field, park

property

Distance to Nearest Road 10 ft

Adjacent Land Use

Stream Hydrology Perennial

RTE Species Present? No Known Cultural Concern? No Wetland Restoration Opportunity? Yes Existing Wetlands Present Yes Evidence of Disturbance No Can Restoration be Completed in NPS Yes Area? Estimated Bank Erosion Score 6 Degree of Channel Incision Score 3

Existing Floodplain Access Score 4
Opportunity for Floodplain Development 9

<u>Score</u>

<u>Threat of Impact to Resources Score</u> 3

 Surrounding Vegetation Score
 8

 Land Use Score
 6

 Opportunity for Ecological Lift Score
 8

 Ease of Access
 8

 Surrounding Land Use Score
 8

Total Score 63
Invasives Species Control? No

 Riparian Buffer Enhancement?
 Yes

 Restore Natural Hydrology?
 Yes

 Livestock Agricultural Exclusion
 No

 Fish Passage?
 Yes

<u>Channel Restoration?</u> Yes

Increase Aesthetic or Educational Value? Yes


<u>Other</u> No


Notes

Paved road crosses stram channel, concrete culvert carries stream under road, channel is much more seriously eroded after culvert. Open field on either side of channel with minimal invasive species. Mild to moderate erosion in upper reach, erosion is more severe in lower reaches. Banks are soft soil. Topography of surrounding land slopes down to the channel. Some small vegetated beaches exist adjacent to channel. Area consists of mostly grasses with some trees along bank. Reccommendations include: old field habitat creation, channel stabilization, fish


passage, and reduction of sedimentation.





















CHOH-01 Site ID Potential Restoration Area 0.05 (Acres) Date of Field Assessment 4/27/16 Existing Land Use Forested Park land Stormwater management; Adjacent Land Use mowed maintained turfgrass; Mcmansions; forest Distance to Nearest Road .5 mile RTE Species Present? No Known Cultural Concern? No Stream Restoration Yes Opportunity? Site Currently Wetland? Yes Site Formerly Wetland? Yes Evidence of Disturbance Yes Soils Score Hydrology Score 7 Existing Vegetation Score 8 Geomorphic Score Surrounding Land Use Score 4 Function and Value Score Presence of Invasive Species 8 Score Site Disturbance Score 2 Ease of Access Score Stormwater Influence Score 3 Total Score Invasive Species Control? Yes Native Plantings? Yes Restore Hydrology? Yes Increase Diversity? Yes Convert Open Water to No Vegetated? Convert Emergent to No Shrub/Forested Increase Asthetic or No Educational Value Other No

Hydrology at site impacted by stormwater management. Existing tributary has no adjacent wetlands; hydrology from this tributary could be used for wetland restoration to make a larger emergent wetland. Hydric soils located adjacent in mapped emergent wetland. Upland grasses and Japanese stilt grass located adjacent to stormwater Notes management berm. Potential for endwall and gabion baskets to be maintained in future; same with storm water management pond and berm. Adjacent closed private community. Storm water from adjacent community. Small area of restoration; potential to increase adjacent wetland using the existing tributary as hydrology, some trees would require removal but very open canopy.

CHOH-01 Site ID Potential Restoration (linear feet) 100 4/27/16 Date

Existing Land Use Forested Parkland

Stormwater management;

Adjacent Land Use mowed maintained turf; upscale

community; Forested

Distance to Nearest Road 2 miles

Stream Hydrology Intermittent/ephemeral

RTE Species Present? No Known Cultural Concern? No Wetland Restoration Opportunity? Yes Existing Wetlands Present Yes Evidence of Disturbance Yes Can Restoration be Completed in NPS Yes Area? 5 Estimated Bank Erosion Score 5 Degree of Channel Incision Score Existing Floodplain Access Score Opportunity for Floodplain Development Score Threat of Impact to Resources Score

0 Surrounding Vegetation Score Land Use Score 0 Opportunity for Ecological Lift Score 4 Ease of Access 1 Surrounding Land Use Score 3 Total Score 31 Invasives Species Control? No Riparian Buffer Enhancement? No Restore Natural Hydrology? No Livestock Agricultural Exclusion No No Fish Passage? Channel Restoration? No

Increase Aesthetic or Educational Value? No

Other No

Both wetland and stream restoration could occur if end wall and gabion baskets are removed and area is restored. Erosion estimated 200 linear ft. No associated floodplain with stream, backwater conditions from canal likely cause water to come out of channel during high storm events. Only at upstream portion of the reach by stormwater management end wall. Stormwater management flow during storm event impacts existing stream Notes resources from erosion. Forested park land dominated by maple, oak, hickory, beech. Site is not easy to access; private community upstream and downstream towpath and canal. Stormwater management influence at top of reach; existing berm for stormwater management access. Should not rank high; local areas of erosion in the channel could be addressed but majority of site should not be restored. Backwater conditions at confluence with canal would complicate restoration.



