

Larry Damm Watershed in 1968

Watershed, which was extensively (80 percent of watershed) logged and roaded from 1963 through 1968.



Outslope treatment site



Stream crossing excavation site



Temporary "Bailey-type" bridge



View of temporary bridge, vegetated streambank and channel. Notice log stringer bridge between stream and temporary bridge.



Failing south abutment of log stringer bridge: one log 30' long & 6' in diameter

Failing north abutment of log stringer bridge: two logs 15-20' long & 4' in diameter