Establish a Trail Connection with the 114th Pennsylvania Monument at Chancellorsville Photos



Proposed beginning of trail, at point where it departs from Hazel Grove-Fairview Trail. Yellow flagging indicates the route.



Much of the proposed trail route goes through open woods, requiring minimal work to establish.

Route follows orange flagging.



A representative view of most of the trail route, marked with flagging through open woods.



One small bridge will be necessary to cross this stream.



Second of two stream crossings requiring a bridge.



Current condition of clearing along south side of eastbound Route 3, illustrating lack of a safe pull off for park staff and visitors. Traffic is extremely heavy and moves at high speed.



View of the clearing, looking north to Route 3. Both east and westbound lanes are visible in the middle ground. The 114th PA Monument is to the left of the view.



This view shows how the clearing has not been able to be maintained, resulting in high grass and encroachment by the surrounding woods.



The 114th PA Monument, with Route 3 in the background. Note the stains on both the stones and metal tablet, a result of lack of safe access for maintenance crews to clean the monument and the encroaching forest cover.



Type of footbridge to be installed on the trail connection.



Type of footbridge to be installed on the trail connection.