



*Figure 1 Facing east looking at Post Bend Lake*





*Figure 2 Facing east looking down eroded bank*





*Figure 3 Facing NE*





Figure 4 Facing east showing extensive erosion. This is another angle of Figure 3





*Figure 5 Facing S. Another angle of Figures 3&4*





*Figure 6 Facing east showing another foot path contributing to erosion*





*Figure 7 Facing south*





*Figure 8 West view of Fig. 7 from shoreline*





*Figure 9 Facing SW. View from shoreline*





*Figure 10 Western view of figure 3-5. Note you can see the Visitor Center*





*Figure 11 Facing S. View of shoreline and USACE rip-rap erosion control*





*Figure 12 Close-up of erosion undermining tree from Fig. 10*