Chattahoochee River National Recreation Area Georgia



Floodplain Statement of Findings

Paces Mill Unit Rehabilitation

September 2022

ANN HONIOUS Date: 2022.09.01 07:56:07	Date:	
Superintendent, Chattahoochee River		
National Recreation Area Recommended		
Recommended		
FORREST HARVEY Digitally signed by FORREST HARVEY Date: 2022.09.01 09:41:19 -06'00'	Date:	
Chief	-	
Water Resources Division		
Certification of Technical Accuracy and Service-wide Consistency		
	Date:	
Regional Director	-	

Regional Director Interior Region 2 Approved THIS PAGE INTENTIONALLY LEFT BLANK

CONTENTS

INTRODUCTION	1
PROPOSED ACTION	1
SITE DESCRIPTION	5
Floodplains	5
Wetlands	
JUSTIFICATION FOR USE OF THE FLOODPLAIN	9
SITE-SPECIFIC FLOOD RISK 1	11
FLOOD MITIGATION PLAN 1	12
SUMMARY 1	13
LITERATURE CITED 1	
APPENDIX A: WETLAND DETERMINATION DATA SHEETS 2	23

Tables

Table 1. Proposed Action Elements	. 1
Table 2. Peak Annual Streamflow, USGS 02335880, Chattahoochee River at Powers & I-285 near Atlanta,	
Georgia (upstream of Paces Mill)	. 6
Table 3. Peak Annual Streamflow, USGS 02335990, Chattahoochee River, US 41, near Atlanta, Georgia (at	
Paces Mill)	. 6
Table 4. Peak Annual Streamflow, USGS 02336490 Chattahoochee River, GA-280, near Atlanta, Georgia	
(downstream of Paces Mill).	. 7

Figures

Figure 1. Chattahoochee River National Recreation Area Vicinity Map	
Figure 1. Paces Mill Aerial Photograph and Topography	
Figure 3. Proposed Action Schematic Design (1 of 2)	
Figure 3. Proposed Action Schematic Design (2 of 2)	
Figure 4. Visitor Contact Station Architecture (1 of 2)	
Figure 4. Visitor Contact Station Architecture (2 of 2)	
Figure 5. National Flood Hazard Layer FIRMette	21

THIS PAGE INTENTIONALLY LEFT BLANK

INTRODUCTION

The National Park Service (NPS), Chattahoochee River National Recreation Area (National Recreation Area), has prepared a draft environmental assessment for proposed rehabilitation of the Paces Mill facility in the Palisades unit in Cobb County in the northern Atlanta metropolitan area, Georgia (figure 1).

Executive Order 11988 Floodplain Management and Executive Order 13690 Establishing a Federal Flood Risk Management Standard and a Process for Further Soliciting and Considering Stakeholder Input, require NPS and other federal agencies to evaluate the likely impacts of actions in floodplains, and to improve the nation's resilience to flood risk. The objective of Executive Order 11988 is to avoid, to the extent possible, the long- and short-term adverse impacts associated with the occupancy and modification of floodplains and to avoid direct or indirect support of floodplain development wherever there is a practicable alternative. Executive Order 13690 was issued to establish a Flood Risk Management Standard for federally funded projects to improve the nation's resilience to floods, and to ensure new federal infrastructure will last as long as intended. NPS procedures for complying with the floodplain Executive Orders are outlined in NPS Director's Order 77-2: Floodplain Management and Procedural Manual 77- 2: Floodplain Management (NPS 2002)

PROPOSED ACTION

The National Recreation Area is proposing to rehabilitate and reconfigure Paces Mill (table 1, figures 1–4). This includes upgrading the physical design, appearance, and infrastructure to address current deficiencies; to create a sustainable unit with a strong NPS identity; and one that is safe, easy to access, and enjoyable to visit. Additional detail can be found in the environmental assessment (NPS 2022) for this project, including design documents in the appendixes. During construction, staging and work would be phased to keep river access open. The unit would be impacted by construction activity and not have available parking, but a boat ramp would remain open for emergency response. Construction is expected to last 8 to 11 months. Standard and customized best management practices would be implemented as described in the environmental assessment (NPS 2022).

Elements	Proposed Action
Parking and Roads	To create a more desirable NPS experience, the current primary parking area would be removed and restored to a meadow consisting of native endemic prairie plant species as described below. A new parking area would be constructed farther north that would replace much of the area where the mowed grass field is currently located. The parking area would be sited to minimize the potential for vehicles to block traffic near the boat launch and would include a designated dropoff and pickup area, and trailer parking. Parking would consist of a two-way elongated "U" with approximately 176 perpendicular parking spaces. The total area encompassed by the parking lot would be similar to the current parking lot, but the paved area would be less than half due to the configuration and the impervious surfaces within the oval.
	Thirty parking spaces would be added to the site west of the entry road accessed from US 41 southbound. Twenty-four spaces would be added adjacent to the southern boat ramp. Fifteen parallel parking spaces would be added along the road connecting the west and east sides of the unit. The estimated total number of parking spaces at Paces Mill would remain the same at approximately 243. Speed tables (long, flat-topped speed bumps), crosswalks, and shade trees (only where outside of the 150-feet-wide Georgia Power easements) would be added to the road. All roads in Paces Mill would accommodate two-way traffic with the exception of the parking loop, which would be one-way. Road and parking lot surfaces would be asphalt with concrete curbs. Wood guardrails would be installed adjacent to roads to prevent parking outside designated parking spaces.

Table 1. Proposed Action Elements

Elements	Proposed Action
Vendor Pickup Area / South Boat Ramp	The layout of this area would be changed to add an oval turnaround loop for boat trailers and 24 parking spaces. This existing ramp is steep, the water is deeper and swifter, which allows motorized access, although the steepness of the ramp is not ideal for trailers. The area would have pull-through trailer parking for loading/offloading. Note: the northern boat ramp does not currently provide motorized access because the water is too shallow and would remain so. Access to boat ramps would be demarcated during construction.
Visitor Contact Station	The current restroom would be removed and a new visitor contact station constructed in the middle of the open end of the parking lot, near the current location, at a raised elevation to reduce the potential for flooding. Materials and drainage systems that minimize damage if flooded would be included. The new contact station would consist of three structures and would be connected to the same water, sewer, and electric utilities currently on-site. The front (southwest) building would be a pavilion/shade structure. A fee station would be moved from its current location to the hard-surface trail connecting the parking lot with the visitor contact station and interpretive and regulation signage. The northern two structures would consist of single-user restrooms/changing rooms. The buildings would include wood and stone construction and be more typical of NPS visitor use buildings. Locally sourced wood and stone would be used for the buildings and walkways to the extent possible. The buildings would optimize energy performance by including a glass pane above the door to minimize the need for lighting. A single LED light fixture would be in each restroom. Except for the restrooms/changing rooms, the visitor contact station would be open and not include heating or air-conditioning. The facility would be Architectural Barriers Act (ABA) compliant and accessible to people with disabilities. Existing trees would be retained to the extent practicable.
Meadow with Native Endemic Prairie Plant Species	The current parking area would be demolished and restored to an approximately 1.5-acre piedmont meadow, planted with native, endemic, non-woody, prairie wildflowers, forbs, and grasses. The plantings would include species found in a prairie remnant along adjacent US 41, including Georgia aster (<i>Symphyotrichum georgianum</i>), a state threatened species. Plantings would include seeds, plugs, and plants. The minimum number of plantings, including Georgia aster, would exceed the number of existing native wildflowers in the parking lot islands. Vegetation would average approximately 3 feet high in late summer. A multiuse trail would flank three of its four sides. Existing trees would be retained to the extent practicable. The area would be fenced with wooden split rail fence to establish the meadow and create a designated and interpreted space at Paces Mill. The site would be maintained as an early successional piedmont prairie vegetation would take 1 to 3 years to become established, and it would be watered for 2 to 3 years. Details of the restoration process, including a plant species list, can be found in appendix H of the environmental assessment (NPS 2022).
New Natural Surface Trail	A new natural-surface, single-track pedestrian-only trail (type 1 in the Trails Management Plan [NPS 2022]) would be created in the wooded section, between the picnic area and the river amphitheater. It would be approximately 2 to 4 feet wide and 800 feet long. The trail would be set back from the river at least 50 feet, in compliance with the Metropolitan River Protection Act. Trail construction would limit vegetation clearing (maximum of approximately 0.3 acre). The trail would be aligned to avoid the need to remove larger trees to the extent practicable. This would likely include using existing social trails along the river as part of the alignment. Remaining social trails would be closed to the extent possible via signage and barriers. The trail would also include access to an elevated river overlook described below. The trail would be maintained minimally including clearing fallen trees, trimming branches and brush, and repairing soil erosion as needed.
Southern Elevated River Overlook	An elevated river overlook would be constructed and consist of a wood platform on the top of the bank, which would not overhang the river. The overlook would be located where people have already created social trails. The site would offer good views of the river while tree/vegetation clearing would be kept to a minimum. This area is densely populated with nonnative species so most vegetation removed would be exotics. The overlook would be accessed via the new natural surface trail described above.
Hard-Surface, Multiuse Trails	A 10-foot-wide, multiuse, universally accessible, hard-surface sidewalk would encircle the interior of the site, providing visitors an easy way to navigate the site and to recreate at Paces Mill (walk, jog, bike, etc.). Interior multiuse sidewalks would connect visitors to the Bob Callan Trail on the north, and US 41 sidewalks.

Elements	Proposed Action
River Amphitheater Seating Area and River Access	The existing riprap on the riverbank, underneath the bridge, would be converted to a river amphitheater seating area and river access point. This area would be reconfigured using large, wide concrete steps that descend into the river. The area would be accessed using the hard- surfaced sidewalk on the southeast side of the southbound US 41 access road. The park will coordinate this project component with the Georgia Department of Transportation (GDOT), which owns the land under the bridge.
Northern Elevated River Overlook	A wood platform river overlook would be developed near the large river take-out sign's current location (this sign would remain for safety reasons). The platform would be sited on top of the riverbank and would not overhang the river. The proposed site is in an open area and very little, if any, vegetation removal would be necessary to construct it. A hard-surface sidewalk would connect it to the sidewalk encircling the parking area.
Picnic Area	The picnic area would remain in its current location. Several picnic tables would be replaced. One additional table would be added for a total of nine.
Shade Structure / Gathering Area	The existing deck, between the picnic area and the limited river access area, would be demolished, rebuilt in its current location on the exiting piers, and expanded. A shade structure would be added.
North Boat Ramp	Existing boulders, blocking vehicle access to the river, would be removed and replaced with a combination of fixed and removable bollards (short posts used to block vehicle access).
Bike Share	The existing bike share would be retained, but moved a short distance to the southwest corner of the new parking lot.
Dumpster Pad	A dumpster pad and dumpster would be located at the intersection of the boat ramp and east parking lot entrance. The dumpster would be shielded from view with a low granite wall and landscaping.
Signage	Most existing signage would be removed and replaced with as few signs as possible while still meeting site needs. New signage would address vehicular flow, parking requirements, allowed uses, interpretation, etc. Most of the signage would be in the pavilion at the visitor contact station, and would include allowed uses and rules, including but not limited to those associated with vehicle parking, boating, dogs, hours, fees, and fires. Waysides (interpretive signs) interpreting the meadow would be added.
Utilities	Power, water, sanitary sewer, and telecommunication utilities are all currently within 75 to 100 feet of the proposed visitor contact station and would be connected to the new facilities.
Site Grading and Storm Drainage	Most site grading would be for the new parking lot and around the visitor contact station. The finished grade would be similar or slightly below the current grade. Five bioswales would be constructed, two along the entrance roads, two in the northern parking lot, and one in the southern parking lot. They would contain moderate slopes on both sides with a gently sloped bottom. The bioswales would be planted in three zones: dry, mesic (moderate moisture), and wet/moist from top to bottom. Several species with the corresponding moisture tolerances would be planted in each zone. A rocky bottom stream channel would be located at the lowest elevation. The parking lots would be pitched to drain into the bioswales. An outlet structure would be constructed in the bioswale areas and approximately 400 feet of 18-inch, reinforced concrete pipe would be installed between the bioswales and the river where water would enter the river through river rock riprap. Additionally, the existing storm drains in the bioswale area, adjacent and south of the northbound US 41 entrance, would be reworked to accommodate the new bioswale design. Another outlet and approximately 100 feet of 18-inch, reinforced concrete pipe would be installed here to drain into the river rock riprap at the river. See appendix H in the environmental assessment (NPS 2022) for details.

THIS PAGE INTENTIONALLY LEFT BLANK

SITE DESCRIPTION

Paces Mill (approximately 14 acres) is the last "take-out" point in the park for casual rafters and kayakers. The unit is at the southern boundary of Cobb County; it was developed in the 1970s (figures 1 and 2). The river flows along the eastern and southern border of the site. Paces Mill is bordered by residential development to the west and northwest. Land use to the east of the river's floodplain is zoned commercial. Cobb Parkway (US 41) crosses the site in the southwestern portion of the property, including a bridge over the river. Additional NPS lands in the Palisades unit border Paces Mill to the northeast along the river. Stillhouse Creek flows into the river at the downstream boundary of Paces Mill.

Paces Mill includes mixed hardwood/pine woodlands to the west of Cobb Parkway and approximately the southeastern half of the property east of the parkway along the river. The remainder of Paces Mill includes a paved parking lot, entry roads, hard-surfaced walkways, a restroom, two boat ramps, a wood deck, dumpsters, a bike share rack, signs, and utilities connected to the restroom. High tension powerlines run through Paces Mill. A mowed grassy area is located in the northeastern corner of the facility. Native prairie vegetation is planted in the parking islands and in a pollinator garden near the restrooms; erosion control grasses are planted alongside the parkway and entrance roads.

FLOODPLAINS

The surface water hydrology of the Chattahoochee River is largely determined by the geological setting and processes that have formed the watershed, as well as hydrologic flow regulation by Buford Dam and its reservoir, which has altered the Chattahoochee River both physically and chemically. The river within the park is located within the Piedmont Province, Southern Piedmont section, Upland Georgia subsection, flowing along the Brevard Fault in a northeast to southwest direction.

This geological setting produces a relatively long and narrow watershed, surrounded in the vicinity of the park by rapidly developing urban and suburban areas. These features channel a large amount of nonpoint runoff into the river in this narrow watershed during storm events, which affect park characteristics, especially water. The portion of the Chattahoochee River watershed encompassed by the park extends from river mile 348.3 at Buford Dam to river mile 300.5 at Peachtree Creek and drains 416 square miles below Buford Dam.

Water releases from Buford Dam provide electrical power during peak demand periods. These surges create rapid and large changes in water levels and velocities downstream of Buford Dam. The surges have resulted in significant erosion of the riverbanks for as far as 20 miles downstream, significant widening of the river, and increased numbers of trees falling into the river (NPS 2000).

Elevations at Paces Mill range from 750 feet at the river to approximately 775 feet across most of the site, which is generally level above the banks of the river. The site is bordered to the west by a palisade (steep uphill slope). Nearly the entire project site is in the 100-year floodplain and Federal Emergency Management Agency (FEMA) Zones AE and A (figure 5). A 100-year floodplain or 100-year flood describes an area or event subject to a 1% probability of a certain size flood occurring in any given year. Zones A and AE are defined by FEMA as the channel of a stream plus any adjacent floodplain areas that must be kept free of encroachment so that the 1% annual chance flood can be carried without substantial increases in flood height. Detailed hydraulic analyses are not conducted for Zone A, but are for Zone AE where base flood elevations are determined and mapped. The base flood elevation (100-year flood) for this site is 778 feet. Impervious surfaces at Paces Mill total approximately 5 acres.

Peak annual streamflow is depicted below for three US Geological Survey (USGS) stream gauges: one upstream, one at Paces Mill, and one downstream (tables 2-4) (USGS 2022). Years of data availability vary by gauge.

Table 2. Peak Annual Streamflow, USGS 02335880, Chattahoochee River at Powers & I-285 near
Atlanta, Georgia (upstream of Paces Mill).

Year	Peak Streamflow (cfs)
1920	63,000
1946	59,000
1972	16,400
1973	17,700
1974	13,500
1975	17,400
1976	15,500
1977	26,000
1979	23,000
1982	22,000
2019	19,700
2020	16,900

Table 3. Peak Annual Streamflow, USGS 02335990, Chattahoochee River, US 41, near Atlanta, Georgia (at Paces Mill).

Year	Peak		
	Streamflow		
	(cfs)		
1972	17,500		
1973	16,800		
1974	14,100		
1975	18,000		
1976	19,200		
1977	28,900		
1978	15,200		
1979	26,700		
1980	15,000		
1981	8,460		
1982	24,100		
1983	15,400		
1984	18,100		
1985	9,910		
1986	6,870		
1987	17,300		
1988	9,920		
1989	12,500		
1990	25,100		
1991	15,000		

Year	Peak		
	Streamflow		
	(cfs)		
1990	33,000		
1991	16,000		
1992	15,900		
1993	23,400		
1994	17,200		
1995	20,500		
1996	28,500		
1997	22,300		
1998	27,700		
1999	8,590		
2000	19,800		
2001	14,300		
2002	19,100		
2003	23,300		
2004	31,000		
2005	27,300		
2006	14,200		
2007	14,900		
2008	9,810		
2009	42,300		
2010	27,200		
2011	12,700		
2012	12,900		
2013	20,100		
2014	21,100		
2015	15,500		
2016	19,700		
2017	17,500		
2018	13 300		
2019	28,200		
2020	24,900		
2021	28,200		

Table 4. Peak Annual Streamflow, USGS 02336490 Chattahoochee River, GA-280, near Atlanta, Georgia (downstream of Paces Mill).

The National Park Service has determined that the applicable regulatory floodplain for the proposed project is Class I (DO 77-2, PM 77-2).

WETLANDS

A qualified wetland scientist conducted a wetlands delineation of Paces Mill on December 5, 2018, which confirmed that no wetlands are present other than the river channel itself (see below) (Aarcher 2019) (appendix A). The wetland delineation was conducted in accordance with the US Army Corps of Engineers (USACE) Wetland Delineation Manual (USACE 1987), Region Supplement to the Corps of Engineers Wetland Delineation Manual: Eastern Mountains and Piedmont (USACE 2012), and the Cowardin et al. (1979) wetlands and deepwater habitats classification system. The scope of the project is not large enough to affect wetlands downstream.

The Chattahoochee River at Paces Mill is classified as a riverine wetland, lower perennial, unconsolidated bottom, and permanently flooded (R2UBH) (Cowardin et al. 1979). A portion of the riprap along the river shore, under the bridge, would be replaced with stone steps that would descend into the river. The steps would replace existing riprap. This action would have no impact on existing riverine wetland function, the total new wetland impacts (permanent and temporary) from construction would be less than 0.1 acre. The action is listed in section 4.2.1 of Procedural Manual #77-1 (NPS 2016) as an exempt action under, "Maintenance, repair, or renovation (but not full reconstruction¹ or expansion) of currently serviceable² facilities or structures:

...This exception allows for minor (0.1 acre or less) deviations in the structure's configuration or fill footprint in wetlands due to changes in construction codes, methods, or safety standards (e.g., handicap accessibility), but does <u>not</u> apply to other types of reconstruction/expansion (e.g., road widening to increase capacity, road re-routing) or conversion to other uses that cause new adverse impacts on wetlands."

Therefore, this project is exempt from the NPS Wetland Statement of Finding and compensation requirements.

The National Park Service will coordinate with the US Army Corps of Engineers to ensure that the work is authorized under section 404 of the Clean Water Act.

¹ Full reconstruction of instream diversions, water intake or outfall structures, or similar, legal and permitted instream structures that are damaged or destroyed by storms, floods, or similar events may be allowed under this exception.

² "Currently serviceable" means usable as is or with maintenance or renovation, but not so degraded as to require full reconstruction.

JUSTIFICATION FOR USE OF THE FLOODPLAIN

The justification for relocating, upgrading, and augmenting existing structures in the 100- year floodplain is as follows:

- The purpose of the unit and its existing functions are river access. Therefore, functions of the unit cannot be moved to another location.
- As noted above, nearly the entire unit is within the 100-year floodplain.
- As noted above, the steep adjacent topography prevents moving the facilities farther upslope.
- The site is needed to provide park visitors with opportunities for land- and water-based recreation in the southern part of the park. Demand for recreational (land and water based) opportunities has been growing.
- This site is the last stop of the National Water Trail.
- This unit provides a gateway to the National Recreation Area as it is within the Atlanta metropolitan area and includes a trailhead for the popular Bob Callahan trail and is adjacent to a multiuse trail that will connect the National Recreation Area with the city of Atlanta and another popular trail.

THIS PAGE INTENTIONALLY LEFT BLANK

SITE-SPECIFIC FLOOD RISK

Flood risks associated with the proposed action include risk to capital investment resulting from damage to infrastructure and a slight risk to human health and life due to floodplain occupancy.

Paces Mill occupies approximately 14 acres, almost all of which is in the 100-year floodplain. The proposed project, which includes new infrastructure, would result in new impacts to property and to floodplain functions and values. New pavement and impervious surface would be installed in the form of new parking areas, multiuse trail, visitor contact station, and restrooms. However, the total area of impervious surface increase after project implementation would be small because the current primary parking lot would be removed and converted to permeable surface, much of the multiuse hard-surface trail would be sited where pavement already exists, and the existing restroom facility would be removed. The reconfigured pavement and structures are unlikely to negatively affect flood storage or groundwater recharge to a measurable degree, or degrade overall riparian services because the impervious surface footprint would remain approximately the same after construction (5 acres). The flood hazard to capital investment is moderated by the fact that the river system is regulated by Buford Dam. Local rainfall events typically do not produce flood conditions at the site.

The 2009 flood left no evidence of scour on the terrace level, where the proposed infrastructure would be located. NPS staff witnessed low flow velocities during this flood. The primary risk on the terrace is sedimentation (being covered by mud) rather than removal by scouring.

Ample notice of severe weather is provided by the National Weather Service and other agencies, which makes warning and evacuating the site a practical option for protecting human life, minimizing the risk to human health and safety.

FLOOD MITIGATION PLAN

The proposed rehabilitation project does not include any changes that would reduce flood storage capacity. The risk of flooding would remain, similar to current conditions. Because proposed and existing structures are located within the floodplain, damage from flooding may occur. The park is willing to accept potential flood damage to structures as the price of providing recreational facilities at this unit.

The following measures are included in the proposed project as design features and would reduce hazards to human life and property in the regulatory floodplain while minimizing the impact on the natural resources of the floodplain:

- The parking lot and drainage system, including bioswales, would include design features to improve drainage patterns to facilitate water return to the river and temporary water pooling on permeable rather than impervious surfaces.
- The visitor contact station, including restrooms, would be consistent with the intent of the standards and criteria of the National Flood Insurance Program (44 CFR Part 60).
- The contact station would be open, which would allow water flow through during flooding.
- The proposed design would include an increased proportion of the total area of native vegetation versus nonnative, largely due to removal of the mowed field and creation of the native prairie meadow.
- All rehabilitated areas would use appropriate native plant materials approved by the National Park Service.
- All disturbed areas would be stabilized as soon as practical to limit erosion and the spread of noxious and nonnative plants.
- The most natural areas of the floodplain, including the wooded areas along the river and tributary, would remain with only minimal disturbance for natural soft surface trail construction.
- All native trees and vegetation would be left in place to the maximum extent possible.
- No overnight use of the unit would be allowed.
- The unit would be closed when flooded.

SUMMARY

The National Park Service has determined that there are no practicable, non-floodplain locations for the proposed action. Potential impacts to human life and health would be mitigated through use pattern (no overnight use) and flood closures. The potential impacts to the proposed capital investment would be mitigated through a combination of implementing design standards consistent with the National Flood Insurance Program's Floodplain Management Criteria for Flood-Prone Areas (44 CFR section 60.3) and selecting movable or sacrificial infrastructure such as picnic tables.

Despite the new parking spaces, trailer spaces, multiuse path, restrooms, visitor contact area, and other paved areas, the natural and beneficial floodplain values are not expected to be negatively impacted to any measurable extent because the cumulative amount of impervious surface at the site would remain approximately the same (5 acres). Aboveground structures would be designed to minimally impede floodwater flows. Therefore, the National Park Service finds that the proposed action would not have any material additional adverse impacts on floodplains and their associated values and that no additional mitigation is required.

LITERATURE CITED

Aarcher, Inc.

2018 Unpublished wetland delineation data. December 5, 2018.

Cowardin, L. M., V. Carter, F. C. Golet, and E. T. LaRoe

1979 Classification of Wetland and Deepwater Habitats of the United States. US Fish and Wildlife Service. USFWS/OBS 79/31. 103 pp.

Federal Emergency Management Agency (FEMA)

2019 National Flood Hazard Layer FIRMette.

National Park Service (NPS)

- 2022 Environmental Assessment, Paces Mill Unit Rehabilitation.
- 2021 Preliminary Trails Management Plan. Chattahoochee River National Recreation Area.
- 2000 Water Resources Management Plan, Chattahoochee River National Recreation Area, by Sam Kunkle and David Vana-Miller. NPS D-48
- 2016 National Park Service Procedural Manual #77-1: Wetland Protection. Reissued June 21, 2016.

US Army Corps of Engineers (USACE)

- 2012 Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Eastern Mountains and Piedmont Region (Version 2.0). ERDC/EL TR-12-9.
- 1987 Corps of Engineers Wetlands Delineation Manual. Environmental Laboratory. Wetlands Research Program Technical Report Y-87-1.

US Geological Survey (USGS)

- 2022 National Water Information System: Web Interface. Internet website: https://nwis.waterdata.usgs.gov/nwis.
- 2006 National Water Information System: Web Interface, USGS Water Data for the Nation. Internet website: https://nwis.waterdata.usgs.gov/nwis.




Figure 1. Chattahoochee River National Recreation Area Vicinity Map




Figure 2. Paces Mill Aerial Photograph and Topography

Figure 3. Proposed Action Schematic Design (1 of 2)






Figure 3. Proposed Action Schematic Design (2 of 2)




Figure 4. Visitor Contact Station Architecture (1 of 2)





Figure 4. Visitor Contact Station Architecture (2 of 2)

Figure 5. National Flood Hazard Layer FIRMette



Zone A - An area inundated by 1% annual chance flooding, for which no BFEs have been determined. **Zone** AE - An area inundated by 1% annual chance flooding, for which (base flood elevations) have been determined. Paces Mill is primarily in Zone AE with the exception of Stillhouse Creek, which is in Zone A.

THIS PAGE INTENTIONALLY LEFT BLANK

APPENDIX A: WETLAND DETERMINATION DATA SHEETS

THIS PAGE INTENTIONALLY LEFT BLANK

U.S. Army Corps of Engineers WETLAND DETERMINATION DATA SHEET – Eastern Mountains and Piedmont Region See ERDC/EL TR-07-24; the proponent agency is CECW-CO-R				Requirement Control Symbol EXEMPT (Authority: AR 335-15, paragraph 5-2a)		
Project/Site: <u>Paces Mill Chattahoochee River National Recreation Ar</u> Applicant/Owner: <u>National Park Service</u> Investigator(s): Pat Ferral	rea City/County: <u>Atlanta/Cot</u> _ Section, Township, Range: _	State:		ng Date: <u>12</u> ng Point: <u> </u>		
	ocal relief (concave, convex, n	one): <u>none</u> .455627		ope (%): Datum:N		
Are climatic / hydrologic conditions on the site typical for this time of years Are Vegetation, Soil, or Hydrology significantly d Are Vegetation, Soil, or Hydrology naturally prob SUMMARY OF FINDINGS – Attach site map showing	listurbed? Are "Normal Cir plematic? (If needed, expl	No cumstances" p ain any answe	(If no, explain in present? Y rs in Remarks.)	n Remarks.) Yes <u>X</u> N	۰ <u>۱</u>	
Hydrophytic Vegetation Present? Yes X No Hydric Soil Present? Yes No X Wetland Hydrology Present? Yes No X	Is the Sampled Area within a Wetland?	Yes	No_>	<u><</u>		
Remarks:						
HYDROLOGY						
Water Marks (B1)	e (B14) dor (C1) eres on Living Roots (C3) ed Iron (C4) ion in Tilled Soils (C6) (C7)	Surface So Sparsely V Drainage F Moss Trim Dry-Seaso Crayfish B Saturation Stunted or Geomorph Shallow Av Microtopoo	icators (minimur bil Cracks (B6) /egetated Conca Patterns (B10) Lines (B16) on Water Table (furrows (C8) Visible on Aeria Stressed Plants ic Position (D2) quitard (D3) graphic Relief (D ral Test (D5)	ave Surface C2) Il Imagery ((s (D1)	(B8)	
Surface Water Present? Yes No X Depth (incl Water Table Present? Yes No X Depth (incl Saturation Present? Yes No X Depth (incl (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photo	nes): Wetland H	ydrology Pres ailable:	sent? Y	ïes N	lo_X_	
Remarks:						

VEGETATION (Four Strata) – Use scientific names of plants.

Sampling Point: UPDP-01

	Absolute	Dominant	Indicator	
<u>Tree Stratum</u> (Plot size: <u>30' radius</u>)	% Cover	Species?	Status	Dominance Test worksheet:
1. Liriodendron tulipifera	30	Yes	FACU	Number of Dominant Species
2. Pinus taeda	20	Yes	FAC	That Are OBL, FACW, or FAC: 3 (A)
3.				Total Number of Dominant
4.		·		Species Across All Strata: 5 (B)
5.		·		
		·		Percent of Dominant Species
6.		·		That Are OBL, FACW, or FAC: <u>60.0%</u> (A/B)
7				Prevalence Index worksheet:
	50	=Total Cover		Total % Cover of: Multiply by:
	20%	of total cover:	10	OBL species x 1 =0
Sapling/Shrub Stratum (Plot size: 15' radius)			FACW species 0 x 2 = 0
1. Ligustrum japonicum	40	Yes	FAC	FAC species 100 x 3 = 300
2.				FACU species 40 x 4 = 160
3.				UPL species 0 x 5 = 0
4.				Column Totals: 140 (A) 460 (B)
5.		·		Prevalence Index = $B/A = 3.29$
6.		·		Hydrophytic Vegetation Indicators:
7.		·		1 - Rapid Test for Hydrophytic Vegetation
		·		X 2 - Dominance Test is >50%
8.		·		
9				3 - Prevalence Index is ≤3.0 ¹
	40	=Total Cover		4 - Morphological Adaptations ¹ (Provide supporting
50% of total cover: 2	20 20%	of total cover:	8	data in Remarks or on a separate sheet)
Herb Stratum (Plot size: 5' radius)				Problematic Hydrophytic Vegetation ¹ (Explain)
1. Ligustrum japonicum	40	Yes	FAC	¹ Indicators of hydric soil and wetland hydrology must
2.				be present, unless disturbed or problematic.
3.				Definitions of Four Vegetation Strata:
4.		·		Tree – Woody plants, excluding vines, 3 in. (7.6 cm) or
5.		·		more in diameter at breast height (DBH), regardless of
6.		·		height.
		·		
7		·		Sapling/Shrub – Woody plants, excluding vines, less
8				than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.
9		. <u> </u>		
10				Herb – All herbaceous (non-woody) plants, regardless
11				of size, and woody plants less than 3.28 ft tall.
	40	=Total Cover		Woody Vine – All woody vines greater than 3.28 ft in
50% of total cover: 2	20 20%	of total cover:	8	height.
Woody Vine Stratum (Plot size: 30' radius)				
1. Lonicera japonica	10	Yes	FACU	
2.				
3.		· · · · · · · · · · · · · · · · · · ·		
		·		
4		·		
5				Hydrophytic
	10	=Total Cover		Vegetation
50% of total cover:	520%	of total cover:	2	Present? Yes X No
Remarks: (Include photo numbers here or on a sepa	arate sheet.)			
· · · · · · · · · · · · · · · · · · ·				

VEGETATION (Five Strata) – Use scientific names of plants.

Sampling Point: UPDP-01

	Absolute Dominan	t Indicator	
Tree Stratum (Plot size:)	% Cover Species?	Status	Dominance Test worksheet:
1			Number of Dominant Species
2.			That Are OBL, FACW, or FAC:(A)
3.			Total Number of Dominant
4.			Species Across All Strata:(B)
5.			Percent of Dominant Species
6			That Are OBL, FACW, or FAC: (A/B)
50% of total cover:	=Total Cove 20% of total cov		Prevalence Index worksheet: Total % Cover of: Multiply by:
Sapling Stratum (Plot size: 30)	20% 01 10181 000	er	
1.			OBL species x 1 = FACW species x 2 =
2.			FACW species x 2 = FAC species x 3 =
3			FACU species x 4 =
			UPL species x 5 =
			Column Totals: (A) (B)
6.			Prevalence Index = B/A =
0.	=Total Cove		Hydrophytic Vegetation Indicators:
50% of total cover:			1 - Rapid Test for Hydrophytic Vegetation
<u>Shrub Stratum</u> (Plot size: 30)	2070 01 10141 000	er	2 - Dominance Test is >50%
·			$3 - Prevalence Index is \leq 3.0^{1}$
			4 - Morphological Adaptations ¹ (Provide supporting
			data in Remarks or on a separate sheet)
4			Problematic Hydrophytic Vegetation ¹ (Explain)
5.			¹ Indicators of hydric soil and wetland hydrology must
6.			be present, unless disturbed or problematic.
	=Total Cove	er	Definitions of Five Vegetation Strata:
50% of total cover:	20% of total cov	er:	Tree – Woody plants, excluding woody vines,
Herb Stratum (Plot size:)			approximately 20 ft (6 m) or more in height and 3 in.
1			(7.6 cm) or larger in diameter at breast height (DBH).
2.			Sapling – Woody plants, excluding woody vines,
3.			approximately 20 ft (6 m) or more in height and less
4			than 3 in. (7.6 cm) DBH.
5			Shrub - Woody Plants, excluding woody vines,
6			approximately 3 to 20 ft (1 to 6 m) in height.
7			Herb – All herbaceous (non-woody) plants, including
8			herbaceous vines, regardless of size, <u>and</u> woody
9			plants, except woody vines, less than approximately 3 ft (1 m) in height.
10			
11			Woody Vine – All woody vines, regardless of height.
	=Total Cove	er	
50% of total cover:	20% of total cov	er:	
Woody Vine Stratum (Plot size: 15)			
1			
2			
3			
4			
5			Hydrophytic
	=Total Cove		Vegetation
50% of total cover:	20% of total cov	er:	Present? Yes No X
Remarks: (Include photo numbers here or on a sepa			

SOIL

Profile Desc Depth	ription: (Describe t Matrix	o the dep		ument the indica x Features	ator or co	onfirm the abse	ence of indic	cators.)	
inches)	Color (moist)	%	Color (moist)	% Type ¹	Loc ²	Texture		Rem	arks
0 - 6	7.5YR 4/4	50				Loamy/Claye	ev	Mixed fill	material
6 - 12	2.5YR 4/8	60				Loamy/Claye			
Type: C=Co	oncentration, D=Depl	etion. RM	=Reduced Matrix. N	/S=Masked San	d Grains.	² Lo	cation: PL=F	Pore Lining, M	=Matrix.
Black His Hydroger Stratified 2 cm Mud Depleted Thick Da Sandy M Sandy G Sandy Re Stripped	(A1) ipedon (A2)	e (A11)	Thin Dark Su Loamy Muck Loamy Gleye Depleted Ma Redox Dark Depleted Da Redox Depre Iron-Mangar MLRA 130 Umbric Surfa Piedmont Flo	Surface (F6) Irk Surface (F7) essions (F8) nese Masses (F1)	A 147, 14 ILRA 136 2) (LRR N A 122, 136 19) (MLR	48) 5) N, 5) A 148)	2 cm Mi Coast P (MLR Piedmo (MLR Red Pa (outs Very Sh Other (B ³ Indicators of wetland	uck (A10) (ML Prairie Redox (A 147, 148) nt Floodplain 5 A 136, 147) rent Material (ide MLRA 12 nallow Dark Su Explain in Ren	A16) Soils (F19) F21) 7, 147, 148) Irface (F22) harks) vegetation and ist be present,
Restrictive L Type: Depth (in Remarks: No hydric soi						Hydric Soil	Present?	Yes	NoX

U.S.	Army Corps of Engi	neers		Requirement Cont	-
WETLAND DETERMINATION DA	t Region	EXEMP1 (Authority: AR			
See ERDC/EL TR-07	-24; the proponent ag	ency is CECW-CO-R		paragraph 5	
Project/Site: Paces Mill Chattahoochee R	iver National Recreation Ar	ea City/County: <u>Atlanta/Co</u>	obb	Sampling Date	e: <u>12/5/2018</u>
Applicant/Owner: National Park Service	e		State:	GA Sampling Poir	t: UPDP-02
Investigator(s): Pat Ferral		Section, Township, Range:			
Landform (hillside, terrace, etc.): floodpla	in Lo	ocal relief (concave, convex,		Slope (%): 0 - 2
Subregion (LRR or MLRA): LRR P, MLRA		Long: 8	4.455609		, NAD 83
Soil Map Unit Name: Toccoa sandy loam				assification:	
Are climatic / hydrologic conditions on the s	ite typical for this time of ve	ear? Yes X		(If no, explain in Rema	rks)
Are Vegetation , Soil , or Hyd				present? Yes X	
Are Vegetation, Soil, or Hyd	ers in Remarks.)				
				,	
SUMMARY OF FINDINGS – Attac	h site map showing	sampling point locati	ons, transec	cts, important feat	ures, etc.
Hydrophytic Vegetation Present?	Yes No X	Is the Sampled Area			
Hydric Soil Present?	Yes No X	within a Wetland?	Yes	<u>No X</u>	
Wetland Hydrology Present?	Yes <u>No X</u>				
Remarks:					
HYDROLOGY					
Wetland Hydrology Indicators:			Secondary Ind	licators (minimum of tw	o required)
Primary Indicators (minimum of one is requ	uired; check all that apply)		Surface S	oil Cracks (B6)	
Surface Water (A1)					
High Water Table (A2)	Patterns (B10)				
Saturation (A3)	Oxidized Rhizosphe Presence of Reduce	eres on Living Roots (C3)		n Lines (B16) on Water Table (C2)	
Water Marks (B1) Sediment Deposits (B2)		ion in Tilled Soils (C6)		Burrows (C8)	
Drift Deposits (B3)	Thin Muck Surface	· · /		Visible on Aerial Image	erv (C9)
Algal Mat or Crust (B4)	Other (Explain in Re	,		r Stressed Plants (D1)	J ()
Iron Deposits (B5)		,		nic Position (D2)	
Inundation Visible on Aerial Imagery (quitard (D3)				
Water-Stained Leaves (B9)				graphic Relief (D4)	
Aquatic Fauna (B13)			FAC-Neut	ral Test (D5)	
Field Observations:					
Surface Water Present? Yes	No X Depth (inch				
Water Table Present? Yes Saturation Present? Yes	No <u>X</u> Depth (inch No <u>X</u> Depth (inch		Hydrology Pres	sent? Yes	<u>No X</u>
(includes capillary fringe)			ily aloiogy i lo		
Describe Recorded Data (stream gauge, n	nonitoring well, aerial photo	s, previous inspections), if a	vailable:		
Remarks:					

VEGETATION (Four Strata) – Use scientific names of plants.

Sampling Point: UPDP-02

	Absolute	Dominant	Indicator	
Tree Stratum (Plot size: 30' radius)	% Cover	Species?	Status	Dominance Test worksheet:
1. Acer saccharum	20	Yes	FACU	Number of Dominant Species
2.				That Are OBL, FACW, or FAC: 0 (A)
3.				Total Number of Dominant
4.				Species Across All Strata: 2 (B)
5.				
		·		Percent of Dominant Species
6.				That Are OBL, FACW, or FAC: 0.0% (A/B)
7		·		Prevalence Index worksheet:
	20	=Total Cover		Total % Cover of: Multiply by:
50% of total cover:1	0 20%	o of total cover:	4	OBL species 0 x 1 = 0
Sapling/Shrub Stratum (Plot size: 15' radius)			FACW species 0 x 2 = 0
1. Ligustrum japonicum	80	Yes	UPL	FAC species 0 x 3 = 0
2.				FACU species 20 x 4 = 80
3.		·		UPL species 80 x 5 = 400
4.				Column Totals: 100 (A) 480 (B)
5.				Prevalence Index = $B/A = 4.80$
6				Hydrophytic Vegetation Indicators:
7				1 - Rapid Test for Hydrophytic Vegetation
8				2 - Dominance Test is >50%
9.				3 - Prevalence Index is ≤3.0 ¹
	80	=Total Cover		4 - Morphological Adaptations ¹ (Provide supporting
50% of total cover: 4	0 20%	of total cover:	16	data in Remarks or on a separate sheet)
Herb Stratum (Plot size: 5' radius)				Problematic Hydrophytic Vegetation ¹ (Explain)
1.				
···				¹ Indicators of hydric soil and wetland hydrology must
2.				be present, unless disturbed or problematic.
3				Definitions of Four Vegetation Strata:
4.				Tree – Woody plants, excluding vines, 3 in. (7.6 cm) or
5				more in diameter at breast height (DBH), regardless of
6				height.
7.				Sapling/Shrub – Woody plants, excluding vines, less
8.				than 3 in. DBH and greater than or equal to 3.28 ft
9.				(1 m) tall.
10.			·	Herb – All herbaceous (non-woody) plants, regardless
				of size, and woody plants less than 3.28 ft tall.
11				
		=Total Cover		Woody Vine – All woody vines greater than 3.28 ft in
50% of total cover:	20%	of total cover:		height.
<u>Woody Vine Stratum</u> (Plot size: <u>30' radius</u>)				
1				
2.				
3.				
4.				
5.				
· · · · · · · · · · · · · · · · · · ·		-Total Cavar		Hydrophytic
		=Total Cover		Vegetation
50% of total cover:	20%	of total cover:		Present? Yes <u>No X</u>
Remarks: (Include photo numbers here or on a sepa	arate sheet.)			

VEGETATION (Five Strata) - Use scientific names of plants.

Sampling Point: UPDP-02

	Absolute	Dominant	Indicator	
Tree Stratum (Plot size:)	% Cover	Species?	Status	Dominance Test worksheet:
1				Number of Dominant Species That Are OBL, FACW, or FAC: (A)
3				Total Number of Dominant Species Across All Strata: (B)
5.				
6.				Percent of Dominant Species That Are OBL, FACW, or FAC:(A/B)
		=Total Cover		Prevalence Index worksheet:
50% of total cover:	20%	of total cover:		Total % Cover of: Multiply by:
Sapling Stratum (Plot size:)				OBL species x 1 =
1				FACW species x 2 =
2				FAC species x 3 =
3				FACU species x 4 =
4				UPL species x 5 =
5				Column Totals: (A)(B)
6.				Prevalence Index = B/A =
		=Total Cover		Hydrophytic Vegetation Indicators:
50% of total cover:	20%	of total cover:		1 - Rapid Test for Hydrophytic Vegetation
<u>Shrub Stratum</u> (Plot size:)				2 - Dominance Test is >50%
1				3 - Prevalence Index is $\leq 3.0^1$
· · · · · · · · · · · · · · · · · · ·	·			
2				4 - Morphological Adaptations ¹ (Provide supporting
3.				data in Remarks or on a separate sheet)
4				Problematic Hydrophytic Vegetation ¹ (Explain)
5				¹ Indicators of hydric soil and wetland hydrology must
6				be present, unless disturbed or problematic.
		=Total Cover		Definitions of Five Vegetation Strata:
50% of total cover:	20%	of total cover:		Tree – Woody plants, excluding woody vines,
Herb Stratum (Plot size:)				approximately 20 ft (6 m) or more in height and 3 in.
1				(7.6 cm) or larger in diameter at breast height (DBH).
2				Sapling – Woody plants, excluding woody vines,
3.				approximately 20 ft (6 m) or more in height and less
4.				than 3 in. (7.6 cm) DBH.
5.				Shrub - Woody Plants, excluding woody vines,
6.				approximately 3 to 20 ft (1 to 6 m) in height.
7.				Herb – All herbaceous (non-woody) plants, including
8.				herbaceous vines, regardless of size, and woody
9.				plants, except woody vines, less than approximately
				3 ft (1 m) in height.
10				
11				Woody Vine – All woody vines, regardless of height.
		=Total Cover		
50% of total cover:	20%	of total cover:		
Woody Vine Stratum (Plot size:)				
3				
4				
5				Hydrophytic
		=Total Cover		Vegetation
50% of total cover:	20%	of total cover:		Present? Yes No X
Remarks: (Include photo numbers here or on a sepa	arate sheet)			

SOIL

Hydric Soil Indicators: Indicators: Indicators for Problematic Hydr Histosol (A1) Polyvalue Below Surface (S8) (MLRA 147, 148) 2 cm Muck (A10) (MLRA 147 Histic Epipedon (A2) Thin Dark Surface (S9) (MLRA 147, 148) 2 com Muck (A10) (MLRA 147 Black Histic (A3) Loamy Mucky Mineral (F1) (MLRA 136) (MLRA 147, 148) Coast Prairie Redox (A16) Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Piedmont Floodplain Soils (F1 Piedmont Floodplain Soils (F1 2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Red Parent Material (F21) (MLRA 136, 147) Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) (outside MLRA 127, 147, 147, 147, 147, 147, 147, 147, 14	<pre>//Clayey //Clayey //Claye //Clay</pre>
0 - 10 7.5YR 4/3 95 2.5YR 4/6 5 Loamy/Clayey 10 - 15 5YR 5/6 100 Loamy/Clayey Loamy/Clayey 11 - 15 5YR 5/6 100 Loamy/Clayey Loamy/Clayey 12 - 15 Polyvalue Below Su	<pre>//Clayey //Clayey //Claye //Clay</pre>
10 - 15 5YR 5/6 100 Loamy/Clayey 11 - 15 5YR 5/6 Indicators Indicators 11 - 15 11 - 15 11 - 15 11 - 15 12 - 11 - 15 11 - 15 11 - 15 11 - 15 13 - 16 - 16 - 16 - 16 - 16 - 16 - 16 -	//Clayey ² Location: PL=Pore Lining, M=Matrix. Indicators for Problematic Hydric Soils 2 cm Muck (A10) (MLRA 147) Coast Prairie Redox (A16) (MLRA 147, 148) Piedmont Floodplain Soils (F19)
¹ Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains. ² Location: PL=Pore Lining, M=Matrix. Hydric Soil Indicators: Indicators for Problematic Hydr Histosol (A1) Polyvalue Below Surface (S8) (MLRA 147, 148) 2 cm Muck (A10) (MLRA 147, 148) Black Histic (A3) Loamy Mucky Mineral (F1) (MLRA 136) (MLRA 147, 148) Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Piedmont Floodplain Soils (F1) Stratified Layers (A5) Depleted Matrix (F3) (MLRA 136, 147) Depleted Below Dark Surface (A11) Depleted Dark Surface (F6) Redox Dark Surface (F6) Stratified Layers (A5) Iron-Manganese Masses (F12) (LRR N, Sandy Gleyed Matrix (S4) Other (Explain in Remarks) Sandy Gleyed Matrix (S6) Umbric Surface (F13) (MLRA 122, 136) ³ Indicators of hydrophytic vegetati wetland hydrology must be pr Stripped Matrix (S6) Piedmont Floodplain Soils (F12) (MLRA 127, 147, 148) wetland hydrology must be pr Dark Surface (S7) Red Parent Material (F21) (MLRA 127, 147, 148) ³ Indicators of nydrophytic vegetati wetland hydrology must be pr Thick Dark Surface (S7) Red Parent Material (F21) (MLRA 127, 147, 148) wetland hydrology must be pr Umbric Surface (S7) Red Parent Material (F21) (MLRA 127, 147, 148) moless disturbed or problemati	² Location: PL=Pore Lining, M=Matrix. Indicators for Problematic Hydric Soils 2 cm Muck (A10) (MLRA 147) Coast Prairie Redox (A16) (MLRA 147, 148) Piedmont Floodplain Soils (F19)
Hydric Soil Indicators: Indicators: Indicators for Problematic Hydr Histosol (A1) Polyvalue Below Surface (S8) (MLRA 147, 148) 2 cm Muck (A10) (MLRA 147 Histic Epipedon (A2) Thin Dark Surface (S9) (MLRA 147, 148) 2 com Muck (A10) (MLRA 147 Black Histic (A3) Loamy Mucky Mineral (F1) (MLRA 136) (MLRA 147, 148) Coast Prairie Redox (A16) Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Piedmont Floodplain Soils (F1 Piedmont Floodplain Soils (F1 2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Red Parent Material (F21) (MLRA 136, 147) Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) (outside MLRA 127, 147, 147, 147, 147, 147, 147, 147, 14	Indicators for Problematic Hydric Soils 2 cm Muck (A10) (MLRA 147) Coast Prairie Redox (A16) (MLRA 147, 148) Piedmont Floodplain Soils (F19)
Hydric Soil Indicators: Indicators: Indicators for Problematic Hydr Histosol (A1) Polyvalue Below Surface (S8) (MLRA 147, 148) 2 cm Muck (A10) (MLRA 147 Histic Epipedon (A2) Thin Dark Surface (S9) (MLRA 147, 148) 2 coast Prairie Redox (A16) Black Histic (A3) Loamy Mucky Mineral (F1) (MLRA 136) (MLRA 147, 148) Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Piedmont Floodplain Soils (F1 Stratified Layers (A5) Depleted Matrix (F3) (MLRA 136, 147) 2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Red Parent Material (F21) Opeleted Below Dark Surface (A11) Depleted Dark Surface (F7) (outside MLRA 127, 147, 147, 147, 147, 147, 147, 147, 14	Indicators for Problematic Hydric Soils 2 cm Muck (A10) (MLRA 147) Coast Prairie Redox (A16) (MLRA 147, 148) Piedmont Floodplain Soils (F19)
Hydric Soil Indicators: Indicators: Indicators for Problematic Hydric Histosol (A1) Polyvalue Below Surface (S8) (MLRA 147, 148) 2 cm Muck (A10) (MLRA 147 Histic Epipedon (A2) Thin Dark Surface (S9) (MLRA 147, 148) 2 com Muck (A10) (MLRA 147 Black Histic (A3) Loamy Mucky Mineral (F1) (MLRA 136) (MLRA 147, 148) Hydrogen Sulfde (A4) Loamy Gleyed Matrix (F2) Piedmont Floodplain Soils (F1 Stratified Layers (A5) Depleted Matrix (F3) (MLRA 136, 147) 2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Red Parent Material (F21) Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) (outside MLRA 127, 147, 147, 147, 147, 147, 147, 147, 14	Indicators for Problematic Hydric Soils 2 cm Muck (A10) (MLRA 147) Coast Prairie Redox (A16) (MLRA 147, 148) Piedmont Floodplain Soils (F19)
Hydric Soil Indicators: Indicators: Indicators for Problematic Hydr Histosol (A1) Polyvalue Below Surface (S8) (MLRA 147, 148) 2 cm Muck (A10) (MLRA 147 Histic Epipedon (A2) Thin Dark Surface (S9) (MLRA 147, 148) 2 coast Prairie Redox (A16) Black Histic (A3) Loamy Mucky Mineral (F1) (MLRA 136) (MLRA 147, 148) Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Piedmont Floodplain Soils (F1 Stratified Layers (A5) Depleted Matrix (F3) (MLRA 136, 147) 2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Red Parent Material (F21) Opeleted Below Dark Surface (A11) Depleted Dark Surface (F7) (outside MLRA 127, 147, 147, 147, 147, 147, 147, 147, 14	Indicators for Problematic Hydric Soils 2 cm Muck (A10) (MLRA 147) Coast Prairie Redox (A16) (MLRA 147, 148) Piedmont Floodplain Soils (F19)
Hydric Soil Indicators: Indicators: Indicators for Problematic Hydr Histosol (A1) Polyvalue Below Surface (S8) (MLRA 147, 148) 2 cm Muck (A10) (MLRA 147 Histic Epipedon (A2) Thin Dark Surface (S9) (MLRA 147, 148) 2 coast Prairie Redox (A16) Black Histic (A3) Loamy Mucky Mineral (F1) (MLRA 136) (MLRA 147, 148) Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Piedmont Floodplain Soils (F1 Stratified Layers (A5) Depleted Matrix (F3) (MLRA 136, 147) 2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Red Parent Material (F21) Opeleted Below Dark Surface (A11) Depleted Dark Surface (F7) (outside MLRA 127, 147, 147, 147, 147, 147, 147, 147, 14	Indicators for Problematic Hydric Soils 2 cm Muck (A10) (MLRA 147) Coast Prairie Redox (A16) (MLRA 147, 148) Piedmont Floodplain Soils (F19)
Hydric Soil Indicators: Indicators: Indicators for Problematic Hydric Histosol (A1) Polyvalue Below Surface (S8) (MLRA 147, 148) 2 cm Muck (A10) (MLRA 147 Histic Epipedon (A2) Thin Dark Surface (S9) (MLRA 147, 148) 2 com Muck (A10) (MLRA 147 Black Histic (A3) Loamy Mucky Mineral (F1) (MLRA 136) (MLRA 147, 148) Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Piedmont Floodplain Soils (F1 Stratified Layers (A5) Depleted Matrix (F3) (MLRA 136, 147) 2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Red Parent Material (F21) Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) (outside MLRA 127, 147, 147, 147, 147, 147, 147, 147, 14	Indicators for Problematic Hydric Soils 2 cm Muck (A10) (MLRA 147) Coast Prairie Redox (A16) (MLRA 147, 148) Piedmont Floodplain Soils (F19)
Histosol (A1) Polyvalue Below Surface (S8) (MLRA 147, 148) 2 cm Muck (A10) (MLRA 147 Histic Epipedon (A2) Thin Dark Surface (S9) (MLRA 147, 148) Coast Prairie Redox (A16) Black Histic (A3) Loamy Mucky Mineral (F1) (MLRA 136) (MLRA 147, 148) Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Piedmont Floodplain Soils (F1) Stratified Layers (A5) Depleted Matrix (F3) (MLRA 136, 147) 2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Red Parent Material (F21) Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) (outside MLRA 127, 147, 148) Thick Dark Surface (A12) Redox Depressions (F8) Very Shallow Dark Surface (F Sandy Mucky Mineral (S1) Iron-Manganese Masses (F12) (LRR N, Other (Explain in Remarks) Sandy Redox (S5) Umbric Surface (F13) (MLRA 122, 136) ³ Indicators of hydrophytic vegetati Stripped Matrix (S6) Piedmont Floodplain Soils (F19) (MLRA 147, 148) unless disturbed or problemat Type:	2 cm Muck (A10) (MLRA 147) Coast Prairie Redox (A16) (MLRA 147, 148) Piedmont Floodplain Soils (F19)
Histic Epipedon (A2)Thin Dark Surface (S9) (MLRA 147, 148)Coast Prairie Redox (A16)Black Histic (A3)Loamy Mucky Mineral (F1) (MLRA 136)(MLRA 147, 148)Hydrogen Sulfide (A4)Loamy Gleyed Matrix (F2)Piedmont Floodplain Soils (F1)Stratified Layers (A5)Depleted Matrix (F3)(MLRA 136, 147)2 cm Muck (A10) (LRR N)Redox Dark Surface (F6)Red Parent Material (F21)Depleted Below Dark Surface (A11)Depleted Dark Surface (F7)(outside MLRA 127, 147, 147, 147, 147, 147, 147, 147, 14	Coast Prairie Redox (A16) (MLRA 147, 148) Piedmont Floodplain Soils (F19)
Black Histic (A3) Loamy Mucky Mineral (F1) (MLRA 136) (MLRA 147, 148) Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Piedmont Floodplain Soils (F4) Stratified Layers (A5) Depleted Matrix (F3) (MLRA 136, 147) 2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Red Parent Material (F21) Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) (outside MLRA 127, 147, 14 Thick Dark Surface (A12) Redox Depressions (F8) Very Shallow Dark Surface (F Sandy Mucky Mineral (S1) Iron-Manganese Masses (F12) (LRR N, Other (Explain in Remarks) Sandy Redox (S5) Umbric Surface (F13) (MLRA 122, 136) ³ Indicators of hydrophytic vegetati wetland hydrology must be pr Dark Surface (S7) Red Parent Material (F21) (MLRA 127, 147, 148) wetland hydrology must be pr Mestrictive Layer (if observed): Type:	(MLRA 147, 148) Piedmont Floodplain Soils (F19)
Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Piedmont Floodplain Soils (F4) Stratified Layers (A5) Depleted Matrix (F3) (MLRA 136, 147) 2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Red Parent Material (F21) Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) (outside MLRA 127, 147, 147, 147, 147, 147, 148) Thick Dark Surface (A12) Redox Depressions (F8) Very Shallow Dark Surface (F Sandy Mucky Mineral (S1) Iron-Manganese Masses (F12) (LRR N, Other (Explain in Remarks) Sandy Redox (S5) Umbric Surface (F13) (MLRA 122, 136) ³ Indicators of hydrophytic vegetati Stripped Matrix (S6) Piedmont Floodplain Soils (F19) (MLRA 148) wetland hydrology must be pr Dark Surface (S7) Red Parent Material (F21) (MLRA 127, 147, 148) unless disturbed or problematical Restrictive Layer (if observed): Type:	Piedmont Floodplain Soils (F19)
Stratified Layers (A5) Depleted Matrix (F3) (MLRA 136, 147) 2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Red Parent Material (F21) Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) (outside MLRA 127, 147, 147, 147, 147, 147, 147, 147, 14	
2 cm Muck (A10) (LRR N) Redox Dark Surface (F6) Red Parent Material (F21) Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) (outside MLRA 127, 147, 147, 147, 147, 147, 147, 148) Thick Dark Surface (A12) Redox Depressions (F8) Very Shallow Dark Surface (F Sandy Mucky Mineral (S1) Iron-Manganese Masses (F12) (LRR N, Other (Explain in Remarks) Sandy Gleyed Matrix (S4) MLRA 136) Other (Explain in Remarks) Sandy Redox (S5) Umbric Surface (F13) (MLRA 122, 136) ³ Indicators of hydrophytic vegetati Stripped Matrix (S6) Piedmont Floodplain Soils (F19) (MLRA 148) wetland hydrology must be pr Dark Surface (S7) Red Parent Material (F21) (MLRA 127, 147, 148) unless disturbed or problemation of problematic problemation of problematic pro	(MLRA 136, 147)
Depleted Below Dark Surface (A11) Depleted Dark Surface (F7) (outside MLRA 127, 147, 147, 147, 147, 147, 147, 148) Thick Dark Surface (A12) Redox Depressions (F8) Very Shallow Dark Surface (F Sandy Mucky Mineral (S1) Iron-Manganese Masses (F12) (LRR N, Other (Explain in Remarks) Sandy Gleyed Matrix (S4) MLRA 136) Other (Explain in Remarks) Sandy Redox (S5) Umbric Surface (F13) (MLRA 122, 136) ³ Indicators of hydrophytic vegetati Stripped Matrix (S6) Piedmont Floodplain Soils (F19) (MLRA 148) wetland hydrology must be pr Dark Surface (S7) Red Parent Material (F21) (MLRA 127, 147, 148) unless disturbed or problematical or pro	
Sandy Mucky Mineral (S1) Iron-Manganese Masses (F12) (LRR N, Other (Explain in Remarks) Sandy Gleyed Matrix (S4) MLRA 136) 3Indicators of hydrophytic vegetati Sandy Redox (S5) Umbric Surface (F13) (MLRA 122, 136) 3Indicators of hydrophytic vegetati Stripped Matrix (S6) Piedmont Floodplain Soils (F19) (MLRA 148) wetland hydrology must be pr Dark Surface (S7) Red Parent Material (F21) (MLRA 127, 147, 148) unless disturbed or problemation Type:	(outside MLRA 127, 147, 148)
Sandy Gleyed Matrix (S4) MLRA 136) Sandy Redox (S5) Umbric Surface (F13) (MLRA 122, 136) Stripped Matrix (S6) Piedmont Floodplain Soils (F19) (MLRA 148) Dark Surface (S7) Red Parent Material (F21) (MLRA 127, 147, 148) Restrictive Layer (if observed): Type:	Very Shallow Dark Surface (F22)
Sandy Redox (S5) Umbric Surface (F13) (MLRA 122, 136) ³ Indicators of hydrophytic vegetati Stripped Matrix (S6) Piedmont Floodplain Soils (F19) (MLRA 148) wetland hydrology must be pr Dark Surface (S7) Red Parent Material (F21) (MLRA 127, 147, 148) unless disturbed or problematical strubbed strubbed or problematical strubbed s	Other (Explain in Remarks)
Stripped Matrix (S6) Piedmont Floodplain Soils (F19) (MLRA 148) wetland hydrology must be pr Dark Surface (S7) Red Parent Material (F21) (MLRA 127, 147, 148) unless disturbed or problemat Restrictive Layer (if observed): Type:	
Dark Surface (S7) Red Parent Material (F21) (MLRA 127, 147, 148) unless disturbed or problemation Restrictive Layer (if observed): Type:	³ Indicators of hydrophytic vegetation and
Restrictive Layer (if observed): Type:	wetland hydrology must be present,
Туре:	3) unless disturbed or problematic.
	Soil Present? Yes No X
Remarks: No hydric indicators.	

U.S.	Army Corps of Engi	neers		Requirement Contro EXEMPT	ol Symbol
WETLAND DETERMINATION DA See ERDC/EL TR-07	-	(Authority: AR 3 paragraph 5-2			
		-		pulugiupilo	- 4/
Project/Site: Paces Mill Chattahoochee Ri	ver National Recreation Ar	ea City/County: Atlan	nta/Cobb	Sampling Date:	12/5/2018
Applicant/Owner: National Park Service	9		State:	GA Sampling Point:	UPDP-03
Investigator(s): Pat Ferral		Section, Township, Ra	ange:		
Landform (hillside, terrace, etc.): floodplai	n Lo	ocal relief (concave, con	ivex, none): <u>flat</u>	Slope (%):	0 - 2
Subregion (LRR or MLRA): LRR P, MLRA	136 Lat: 33.868170	Lo	ong: 84.455494	Datum:	NAD 83
Soil Map Unit Name: Toccoa sandy loam			NWI cl	assification:	
Are climatic / hydrologic conditions on the si	ite typical for this time of ve	ear? Yes		(If no, explain in Remark	(s.)
Are Vegetation , Soil , or Hydr				present? Yes X	
Are Vegetation, Soil, or Hydr			d, explain any answe	,	
SUMMARY OF FINDINGS – Attac	h site map showing	sampling point lo	cations, transed	cts, important featu	ires, etc.
Hydrophytic Vegetation Present?	Yes No X	Is the Sampled Are	а		
Hydric Soil Present?	Yes No X	within a Wetland?	Yes	<u>No X</u>	
Wetland Hydrology Present?	Yes No X				
Remarks:					
HYDROLOGY					
Wetland Hydrology Indicators:			Secondary Inc	dicators (minimum of two	required)
Primary Indicators (minimum of one is requ	uired; check all that apply)		Surface S	oil Cracks (B6)	
Surface Water (A1)	True Aquatic Plants			Vegetated Concave Surfa	ace (B8)
High Water Table (A2)					
Water Marks (B1)	Presence of Reduce			n Lines (B16) on Water Table (C2)	
Sediment Deposits (B2)		ion in Tilled Soils (C6)		Burrows (C8)	
Drift Deposits (B3)	Thin Muck Surface (· · ·		N Visible on Aerial Imager	v (C9)
Algal Mat or Crust (B4)	Other (Explain in Re	. ,		r Stressed Plants (D1)	J ()
Iron Deposits (B5)			Geomorpl	hic Position (D2)	
Inundation Visible on Aerial Imagery (E	quitard (D3)				
Water-Stained Leaves (B9)				graphic Relief (D4)	
Aquatic Fauna (B13)			FAC-Neut	tral Test (D5)	
Field Observations:					
Surface Water Present? Yes	No X Depth (inch				
Water Table Present? Yes	No X Depth (inch				
Saturation Present? Yes (includes capillary fringe)	No X Depth (inch	nes): vveti	and Hydrology Pre	sent? Yes	<u>No X</u>
Describe Recorded Data (stream gauge, m	onitoring well aerial photo	s previous inspections) if available		
			, il avallable.		
Remarks:					

VEGETATION (Four Strata) - Use scientific names of plants.

Sampling Point: UPDP-03

Tree Stratum (Plot size: 30' radius)	Absolute % Cover	Dominant Species?	Indicator Status	Dominance Test worksheet:
1. Ligustrum japonicum	20	Yes	UPL	Number of Dominant Species
2. Acer saccharum	5	Yes	FACU	That Are OBL, FACW, or FAC: 0 (A)
3.				Total Number of Dominant
4.				Species Across All Strata: 5 (B)
5.				Percent of Dominant Species
6.				That Are OBL, FACW, or FAC: 0.0% (A/B)
7.				Prevalence Index worksheet:
	25	=Total Cover		Total % Cover of: Multiply by:
50% of total cover: 1	3 20%	of total cover:	5	OBL species 0 $x 1 = 0$
Sapling/Shrub Stratum (Plot size: 15' radius)				FACW species 0 x 2 = 0
1. Ligustrum japonicum	20	Yes	UPL	FAC species 0 x 3 = 0
2.				FACU species 15 x 4 = 60
3.				UPL species 60 x 5 = 300
4.				Column Totals: 75 (A) 360 (B)
5.				Prevalence Index = $B/A = 4.80$
6.				Hydrophytic Vegetation Indicators:
7.				1 - Rapid Test for Hydrophytic Vegetation
8.				2 - Dominance Test is >50%
9.				$3 - Prevalence Index is \leq 3.0^{1}$
	20	=Total Cover		4 - Morphological Adaptations ¹ (Provide supporting
50% of total cover: 1		of total cover:	4	data in Remarks or on a separate sheet)
Herb Stratum (Plot size: 5' radius)	<u> </u>			Problematic Hydrophytic Vegetation ¹ (Explain)
1. Ligustrum japonicum	20	Yes	UPL	¹ Indicators of hydric soil and wetland hydrology must
2.				be present, unless disturbed or problematic.
3.	·			Definitions of Four Vegetation Strata:
4.				Tree – Woody plants, excluding vines, 3 in. (7.6 cm) or
5.	·			more in diameter at breast height (DBH), regardless of
6.	·			height.
7.				Sapling/Shrub – Woody plants, excluding vines, less
8.				than 3 in. DBH and greater than or equal to 3.28 ft
9.				(1 m) tall.
10.				Herb – All herbaceous (non-woody) plants, regardless
11.	·			of size, and woody plants less than 3.28 ft tall.
	20	=Total Cover		Woody Vine – All woody vines greater than 3.28 ft in
50% of total cover: 1		of total cover:	4	height.
Woody Vine Stratum (Plot size: 30' radius)	<u> </u>			
1. Smilax bona-nox	10	Yes	FACU	
2.				
3.	·			
4.				
5.				
····	10	=Total Cover		Hydrophytic Verstation
50% of total cover: 5		of total cover:	2	Vegetation Present? Yes No X
			2	
Remarks: (Include photo numbers here or on a sepa	rate sheet.)			

VEGETATION (Five Strata) – Use scientific names of plants.

Sampling Point: UPDP-03

	Absolute Dominant Indicato	r
Tree Stratum (Plot size:)	% Cover Species? Status	Dominance Test worksheet:
1		Number of Dominant Species
2.		That Are OBL, FACW, or FAC:(A)
3.		_ Total Number of Dominant
4 5		Species Across All Strata:(B)
6.		Percent of Dominant Species That Are OBL, FACW, or FAC: (A/B)
0.	=Total Cover	Prevalence Index worksheet:
50% of total cover:	20% of total cover:	Total % Cover of: Multiply by:
Sapling Stratum (Plot size:)		OBL species x 1 =
1		FACW species x 2 =
2.		FAC species x 3 =
3.		FACU species x 4 =
4.		UPL species x 5 =
5.		Column Totals: (A) (B)
6.		Prevalence Index = B/A =
	=Total Cover	Hydrophytic Vegetation Indicators:
50% of total cover:	20% of total cover:	1 - Rapid Test for Hydrophytic Vegetation
Shrub Stratum (Plot size:)		2 - Dominance Test is >50%
1		3 - Prevalence Index is ≤3.0 ¹
2		4 - Morphological Adaptations ¹ (Provide supporting data in Remarks or on a separate sheet)
4.		Problematic Hydrophytic Vegetation ¹ (Explain)
5.		¹ Indicators of hydric soil and wetland hydrology must
6.		be present, unless disturbed or problematic.
	=Total Cover	Definitions of Five Vegetation Strata:
50% of total cover:	20% of total cover:	Tree – Woody plants, excluding woody vines,
Herb Stratum (Plot size:) 1.)		approximately 20 ft (6 m) or more in height and 3 in. (7.6 cm) or larger in diameter at breast height (DBH).
2.		Sapling – Woody plants, excluding woody vines,
3		approximately 20 ft (6 m) or more in height and less than 3 in. (7.6 cm) DBH.
5.		Shrub - Woody Plants, excluding woody vines,
6.		approximately 3 to 20 ft (1 to 6 m) in height.
7.		Herb – All herbaceous (non-woody) plants, including
8.		herbaceous vines, regardless of size, <u>and</u> woody
9.		plants, except woody vines, less than approximately
10		3 ft (1 m) in height.
11		Woody Vine – All woody vines, regardless of height.
	=Total Cover	
	20% of total cover:	_
Woody Vine Stratum (Plot size:)		
1		_
2		_
3		_
4.		-
5		– Hydrophytic
	=Total Cover	Vegetation
50% of total cover:	20% of total cover:	Present? Yes No X
Remarks: (Include photo numbers here or on a sepa	arate sheet.)	

SOIL

Wetland / Wildlife Biologist

PAT FERRAL



Mr. Farrel has 26 years of experience conducting natural and water resources studies including wetland delineation, protected species surveys, environmental assessments, stream assessments, and water quality sampling. His career includes

service as a wildlife diversity biologist with the South Carolina Department of Natural Resources, a consulting forester, wildlife biologist for American Forest Management, Inc. and as an environmental consultant. He is an accomplished endangered species biologist, wetland delineator, botanist, ornithologist and forest land manager.

Selected Relevant Experience

- Conducted wetland delineations and stream assessments for Haile Gold Mine Mitigation Project. Lancaster County, SC.
- South Carolina Department of Transportation, Statewide project responsibility - On-Call Environmental Permitting, Multiple Locations, South Carolina, 2013-14. Assisted with jurisdictional waters of the US/wetlands and critical areas delineations and permitting along roadway improvement projects throughout South Carolina including protected species assessments, alternatives analysis and establishment/survey of critical area lines for coastal waters.
- US-17 Business Management Access Improvement, SCDOT, Surfside Beach, Horry County, SC. Assisted with wetland and vegetative characteristics for US Highway 17 Business at Surfside Beach intersection Improvement.
- Dorchester County Public Works Department, Summerville, Dorchester County, SC. Conducted wetland delineation and vegetative characteristics for roadway improvements.
- I-85 and I-385 Interchange Improvement Project, SCDOT, Mauldin, Greenville County, SC. Conducted wetland delineation, stream assessments and vegetative characteristics for intersection improvements at the junction of US Highway I-85 and I-385. Design -Build permitting services included protected species assessments and review of the alternatives proposed.
- Berkeley County Engineering Department, Holly Hill, Berkeley County, SC. Assisted with wetland delineation and vegetative characteristics for roadway improvements at the intersection of US Highway 176 and the proposed Nexton Parkway.
- Charleston County Transportation Department, McClellanville, Charleston County, SC. Conducted wetland delineation, stream assessment and vegetative characteristics for intersection improvements at the junction of US Highway 17 and SC 45 at South Pinckney Street. Permitting services include protected species assessments and establishment/survey of critical area lines for coastal waters.
- Town of Mount Pleasant Transportation Department, Mount Pleasant, Charleston County, SC. Assisted with wetland delineation and vegetative characteristics for roadway improvements at the intersection of Park West Boulevard and Bessemer Road.

Education

MS, Forest Resources, Clemson University, 1998

BS, Biology, Winthrop University, 1987

Areas of Expertise

Wetland Delineation

Wildlife Biology

Forestry

Natural Resources Management

Threatened and Endangered Species

Fire Ecology and Management

Registrations/Permits/ Certifications

Certified Wildlife Biologist, The Wildlife Society #112043

South Carolina Registered Forester #1554

South Carolina Certified Prescribed Fire Manager #720

Federal Bird Banding Permit and Auxiliary Color Marking Permit #22813 (Inactive)

North Carolina Stream Identification Method Version 4.11, 2017

Advanced Wildlife Hazard Management Training Course, 2016

Hazardous Waste Operations and Emergency Response 40 Hour Training, 2010,

Problem and Atypical Wetland Delineation – Piedmont, D&D WEST, Atlanta, Georgia, 2012

Basic Wetland Delineation, D&D West, Atlanta, Georgia, 2011

Publications

Ferral, Daniel Patrick. 1998. Habitat Quality and the Performance of Red-cockaded Woodpecker Groups in the South Carolina Sand Hills. M.S. Thesis, Clemson University. 74 p.

PAT FERRAL

- Mead WestVaco, Summerville, Dorchester County, SC. Conducted wetland delineation and vegetative characteristics for roadway improvements at the intersection of US Highway 17A and Summers Drive.
- I-26 Corridor Study, Berkeley and Dorchester Counties, SC. Completed jurisdictional waters (streams and wetlands) delineation and Section 404 permitting.
- Georgetown County Department of Public Services, North Litchfield, Georgetown County, SC. Assisted with
 wetland delineation and vegetative characteristics for the construction of drainage improvements to the intake
 and outfall of Osprey Lake. Permitting services included protected species assessments and establishment and
 survey of critical area lines for coastal waters.
- South Carolina Electric and Gas transmission Line Right of Way Expansion, Multiple Counties and Locations, SC. Assisted with wetland delineations for South Carolina Electric and Gas transmission line right of way expansion for the V. C. Summer Nuclear Power Station.
- Independent Engineering Evaluation –Two 19 MW Biomass Plants, Allendale and Dorchester Counties, SC. Assisted with high level technical review and risk assessment of the environmental permits and regulatory issues that impact the projects. Coordinated the consolidation of all environmental responses including air, water, wastewater, T&E species, cultural resources, wetlands, transportation, noise, land use and zoning.
- River Park Tract, Mount Holly, Gaston County, NC. Assisted with wetland delineation, stream assessments and vegetative characteristics for a proposed housing development.
- NC-150 Road Widening Project for NCDOT, Catawba and Iredell Counties, NC. Conducted rare plant surveys for Schweinitz's sunflower (*Helianthus schweinitzii*) and Dwarf flowered heartleaf (*Hexastylis naniflora*), as well as wetland assessments, stream determinations and biological assessment along 13 miles of NC 150.
- TN SR-33 Roadway Widening Environmental Boundaries Study for TNDOT, Knoxville, Knox and Union Counties, TN. Assisted with wetland delineation, vegetative characteristics and stream assessments along 2 miles of SR-33.
- Haile Gold Mine Stream and Wetland Mitigation, Kershaw, Lancaster County, SC. Conducted wetland delineations, stream assessments and vegetative characteristics. Conducted water quality sampling at various locations in streams associated with proposed compensatory mitigation.
- Verizon Cell Phone Tower Expansion Project, Various sites, NC and SC. Conducted site inspections and wetland delineations at various cell tower locations.
- Kinder/Morgan (TGP) Conversion Project, Multiple Counties and Locations, Ohio and KY. Conducted site characteristics and landscape assessments for workspace determinations within ROW's at selected TGP pipeline taps or main line valve facilities. Surveys were conducted for the presence or absence of endangered and invasive plant species, streams and wetlands.
- Conducted wetland delineation for Orangeburg County Industrial Park.
- Conducted wetland delineations for Haile Gold Mine Mitigation Planning. Lancaster County, South Carolina.
- Conducted site inspections and wetland determination for client, Verizon Cell Phone Tower expansions, in multiple counties in South Carolina.
- Conducted wetland delineation for South Carolina Electric and Gas right of way for natural gas line for Continental Tire Corp., Sumter, South Carolina.
- Conducted surveys of wading bird use of littoral wetland vegetation on cooling reservoirs at Savannah River Site, New Ellenton, South Carolina for NEPA requirements under the Clean Waters Act. Savannah River Ecology Laboratory.