



- General Notes:**
- * Rehabilitate buildings, landscape and roads in HQ district
 - * Better delineate roads and parking areas through asphalt removal and revegetation
 - * Employ palette of fixtures recommended in the 2007 Cultural Landscape Report
 - * Convert to individual furnaces for heating
 - * Upgrade existing hydrant system to meet NFPA 1142

Headquarters Area Plan
Denali National Park and Preserve
Headquarters Historic District

National Park Service

Alternative 3

- SOURCES**
1. CAD File name HQtopo-master plan
 2. Field Survey completed by Olmsted Center, April 2005
 3. EA and Planning by Denali Park Staff

- LEGEND:**
- (L) Light locations
 - HQ District Boundary
 - Revegetation Areas
 - New Construction
 - Landscaped Areas

DRAWN BY
National Park Service / Joel Smith
NPS/ Mary Tidlow

Using AutoCAD 2002 and Adobe Illustrator 10

DRAWN: JS 2006/11/27
CHANGES: MT 08/07



SCALE: 1" = 150'

Figure 2-3: Alternative 3 - Preferred Alternative