



---

## Memo To File

### A. Project Information

**Park Name:** Yosemite National Park

**PEPC Project Number:** 94109

**Project Title:** Curry Village Pavilion Chimney Repairs (YH 2020) 2020-023

**Project Leader:** Joshua Keyes

### B. Description of the Current Action (Project Description)

**JUSTIFICATION:** The concrete work on the top of the chimney is eroding and falling apart. The chimney was constructed with the 1974 reconstruction and is not part of the original building that burned in the early 1970s.

**SCOPE:** 1. The contractor will chip, clean, and remove the eroding concrete debris from the chimney. 2. They will form, dowel, and pour the repair piece for chimney. 3. They will fabricate and install a custom copper angle form and chimney cap. 4. The chimney cap will be painted with a heat resistant black paint to ensure no glare from Glacier Point while keeping the chimney functionality the same.

### C. Description of Previous Compliance Documentation

**Decision Document Name:** Half Dome Village Pavilion Remodel (YH 2018)

**Decision Document PEPC ID:** 79632

**Decision Document Approval Date:** 2018-09-28 00:00:00.0

### D. Notes

### E. Conclusion

The existing NPS NEPA document has been reviewed and there are no substantive differences between the current proposal and its associated environmental impacts and the proposal and impacts as described in the existing NEPA document and associated decision document.