

APPENDIX C


Existing Conditions Survey Plans



FIRST FLOOR PLAN

2. EALU 16: 10000
 3. 10000
 4. 10000
 5. 10000
 6. 10000
 7. 10000
 8. 10000
 9. 10000
 10. 10000
 11. 10000
 12. 10000
 13. 10000
 14. 10000
 15. 10000
 16. 10000
 17. 10000
 18. 10000
 19. 10000
 20. 10000
 21. 10000
 22. 10000
 23. 10000
 24. 10000
 25. 10000
 26. 10000
 27. 10000
 28. 10000
 29. 10000
 30. 10000
 31. 10000
 32. 10000
 33. 10000
 34. 10000
 35. 10000
 36. 10000
 37. 10000
 38. 10000
 39. 10000
 40. 10000
 41. 10000
 42. 10000
 43. 10000
 44. 10000
 45. 10000
 46. 10000
 47. 10000
 48. 10000
 49. 10000
 50. 10000
 51. 10000
 52. 10000
 53. 10000
 54. 10000
 55. 10000
 56. 10000
 57. 10000
 58. 10000
 59. 10000
 60. 10000
 61. 10000
 62. 10000
 63. 10000
 64. 10000
 65. 10000
 66. 10000
 67. 10000
 68. 10000
 69. 10000
 70. 10000
 71. 10000
 72. 10000
 73. 10000
 74. 10000
 75. 10000
 76. 10000
 77. 10000
 78. 10000
 79. 10000
 80. 10000
 81. 10000
 82. 10000
 83. 10000
 84. 10000
 85. 10000
 86. 10000
 87. 10000
 88. 10000
 89. 10000
 90. 10000
 91. 10000
 92. 10000
 93. 10000
 94. 10000
 95. 10000
 96. 10000
 97. 10000
 98. 10000
 99. 10000
 100. 10000


PHOTOGRAPHED NOV. 4, 1963
WITH CALLER - SANTIAGO PHOTOGRAPHISTS - DOING
A PLOT ON WILD A-7 AUTOGRADE
AT THE OHIO STATE UNIVERSITY
SUPERVISOR - DEE E. BOWMAN
RESEARCH ASSOCIATE - KRILL H. GLUTEN
PHOTOGRAPHER - H. L. HAN, THOMAS W. CARRY,
PHOTOGRAPHER



SECOND FLOOR PLAN
1/16" = 1'-0"

EXISTING CONDITIONS SURVEY
SAGAMORE HILL


DECEMBER, 2008



THIRD FLOOR PLAN
1/16" = 1'-0"

EXISTING CONDITIONS SURVEY
SAGAMORE HILL

DECEMBER, 2008




FOURTH FLOOR PLAN (ATTIC)



EXISTING CONDITIONS SURVEY
SAGAMORE HILL


DECEMBER, 2008



ROOF PLAN
1/16" = 1'-0"


EXISTING CONDITIONS SURVEY
SAGAMORE HILL

DECEMBER, 2008



NORTH ELEVATION

EXISTING CONDITIONS SURVEY
SAGAMORE HILL




SOUTH ELEVATION

EXISTING CONDITIONS SURVEY
SAGAMORE HILL

DECEMBER, 2008



GENERAL NOTE:
ALL WINDOW WELLS ARE UNDRAINED
AND CONTRIBUTING TO MOISTURE
RETENTION DUE TO DEBRIS COLLECTION



WEST ELEVATION

EXISTING CONDITIONS SURVEY
SAGAMORE HILL