Oconaluftee Visitor Center Planning

Improving Visitor Services

National Park Service U.S. Department of the Interior

Great Smoky Mountains National Park



EXISTING CONDITIONS

BUILDING ISSUES



Not designed to be a visitor center



Sales area inadequate



Small visitor orientation area



Difficult to access rest rooms



Limited space for exhibits



No area for interpretive talks

SITE ISSUES



No sense of arrival for visitor



Poor pedestrian circulation and way finding



Poor vehicle access and parking

