



Women's Rights National Historical Park - Wesleyan Chapel
Seneca Falls, New York



Rehabilitation and Preservation of the Wesleyan Chapel
Environmental Assessment/Assessment of Effect

Table of Contents

1.	Purpose and Need.....	I-1
1.1	Introduction	I-1
1.2	Background	I-1
1.3	Project Location.....	I-4
1.4	Purpose of the Action.....	I-6
1.5	Need for the Proposed Action.....	I-6
1.6	Scoping.....	I-9
1.7	Issues	I-10
1.8	Impact Topics Retained for Analysis.....	I-12
1.9	Impact Topics Dismissed.....	I-14
1.10	Related Plans and Studies	I-19
2.	Alternatives.....	II-1
2.1	Alternatives Development.....	II-1
2.2	Alternative A - No Action.....	II-2
2.3	Alternative B - Expand the Existing Treatment/Provide Visitor Enclosure.....	II-2
2.4	Alternative C - Rehabilitate Chapel with Alternative Material.....	II-3
2.5	Alternative D - Rehabilitate Chapel with Non-Historic Brick Masonry Units (NPS Preferred Alternative)	II-4
2.6	Alternative E - Enclose Chapel Remains in a New Structure.....	II-5
2.7	Alternatives Considered But Dismissed.....	II-6
2.8	Preferred Alternative.....	II-7
2.9	Environmentally Preferred Alternative.....	II-8
3.	Affected Environment.....	III-1
3.1	Area of Potential Effect for Cultural Resources under Section 106.....	III-1
3.2	Historic Architectural Resources.....	III-1
3.3	Archeological Resources.....	III-2
3.4	Visitor Use and Experience.....	III-2
4.	Environmental Consequences.....	IV-1
4.1	Methodology for Assessing Impacts.....	IV-2
4.2	Historic Architectural Resources.....	IV-5
4.3	Archeological Resources.....	IV-12
4.4	Visitor Use and Experience.....	IV-17
4.5	106 Summary.....	IV-20
4.6	Summary of Impacts by Alternative.....	IV-22

5.	Consultation and Coordination.....	V-1
5.1	Brief History of Planning and Public Involvement.....	V-1
5.2	Interagency Coordination.....	V-2
5.3	List of Recipients.....	V-2
5.4	List of Preparers.....	V-3
5.5	References.....	V-3
5.6	Acronyms and Abbreviations.....	V-4
Appendix A – Correspondence.....		Appendix A-1
Appendix B – Scoping Process Documentation.....		Appendix B-1
Appendix C – Consultation with NY SHPO.....		Appendix C-1

Figures

Figure 1	Architectural Evolution of Chapel.....	I-2
Figure 2	Current design of the Wesleyan Chapel.....	I-3
Figure 3	Winning Model of 1987 National Design Competition.....	I-4
Figure 4	Map of Seneca Falls.....	I-5
Figure 5	Location Map of Wesleyan Chapel in Seneca Falls Historical District.....	I-5
Figure 6	Noise Monitoring Locations.....	I-7
Figure 7	Deteriorating Chapel Bricks.....	I-13
Figure 8	Alternative A - No Action.....	II-2
Figure 9	Model of Alternative B.....	II-3
Figure 10	Alternative B - Expand the Existing Treatment/Provide Visitor Enclosure.....	II-3
Figure 11	Model of Alternative C.....	II-3
Figure 12	Alternative C - Rehabilitate Chapel with Alternative Material.....	II-4
Figure 13	Model of Alternative D.....	II-4
Figure 14	Alternative D - Rehabilitate Chapel with Non-Historic Brick Masonry Units.....	II-5
Figure 15	Model of Alternative E.....	II-5
Figure 16	Alternative E - Enclose Chapel Remains in a New Structure....	II-6
Figure 17	Drawing Depicting Encapsulating the Site.....	II-7

Tables

Table 1	Comparative Summary of how Alternatives Meet the Purpose of the Project.....	II-10
Table 2	Summary of Environmental Consequences.....	II-12