

Replace Plumbing Components to the Shower in the Master Bedroom of the Superintendent's House (Quarters #2)
Photos



Superintendent's House (Quarters #2)



Inside the Master Bedroom of the Superintendent's House, looking east. The bathroom is through the door to the left. The center door opens to the closet. The door to the right opens into the second floor hallway.



Inside the closet in the Master Bedroom. The wall to the front is shared with the back of the shower on the other side. The plumbing for the shower is inside the wall. The park is proposing to cut an access hole into the gypsum wall in the closet. This will provide the needed access to the pipes. The necessary repairs and replacement of the plumbing will occur. A simple access panel will be framed out and left in the closet wall for future plumbing access needs.



Inside the bathroom in the Master Bedroom. The door to right opens into the bedroom. To the left is the shower.



Inside the shower in the bathroom of the Master Bedroom. The fixtures are stripped, leaking and failing to operate correctly. This project will require the removal of some tile around the fixtures in order to access the valve(s) for the dual handle shower fixtures. Repair/replacement will occur.

The park will work to retain the handles. Replacement of the tiles will occur once the repair/replacement of the valve(s) has occurred.