## **CHAPTER 4: HISTORIC STRUCTURE REPORT**

## OUTER ISLAND INTRODUCTION

The following sections commence the HSR for Outer Island. The disciplines of Architecture, Structural, Mechanical (HVAC and plumbing), Electrical and Environmental Engineering are addressed individually (refer to Volume I Chapters 1 and 2 for more details on report organization and methodology). The Island's extant buildings include:

- Outer Island Tower
- Keepers Quarters
- Fog Signal Building
- Oil Storage
- Privy


Original construction of each building is discussed, followed by its specific history/chronology of alterations (determined by studying historic photos, historic drawings, examining park records and archives and on site investigations and observations by the Study Team).

The Physical Description section describes the current conditions, by discipline and by component, as observed on site during the September 2009 site visit. Each component has been given a condition rating (as outlined in Volume I, Chapter 2: Methodology) in the Condition Assessment section. Treatment Recommendations are based on the Preferred Alternative of the May 2010 Value Analysis/CBA conducted at the park.

## Historic Photographs




Historic Image OI-01: Northwest view of the Light Tower, 1893 (Source: NPS APIS Archives)




Historic Image OI-03: Southwest elevations of the Fog Signal Buildings, 1893 (Source: NPS APIS Archives)


12



Historic Image OI-05: West elevation of the Fog Signal Building, Tower and Keepers Quarters, 1905 (Source: NPS APIS Archives)




Historic Image OI-06: Northwest elevation of the Light Tower, 1916-1925 (Source: NPS APIS Archives)



Historic Image OI-07: West elevation of the Keepers Quarters and kitchen vestibule, 1916 (Source: NPS APIS Archives)

Historic Image OI-08: Kitchen vestibule's screen door, unknown date (Source: NPS APIS Archives)




Historic Image OI-09: North elevation of the Fog Signal Building, 1937 (Source: NPS APIS Archives)



Tramway and Landing


1 2 3

Historic Image OI-10: View of the boat ramp and Fog Signal stack, 1937 (Source: NPS APIS Archives)




Historic Image OI-11: North elevation of the Oil Storage, unknown date (Source: NPS APIS Archives)

Historic Image OI-12: Shoreline stabilization work, c. 1980 (Source: NPS APIS Archives)




Historic Image OI-13: West elevation of the Keepers Quarters, 1981 (Source: NPS APIS Archives)

## 1 Historic Drawings




Historic Drawing OI-01: 1877 Site Plan

Historic Drawing OI-02: 1893 Survey by H. Bamber, published 1899




Historic Drawing OI-03: September, 1893 Survey by H. Bamber, revised 1901 and 1911


Historic Drawing OI-04: Undated plan and elevations of Tower



Historic Drawing OI-05: Plan of Keepers Quarters, undated (assumed original with 1925 additions overlaid)



Historic Drawing OI-06: 1925 Plan to convert second floor of Keepers Quarters into one living space for first assistant



Historic Drawing OI-07: 1925 Plan to convert attic of Keepers Quarters into living space for second assistant

Historic Drawing OI-08: 1929 revised plans, elevations and details of Fog Signal Building