

*Reconstruct the Basement Stairway Entrance Roofs at Chatham*

**Photos**



Chatham, as viewed from the west.



Cropped view of the northern basement stairway entrance. Photo dated 1863.



Cropped view of the southern basement stairway entrance. Photo dated 1863.



Current view of northern basement stairway entrance. Garden wall added in 1920s. Note ghost lines for pitched roof on wall of the house. The park proposes to reconstruct the missing roof.



Current view of the flat roof on the northern basement stairway entrance. This area fills with rainwater that eventually seeps into the basement.



Current view southern basement stairway entrance. Garden wall added in 1920s. The park proposes to reconstruct the missing roof.



Current view northern basement stairway entrance. Garden wall added in 1920s. Note ghost lines for pitched roof on wall of the house. The park proposes to reconstruct the missing roof.



Current view of the flat roof on the southern basement stairway entrance. This area fills with rainwater that eventually seeps into the basement.

