

ATTACHMENT C

PHOTOGRAPHIC RECORD OF PROPOSED WETLAND MITIGATION SITES

This page intentionally left blank

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)




Road Section Survey, Arnott Fen



Arnott Fen Berm/Road Trace



Arnott Fen Upper Cell



Arnott Fen Berm/Road Trace

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Blaufarb Pond Emergent Wetland Fringe



Hemlock Pond



Blaufarb Pond



Hemlock Pond Emergent Wetland Fringe

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Camp Kittatinny Main Pond



Camp Kittatinny Dam



Camp Kittatinny Main Pond



Camp Kittatinny Road Access

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Camp Kittatinny Upper Pond



Camp Kittatinny Upper Pond



Camp Kittatinny Upper Pond



Sussex Vo-Tech Pond Breached Dam

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Sussex Vo-Tech Pond Breached Dam



Sussex Vo-Tech Pond



Sussex Vo-Tech Pond Breached Dam



Sussex Vo-Tech Pond Shoreline

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Miller Wetland



Miller Wetland Agricultural Field



Miller Wetland Channels



Miller Wetland

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Miller Wetland Pond



Miller Wetland Invasive Species



Miller Wetland Pond – Beaver Area



Miller Wetland Invasive Species

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Miller Wetland - Van Campens Brook



Van Campens Brook Side Channel



Miller Wetland Van Campens Brook



Cutoff Road Dam

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)




Cutoff Road Dam – Looking Upstream



Cutoff Road Dam Breach



Cutoff Road Dam Breach



Cutoff Road Dam - Looking Downstream

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)




Upper Watergate Offline Pond



Upper Watergate Offline Pond



Upper Watergate Offline Pond



Upper Watergate Offline Pond

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Upper Watergate Offline Pond



Upper Watergate Rec Access



Upper Watergate Offline Pond



Upper Watergate Offline Main Pond

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Upper Watergate Offline Main Pond



Upper Watergate Offline Main Pond



Upper Watergate Offline Pond



Upper Watergate Offline Pond Bottom

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Upper Watergate Offline Main Pond Shore



Upper Watergate Access Road



Upper Watergate Offline Main Pond Drain



Upper Watergate Offline Main Pond

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Watergate Recreation Area Parking



Watergate Downstream of Dam 6



Watergate Recreation Area Parking



Watergate Downstream of Dam 6

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Watergate Dam 7



Stone Wall Below Watergate Dam 7



Point Bar Area Between Dam 6 and 7



Stonewall Below Watergate Dam 7

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Wetlands Above Watergate Dam 6



Watergate Dam 10 Berm




Watergate Dam 10 Pond and Berm



Watergate Dam 10 Pond

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Watergate Dam 10 Spillway



Watergate Dam 10 Spillway and Bridge



Watergate Dam 10 Bridge



Watergate Dam 10 Pond

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Watergate Dam 10 Pond



Watergate Dam 10 Pond



Watergate Dam 10 Shore



Birchenough Fringe Wetlands

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Birchenough Pond and Wetlands



Birchenough Barn and Wetlands



Birchenough Barn and Wetlands



Peters Mill Pond

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Peters Mill Pond UNT to Little Flat Brook



Peters Mill Pond Wetlands



Peters Mill Pond Stream

Photographic Record


S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Peters Mill Pond UNT to Little Flat Brook



Peters Mill Pond Dam



Peters Mill Pond UNT to Little Flat Brook



Peters Mill Pond Dam

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Peters Mill Pond Dam



UNT to Little Flat Brook



UNT to Little Flat Brook



Debris Jam, NJ Route 615 Culvert

Photographic Record

S-R Transmission Line – DEWA, MDSR, APPA
Pennsylvania and New Jersey
Wetland Function – Value Evaluation Survey (June 2012)



Peters Valley NJ Route 615



Fill Area, NJ Route 615



Concrete Pipe Culvert, NJ Route 615



Adjacent Wetlands, NJ Route 615