December 2005 Environmental Assessment APPENDIX C: PHOTOGRAPHIC LOG Replacement of a Communications Tower and Access Road Improvement

Environmental Assessment December 2005

PHOTOGRAPHIC LOG



PHOTOGRAPH 1: EXISTING TOWER BASE; NOTE RELATIVELY FLAT, GENTLE TERRAIN

Environmental Assessment December 2005



PHOTOGRAPH 2: RELATIVELY STEEP TERRAIN ALONG NFSR #730A-2

Environmental Assessment	December 200:
APPENDIX D: PHOTOGRAPHIC SIMULATIONS	







Site Name: ND04 Rough Rider
Site Address: 3204 East River Road Medora, ND 58645

Point of View: Looking North, North-West at site from town of Medora.









Site Name: ND04 Rough Rider
Site Address: 3204 East River Road

Medora, ND 58645

Point of View: Looking North, North-West at site from town of Medora.









Site Name: ND04 Rough Rider
Site Address: 3204 East River Road

Medora, ND 58645

Point of View: Looking North, North-East at site from about 1000 feet away.









Site Name: ND04 Rough Rider
Site Address: 3204 East River Road
Medora, ND 58645

Point of View:

Looking South at site from about a 1000 feet (near Wilderness Area boundry).

