APPENDIX B: HAZARDOUS MATERIALS PHOTOGRAPHS

Sir Francis Drake Boulevard Project Site Reconnaissance Photographs June 2014



Photo 1: Aboveground Storage Tank on Nunez Family Farm Property







Photo 4: Household refuse, small wood debris, and tires on Nunez Family Farm Property

