

Figures

 Site Boundary








Figure 1
Site Map
Saugus Iron Works NHS
Saugus, Massachusetts









- Restoration Area
- Saugus River
- Benthic Invertebrate Sample Location
- Habitat Areas
 - Cattail
 - Gravel/Cobble Bar
 - Mudflat
 - Phragmites
 - Sandbar
 - Mix of Plant Species




Figure 5
Aquatic Habitat and Vegetation
within the Study Area
Saugus Iron Works NHS
Saugus, Massachusetts



 Restoration Area

- Predominant Channel Substrate
-  Gravel and Sand
 -  Gravel and Cobble
 -  Sand with Submerged Aquatic Vegetation




Figure 6
River Channel Substrates
Saugus Iron Works NHS
Saugus, Massachusetts





Figure 7
Existing Topography
Saugus Iron Works NHS
Saugus, Massachusetts