

## Attachment 1: Photos - Upper Nisqually River Revetment Retrofit



Upstream end of project adjacent to SR 706 (entrance to MRNP)

5/23/2017



Upstream end of project, closer look at damaged toe and face scour

5/23/2017



**Attachment 1: Photos - Upper Nisqually River Revetment Retrofit**



Looking upstream towards SR 706

5/23/2017



Looking downstream (small section of remnant levee on left in channel)

5/23/2017



**Attachment 1: Photos - Upper Nisqually River Revetment Retrofit**



Looking upstream-portion of the braided river. Remnant levee is center left 5/23/2017



Looking downstream at Park boundary and gate. River veers away from levee 5/23/2017



**Attachment 1: Photos - Upper Nisqually River Revetment Retrofit**



Looking upstream, 200 ft from the bottom end.

12/15/2015



Looking downstream, 200 ft from the bottom end.

12/15/2015



**Attachment 1: Photos - Upper Nisqually River Revetment Retrofit**



Looking upstream. End of project reach.

12/15/2017

Braided Nisqually River in moderate flows (~8,000 cfs)

12/9/2015

