

Reinstall Diana Statue at Chatham
Photos



Diana Statue in situ – 1927
Looking east through the gates of the walled garden



Diana Statue in situ – 1927
Looking east from the gates of the walled garden



Diana Statue in situ – 1927
Looking east from the gates of the walled garden



Ceres Statue in new location - ca.1960
Looking west to the gates of the walled garden



Ceres Statue in new location - 1977
Looking west to the gates of the walled garden



Ceres Statue in new location – 2019
Looking east through the gates of the walled garden
Ceres will be replaced by the Diana Statue moved to the west side of the main house



Ceres Statue in new location – 2019
Looking west to the gates of the walled garden
Ceres will be replaced by the Diana Statue moved to the west side of the main house



Ceres Statue in new location – 2019

The plinth that originally held the Diana Statue. Note the apron of cement used to attach the Ceres Statue.

Ceres will be replaced by the Diana Statue moved to the west side of the main house



Empty Plinth on the west side of the house – 2019

Looking south across the upper terrace. Flora Statue is indicated by the red arrow.
The Ceres Statue will be installed on the vacant plinth.



Empty Plinth on the west side of the house – 2019
The Ceres Statue will be moved to, and reinstalled on, this plinth.



Flora Statue on the west side of the house – 2019
Looking north across the upper terrace. Empty plinth is indicated by the red arrow.
The Ceres Statue will be installed on the vacant plinth.



Flora Statue – 2019

Note the apron of cement used to attach the Flora Statue.



Diana Statue at VFMA – 2018

This is prior to the on-going restoration work



Diana Statue at VFMA – 2018
This is prior to the on-going restoration work