

Rehabilitation of Chatham Walkway Surrounding Diana Statue
Photos



1920s view looking east, showing Diana's original location with vegetation around the plinth and a circular space surrounding it - 1927



Closeup view of Diana with vegetation around the plinth - 1927



Diana statue looking east, with circular walkway defined by plantings - 1927



Ceres Statue occupying the location where Diana will be installed. The reinstalled statue will be very close to the public walkway. The proposal calls for widening the circle around the plinth to an 11 foot diameter. Facing East - 2019



Ceres statue, facing West. - 2019




Figure 1 Chatham Entrance Landscape and Path Alterations Proposal, March 2019, original sketch by Scott Blake, digitized by Luisa Dispenzirie. - 2019

