# Why Are We Doing This Study?

- Current maintenance facility is over capacity and vehicle maintenance is completed on a gravel lot.
- Current maintenance facility is in the approximate historic location of the Grand Portage Trail.
- Equipment/material storage yard is located on archaeologically sensitive resources, and on prime lake front property that could be put to a more valuable use.
- Seasonal housing units are in need of repairs, and are on lake front property owned by the Tribal Council.



#### **Existing Conditions**



The outdoor storage area for equipment and supplies; located on prime lake front property.




Maintenance facility is overcrowded.



Seasonal housing in need of repairs and located on prime lake front property.



### **Proposed Maintenance Facility**





### **Proposed Layout Plan**





# **Study Elements**

An Environmental Assessment (EA) will be prepared and made available for public review. The study will address various resources including:

- Wetland and Waters of the U.S.
- Sensitive Plant and Animal Species
- Cultural Resources
- Land Use
- Public Health and Safety
- Traffic Volumes at Site
- Noise



## **Study Timeline**

**Housing Project** 

**Maintenance Facility** 

Task	Spring	Summer	Fall	Winter
Collect Data				
Develop and Analyze Alternatives				
Prepare Environmental Assessment				
Conduct Public Information Meeting		<b>♦</b>		
Prepare Preliminary Design	Complete	(Stock Plan)		
Prepare Final Design				
Begin Construction			Unknown	



### **How Can the Public Participate?**

- Public Information Meeting
- Contact Us Anytime by Phone or E-Mail
- Citizen Comment Forms

Melvin Gagnon
P.O. Box 428 / 83 Stevens Rd
Grand Portage, MN 55605
(218) 475-0123
Melvin\_gagnon@partner.nps.gov

